

Motherboard Logo Program (MLP)

# Intel<sup>®</sup> Desktop Board DB65AL

## **MLP Report**

3/24/2011

Purpose:

This report describes the DB65AL Motherboard Logo Program testing run conducted by Intel Corporation.

#### THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppels or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel® Core™ i7 and Intel® are trademarks of Intel Corporation in the U.S. and other countries.

\*Other names and brands may be claimed as the property of others

Copyright ° 2009, Intel Corporation. All rights reserved.

## Contents

Introduction	4
Terms and Definitions	.4
Desktop Board Configuration	5
Desktop Board DB65AL Final Configuration Report: Completion of MLP	.5
Board Information	
Product Code	.5
Processor	.5
Motherboard	.5
System Memory	.5
Power Management	.5
Operating System Tested	.5
Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit	.6
Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit	
Windows Logo Kits Used (WLK)	.7
Errata and Contingencies	.8
Test Notes	11

#### Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
WLK	Windows Logo Kits
MLP	Motherboard Logo Program. For further information see: http://www.microsoft.com/whdc/hwtest/default.mspx
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: <a href="http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;g=s">http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;g=s</a>

## **Desktop Board Configuration**

#### Desktop Board DB65AL Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

#### **Board Information**

Product Code <sup>1</sup>	BIOS String/Model	Technologies NOT Logo'd (yet)				
DB65AL	ALB6510H.86A.0033.2010.1210.2325	N/A - all technologies logo'd				
Processor						
Speed	3.4GHz					
Family	Intel <sup>®</sup> Core i7-2600 D2					
Bus Speed	100MHz					
Motherboard						
Board AA #	G12530					
Board FAB #	301					
	es to the production FAB revision; Please co ion you intend to perform logo testing if not	nsult your Intel Corporation representative to clarify the the same.				
System Memory						
Speed	Dual Channel, DDR3, 1333MHz					
Метогу Туре	DIMM	DIMM				
Connector Type	DDR3, 240 Pin					
Power Management						
BIOS Default	53					
Operating System	Tested					
	Check Tested	Comments				
Windows 7 32 and 64-bit		Windows 7 Ultimate				
Windows Vista 32 and 64-bit		Windows Vista Ultimate with Service Pack 2				

<sup>&</sup>lt;sup>1</sup> These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

#### Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit

Technology	OS	Version	Package version
Chipset Update Utility	Windows Vista	9.2.0.1016	9.2.0.1016
Intel <sup>®</sup> Chipset Software Utility	Windows Vista 64-bit	9.2.0.1016	9.2.0.1016
On-board GFX	Windows Vista	8.15.10.2253	15.21.3.2253
Intel(R) HD Graphics Family	Windows Vista 64-bit	8.15.10.2253	15.21.3.64.2253
On-board Audio	Windows Vista	6.0.1.6257	PG314
Realtek High Definition Audio	Windows Vista 64-bit	6.0.1.6257	PG314
LAN Jotol 825701 V Cigobit Notwork	Windows Vista	11.8.78.0	N/A
Intel 82579LV Gigabit Network Connection	Windows Vista 64-bit	11.8.78.0	N/A
ME	Windows Vista	7.0.0.1144	N/A
Intel Management Engine Interface	Windows Vista 64-bit	7.0.0.1144	N/A
<u> </u>			
IDCT	Windows Vista	10.0.0.1008	N/A
IRST	Windows Vista 64-bit	10.0.0.1008	N/A

#### Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit

Technology	OS	Version	Package version
Chipset Update Utility	Windows 7	9.2.0.1016	9.2.0.1016
Intel <sup>®</sup> Chipset Software Utility	Windows 7 64-bit	9.2.0.1016	9.2.0.1016
On-board GFX	Windows 7	8.15.10.2253	15.21.3.2253
Intel(R) HD Graphics Family	Windows 7 64-bit	8.15.10.2246	15.21.3.64.2253
Audio	Windows 7	6.0.1.6257	PG314
Realtek High Definition Audio	Windows 7 64-bit	6.0.1.6257	PG314
LAN	Windows 7	11.8.81.0	N/A
Intel 82579LV Gigabit Network Connection	Windows 7 64-bit	11.8.81.0	N/A
ME	Windows 7	7.0.0.1144	N/A
Intel Management Engine Interface	Windows 7 64-bit	7.0.0.1144	N/A

IRST	Windows 7	10.0.0.1008	N/A
	Windows 7 64-bit	10.0.0.1008	N/A

#### Windows Logo Kits Used (WLK)

Microsoft website: <a href="http://www.microsoft.com/whdc/DevTools/WDK/DTM.mspx">http://www.microsoft.com/whdc/DevTools/WDK/DTM.mspx</a>

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows 7	WLK1.5 for Windows 7	WLK1.5 for Windows 7
Windows 7 64-bit		
Windows Vista	WLK1.5 for Windows Vista SP2	WLK1.5 for Windows Vista SP2
Windows Vista 64-bit		WENT.S TOT WITHOWS VISIO SPZ

### Errata and Contingencies

	-				
Operating System	Failing Test	Expiry Date	ID Number	Туре	Error Description
Windows Vista	PCI Hardware Compliance Test For Systems	6/1/2011	401	Erratum	
Windows Vista- 64bit	PCI Hardware Compliance Test For Systems	6/1/2011	401	Erratum	Issue Description: The following PCI Compliance test failure is acceptable: Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return O as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges. Assertion 13A41D3E-2576- 41DC-A67C-525DA3637CEA This failure is acceptable because this is a PCIe 1.1 feature and the WLP requires compliance with only PCIe 1.0a.
Windows 7					1.0a.
Windows 7 64-bit					
Windows Vista Windows Vista- 64bit	Vista:UAA Test-Vista or Server08	06/01/2011	1300	Erratum	Issue Description: HD Audio pin configuration document calls out setting Port Connectivity to No Connection as the way to turn a pin off in a particular system. UAA Test incorrectly tests such pins
Windows 7	WIN7:UAA Test - Win7 (System)	•			
Windows 7 64-bit	WINY.OAA Test - WIIT (System)				
Windows Vista Windows Vista- 64bit	Vista:UAA Test-Vista or Server08	07/01/2011	1466	Erratum	<b>Issue Description:</b> Preview Filter: UAA Test - Intel Low Power DCN says "EPSS implies KeepAlive, but only after July 1st
Windows 7					2011"
Windows 7 64-bit	WIN7:UAA Test - Win7 (System)				
Windows Vista	Vista:UAA Test-Vista or Server08	02/28/2011	1299	Erratum	
					Issue Description:

Windows Vista- 64bit Windows 7 Windows 7 64-bit	WIN7:UAA Test - Win7 (System)				Preview filter - Jack Detect Override on digital pin widgets Errata 1299 The HD Audio configuration default register (7.3.3.31 in the HD Audio specification) includes a "Jack Detect Override" flag that can be used to indicate that although a pin widget would normally be capable of jack detection, there is something about this particular system that causes this to be impossible. This was intended to be used, for example, for analog pin widgets that are connected to RCA jacks, which do not allow for impedance detection. Some digital pin widgets are using the Presence Detect pin sense response to indicate that a digital handshake has occured - indeed, HDMI pins have entire DCNs built around this concept, and it applies equally well to S/PDIF pins. A digital converter that supports presence detection should be able to do so in any system, so the "Jack Detect Override" concept should not apply to digital pins.
Windows Vista Windows Vista- 64bit Windows 7 Windows 7 64-bit	Vista:UAA Test-Vista or Server08 WIN7:UAA Test - Win7 (System)	06/01/2015	513	Erratum	Issue Description: UAA Test requires the Traffic Priority bit to be read/write - however there are two specs that apply, and they conflict. One says the bit must be read/write, the other says it must be read-only. Contact has been made with the author of both specs (Intel) but until this point is clarified we cannot fail submissions containing this test failure.
Windows Vista	<b>Vista:</b> HDAudio Class Driver Fidelity Test - Vista (System, Manual)	07/31/2011	598	Erratum	Issue Description:

Windows Vista- 64bit Windows 7	<b>Win7:</b> Class Driver Fidelity Test - Win7(System, Manual)				Preview filter - Jack Detect Override on digital pin widgets Errata 1299 The HD Audio configuration default register (7.3.3.1 in the HD Audio specification) includes a "Jack Detect Override" flag that can be used to indicate that although a pin widget would normally be capable of jack detection, there is something about this particular system that causes this to be impossible. This was intended to be used, for example, for analog pin widgets that are connected to RCA jacks, which do not allow for impedance detection. Some digital pin widgets are using the Presence Detect pin sense response to indicate that a digital handshake has occured - indeed, HDMI pins have entire DCNs built around this concept, and it applies equally well to S/PDIF pins. A digital converter that supports presence detection should be able to do so in any system, so the "Jack Detect Override" concept should not apply to digital pins.
Windows 7 64-bit					
Windows Vista	<b>Vista:</b> HDAudio Class Driver FidelityTest (System Munual)	06/01/2011	1801	Erratum	
Windows Vista- 64bit					Issue Description: There is a test bug which causes the measurement of system noise during Render Power Transition Test to be about 3 dB worse than it should be. This filter forgives errors up to 6 dB.
Windows 7	<b>Win7:</b> Class Driver Fidelity Test - Win7(System, Manual)				
Windows 7 64-bit					
Windows Vista	Vista:HDAudio Class Driver FidelityTest (System Munual)	06/30/2025	1256	Erratum	
Windows Vista- 64bit Windows 7	<b>Win7:</b> Class Driver AC3 Test - Win7(system)				Issue Description: Run AC3 test on a system with the Microsoft HD Audio class driver installed. Expected results: All AC3 kernel streaming data ranges should advertise MinimumBitsPerSample = 16 and MaximumBitsPerSample = 16. Actual results: HD Audio class driver sometimes advertises MaximumBitsPerSample = 24.
WILLOWS /	WIII/ CIASS DITVELACO TEST - MIII/ (SYSTEIII)				

	Windows 7 64-bit					
--	------------------	--	--	--	--	--

#### **Test Notes**

Operating System	Test	Description
Windows 7 and Vista	BIOS download	Internal: <u>http://bios.intel.com/downloads/</u> External: <u>http://www.intel.com/</u> click on Support and Download
Windows 7 and Vista	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings. System Date and Time: Current date and time Trusted Platform Module: Enable Others: BIOS default setting
Windows 7 and Vista filter update	WLK WHQL test	http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filte rupdates.cab
Special H/W that use to PASS the test	None	None