

Motherboard Logo Program (MLP)

# Intel® Desktop Board DH77KC

## MLP Report

10/18/2012

#### Purpose:

This report describes the DH77KC Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel® Core™ i7 and Intel® are trademarks of Intel Corporation in the U.S. and other countries.

 $\ensuremath{^{\star}}\xspace 0 \text{ ther names}$  and brands may be claimed as the property of others

Copyright ° 2009, Intel Corporation. All rights reserved.

## **Contents**

Introduction	4
Terms and Definitions	
Desktop Board Configuration	5
Desktop Board DH77KC Final Configuration Report: Completion of MLP	5
Board Information	
Product Code	
Processor	5
Motherboard	5
System Memory	5
Power Management	5
Operating System Tested	
Onboard Integrated Devices and Driver for Windows 8 64-bit	
Windows Hardware Certification Kits Used (WHCK)	
Errata and Contingencies	
Test Notes	7

## Introduction

#### **Terms and Definitions**

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
WHCK	Windows Hardware Certification Kit
MLP	Motherboard Logo Program. For further information see: <a href="http://msdn.microsoft.com/en-us/windows/hardware/gg463010.aspx">http://msdn.microsoft.com/en-us/windows/hardware/gg463010.aspx</a>
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: <a href="http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;g=s">http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;g=s</a>

## **Desktop Board Configuration**

#### Desktop Board DH77KC Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

#### **Board Information**

Product Code <sup>1</sup>	BIOS String/Model	Technologies NOT Logo'd (yet)					
DH77KC	KCH7710H.86A.0102.2012.1008.1611	N/A - all technologies logo'd					
Processor	Processor						
Speed	3.4GHz						
Family	Intel Core i5 3570K						
Bus Speed	100 MHz						
Motherboard							
Board AA #	G39641						
Board FAB #	400 (eg. 10x for fab A, 20x for fab B and	etc)					
	es to the production FAB revision; Please co ion you intend to perform logo testing if no	onsult your Intel Corporation representative to clarify the of the same.					
System Memory							
Speed	Dual Channel, DDR3, 1600MHz						
Метогу Туре	DIMM						
Connector Type	DDR3, 240 Pin						
Power Management							
BIOS Default	ılt S3						
Operating System Tested							
	Check Tested	Comments					
Windows 8 64- bit	Ø	Windows 8 Professional					
Windows 7 and 64-bit	Windows 7 Ultimate Service Pack 1						
Windows Vista and 64-bit	Vista Ultimate with Service Pack 2						
Windows Vista Basic and 64-bit	□ Vista Basic with Service Pack 2						

<sup>&</sup>lt;sup>1</sup> These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

#### Onboard Integrated Devices and Driver for Windows 8 64-bit

Technology	OS	Version	Package version
Chipset Update Utility Intel® Chipset Software Utility	Windows 8 64-bit	V9.3.0.1021	INF_allOS_9.3.0.1021_ PV
<b>Graphics</b> Intel® HD Graphics 4000	Windows 8 64-bit	V9.17.10.2843	GFX_Win8_64_9.17.10 .2843_PV
<b>Audio</b> Realtek	Windows 8 64-bit	V6.0.1.6662	AUD_Win7_Win8_6.0.1. 6662_PV
<b>LAN</b> Intel <sup>®</sup> 82579V Gigabit	Windows 8 64-bit	V12.2.45.0	LAN_Win8_12.2.45.0_ PV
<b>MEI</b> Intel <sup>®</sup> Management Engine Interface	Windows 8 64-bit	V8.1.0.1263	MEI_1.5M_Win8_8.1.0. 1248_PV
litteriace			
USB 3.0			
Intel <sup>®</sup> USB 3.0 Extensible Host Controller	Windows 8 64-bit	V6.2.9200.16384	MS In box Driver

#### Windows Hardware Certification Kit Used (WHCK)

Microsoft website: <a href="http://msdn.microsoft.com/library/windows/hardware/hh833788">http://msdn.microsoft.com/library/windows/hardware/hh833788</a>

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows 8 64-bit	WHCK for Windows 8	WHCK for Windows 8

### **Errata and Contingencies**

Operating System	Failing Test	Expiry Date	ID Number	Туре	Error Description
Windows 8 64-bit	UAA Test (System)	12/2/2012	235	Erratum	UAA test was modified to turn warnings into errors for reserved bits being non-zero. This is a preview filter to allow IHVs to fix the issue.
Windows 8 64-bit	UAA Test (System)	7/2/2013	372	Contingency	Section 3.3.14 of the Intel High Definition Audio specification mandates a reset value of 0 for the Interrupt Control register on HD Audio controllers. Some Intel HD Audio controllers have bit 30 (Controller Interrupt Enable) and/or bit 31 (Global Interrupt Enable) set to 1 after a reset.
Windows 8 64-bit	UAA Test (System)	7/1/2013	244	Contingency	Section 3.3.14 of the Intel High Definition Audio specification mandates a reset value of 0 for the Interrupt Control register on HD Audio controllers.
Windows 8 64-bit	UAA Test (System)	7/1/2014	354	Contingency	The FIFO size for Input and Output Stream Descriptors should be read only

#### **Test Notes**

Operating System	Test	Description
Windows 8	BIOS download	Internal: <a href="http://bios.intel.com/downloads/">http://bios.intel.com/downloads/</a> External: <a href="http://www.intel.com/">http://www.intel.com/</a> click on Support and Download
Windows 8	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings.  System Date and Time: Current date and time Peripheral Configuration: Enable all onboard component (Except CIR) Drive Configuration: Set to AHCI Chipset Configuration: Enable HPET ACPI Suspend State: Set to <s3 state=""> Boot Device Priority: set <hard disk="" driver=""> to first  Note: Enhanced Consumer IR (CIR) component is not supported under Windows7.</hard></s3>
Windows 8 filter update	WHCK WHQL test	https://sysdev.microsoft.com/member/SubmissionWizard/LegalExemptions/HC KFilterUpdates.cab
Special H/W that use to PASS the test	None	None