

Motherboard Logo Program (MLP)

# Intel® Desktop Board DQ45CB

## MLP Report

9/9/2009

#### Purpose:

This report describes the DQ45CB Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NONINFRINGEMENT FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel®s Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel and Pentium are registered trademarks of Intel Corporation in the United States and other countries.

 $^{\star}\,$  Other names and brands may be claimed as the property of others.

Copyright © 2007 Intel Corporation. All rights reserved.

## Contents

Introduction	4
Terms and Definitions	
Desktop Board Configuration	5
Desktop Board DQ45CB Final Configuration Report: Completion of MLP	5
Board Information	5
Product Code	5
Processor	
Motherboard	5
System Memory	5
Power Management	5
Operating System Tested	5
Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit	6
Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit	
Windows Logo Kits Used (WLK)	7
Errata and Contingencies	
Test Notes	10

## Introduction

#### **Terms and Definitions**

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
WLK	Windows Logo Kits
MLP	Motherboard Logo Program. For further information see: <a href="http://www.microsoft.com/whdc/hwtest/default.mspx">http://www.microsoft.com/whdc/hwtest/default.mspx</a>
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: <a href="http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;g=s">http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&amp;cid=105&amp;g=s</a>

## **Desktop Board Configuration**

#### Desktop Board DQ45CB Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

#### **Board Information**

Product Code <sup>1</sup>	BIOS String/Model	Technologies NOT Logo'd (yet)				
DQ45CB	CBQ4510H.86A.0085.2009.0610.1407	N/A - all technologies logo'd				
Processor						
Speed	3.0GHz					
Family	Intel® Core™2 Quad					
Bus Speed	1333 MHz					
Motherboard						
Board AA #	E30148					
Board FAB #	205					
	es to the production FAB revision; Please co ion you intend to perform logo testing if no	nsult your Intel Corporation representative to clarify the the same.				
System Memory						
Speed	Dual Channel, DDR2, 800MHz					
Memory Type	DIMM					
Connector Type	DDR2, 240 Pin					
Power Management						
BIOS Default	S3					
Operating System	Operating System Tested					
	Check Tested Comments					
Windows 7 and 64-bit		Windows 7 Ultimate				
Windows Vista and 64-bit	Vista Ultimate with Service Pack 1					
Windows Vista Basic and 64-bit	□ Vista Basic with Service Pack 1					

<sup>&</sup>lt;sup>1</sup> These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

#### Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit

Technology	OS	Version	Package version			
Chipset Update Utility	Windows Vista	9.0.0.1009	9.0.0.1009			
Intel <sup>®</sup> Chipset Software Utility	Windows Vista 64-bit	9.0.0.1009	9.0.0.1009			
-						
Graphics	Windows Vista	7.15.10.1537	15.11.0.1537			
Intel® Graphics Media Accelerator	Windows Vista 64-bit	7.15.10.1537	15.11.64.1537			
Audio	Windows Vista	6.10.1.6520	6520			
ADI	Windows Vista 64-bit	6.10.1.6520	6520			
LAN	Windows Vista	10.3.39.0	13.5			
Intel® PRO Network Connections	Windows Vista 64-bit	10.3.39.0	13.5			
MEI	Windows Vista	5.0.1.1055	5.0.0.1098			
Intel <sup>®</sup> Management Engine Interface	Windows Vista 64-bit	5.0.1.1055	5.0.0.1098			
iAMT	Windows Vista	5.5.0.1057	5.0.0.1098			
Intel <sup>®</sup> Active Management Technology	Windows Vista 64-bit	5.5.0.1057	5.0.0.1098			

#### Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit

Technology	OS	Version	Package version			
Chipset Update Utility	Windows 7	9.1.1.1015	9.1.1.1015			
Intel <sup>®</sup> Chipset Software Utility	Windows 7 64-bit	9.1.1.1015	9.1.1.1015			
Graphics	Windows 7	8.15.10.1855	15.15.0.1855			
Intel <sup>®</sup> Graphics Media Accelerator	Windows 7 64-bit	8.15.10.1808	15.15.3.64.1855			
Audio	Windows 7	6.10.2.6585	6585			
ADI	Windows 7 64-bit	6.10.2.6585	6585			
LAN	Windows 7	11.0.41.0	14.2			
Intel® PRO Network Connections	Windows 7 64-bit	11.0.41.0	14.2			
MEI	Windows 7	5.2.0.1008	5.2.0.1018			
Intel <sup>®</sup> Management Engine Interface	Windows 7 64-bit	5.2.0.1008	5.2.0.1018			
iAMT	Windows 7	5.5.1.1012	5.2.0.1018			
Intel® Active Management						
Technology	Windows 7 64-bit	5.5.1.1012	5.2.0.1018			

#### Windows Logo Kits Used (WLK)

Microsoft website: <a href="http://www.microsoft.com/whdc/DevTools/WDK/DTM.mspx">http://www.microsoft.com/whdc/DevTools/WDK/DTM.mspx</a>

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows 7 Windows 7 64-bit	WLK1.4 for Windows 7	WLK1.4 for Windows 7
Windows Vista Windows Vista 64-bit	WLK1.4 for Windows Vista SP1	WLK1.4 for Windows Vista SP1

### Errata and Contingencies

		Expiry	ID		
Operating System	Failing Test	Date	Number	Туре	Error Description
Windows 7 Windows 7 64-bit	1)Class Driver Fidelity Test - Win7 (System, Manual)  2)Fidelity Test - Win7 (System, Manual)	12/01/2009	1417	Erratum	Fidelity Test includes a "System Activity Test" that verifies audio fidelity is not compromised during system activity.  It uses an activity generator called rws.exe (Real World Stress) which has a bug that causes it to hit an access violation. When this happens it exits with return code 0xC00000005, or - 1073741819.
Windows 7 Windows 7 64-bit	1)Class Driver Fidelity Test - Win7 (System, Manual)  2)Fidelity Test - Win7 (System, Manual)	12/31/2009	1547	Erratum	Fidelity Test now includes a "Render Power Transition" test. This preview filter covers all errors in this new test of SYSFUND-0050.
Windows 7 Windows 7 64-bit	Class Driver Fidelity Test - Win7 (System, Manual)	12/01/2009	1670	Erratum	EU restrictions place a cap on the output level of headphone jacks at 32 Ohm load: headphones are not allowed to have an electrical output of more than 150 mV at that load.  We test headphone jacks at 300 Ohm load; the relationship between the output at 32 Ohms and the output at 320 Ohms depends on the output impedance of the headphone jack.  In particular, if a headphone jack meets the EU requirement of X <= 150 mV at 32 Ohms, depending on the output impedance, it could output a huge amount of power at 300 Ohms, or very slightly over X mV. Since we require X >= 120 mV at 32 Ohms, absent knowledge of the output impedance we can only require X >= 120 mV at 300 Ohms.  120 mV is -18.42 dBV. Any headphone output level at 32 Ohms that is less than -18.42 dBV is a legitimate failure, even if it is targeted at EU compliance. Any headphone output level greater than 1 Vrms (0.707 Vrms for mobile systems) is a legitimate pass, regardless of EU compliance.  This errata covers output level failures for headphone jacks between -18.42 dBV and 1 Vrms/0 dBV (0.707 Vrms/-6.93 dBV for mobile systems)) in accordance with note 6 of the WLP fidelity requirements.
Windows 7 Windows 7 64-bit	Class Driver Fidelity Test - Win7 (System, Manual)	12/01/2009	1424	Erratum	Fidelity plays a quiet (-60 dB FS) test tone during System Activity test which is filtered out of the noise level measurement.  However, Fidelity is quite prone to glitches during system activity the glitches leak into the measured noise, causing false failures.
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/31/2009	385	Erratum	The following PCI Compliance test failure is acceptable: Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return 0 as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges. Assertion 13A41D3E-2576-41DC-A67C-525DA3637CEA This failure is acceptable because this is a PCIe 1.1 feature and the WLP requires compliance with only PCIe 1.0a.

Windows 7	PCI Hardware	12/31/2009	1029	Erratum	Assertion B576282C-5C66-4253-A275-257F5D49EFEF
Windows 7 64-bit	Compliance Test For Systems	72/01/2000	. 525		SSVID register of the Subsystem ID and Subsystem Vendor ID Capability table cannot have a value of 0h.
	Systems				Assertion 4BA8F23A-6BB1-48EE-88D8-ED1A3ECD34B9
					SSVID register of the Subsystem ID and Subsystem Vendor ID Capability table must be read-only .
					Assertion 6B0F606E-DBB3-4B8C-8879-32B302412EB8
					SSID register of the Subsystem ID and Subsystem Vendor ID Capability table must be read-only .
					Assertion 7A5587BC-5646-4DC4-9A5D-22F85AB2204E
					PCI Express ports and bridges must implement Subsystem ID and Subsystem Vendor ID Capability.
Windows 7 Windows 7 64-bit	UAA Test - Win7 (System)	12/01/2009	1394	Erratum	UAA Test requires the Traffic Priority bit to be read/write - however there are two specs that apply, and they conflict. One says the bit must be read/write, the other says it must be read-only. Contact has been made with the author of both specs (Intel) but until this point is clarified we cannot fail submissions containing this test failure.
Windows 7 Windows 7 64-bit	UAA Test - Win7 (System)	12/31/2009	1395	Erratum	Certain ADI audio codecs do not correctly implement PinControls. In particular, setting unsupported VRef settings is not zerod out in the register. This requires a hardware change. There is hardware validation, so the unsupported settings are not applied. The unsupported VRefs in question are:  0b011 (Reserved) 0b101 (100%) 0b110 (Reserved) 0b111 (Reserved) This affects the following ADI codecs:  AD1981HD (DEV_1981) AD1983 (DEV_1983) AD1984 (DEV_1984) AD1984 (DEV_194A) AD1984B (DEV_194A) AD1984B (DEV_194B) AD1986A (DEV_1986) AD1987 (DEV_1987) AD1988B (DEV_1988) AD1988B (DEV_198B) AD1882 (DEV_1882) AD1883 (DEV_1883) AD1884 (DEV_1884)  For unsupported VRefs, the pin must either retain the previous value or take the value of 0b000 (Hi-Z). See HD Audio specification section 7.3.3.13.

Windows 7 Windows 7 64-bit	UAA Test - Win7 (System)	12/01/2009	1396	Erratum	Certain ADI audio codecs do not correctly implement PinControls. In particular, unsetting InputEnable and OutputEnable does not allow turning off the audio input or output of a pin. This requires a hardware design fix. The particular failures are:
					Turning an input pin off leaves it on
					Turning an output pin off leaves it on
					Setting an input/output pin to output leaves it as input

#### **Test Notes**

Operating System	Test	Description
Windows 7 and Vista	BIOS download	Internal: <a href="http://bios.intel.com/downloads/">http://bios.intel.com/downloads/</a> External: <a href="http://www.intel.com/">http://www.intel.com/</a> click on Support and Download
Windows 7 and Vista	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings.  System Date and Time: Current date and time Peripheral Configuration: Enable all onboard component (Except CIR) Drive Configuration: Set to IDE Chipset Configuration: Enable HPET ACPI Suspend State: Set to <s3 state=""> Boot Device Priority: set <hard disk="" driver=""> to first  Note: Enhanced Consumer IR (CIR) component is not supported under Windows7.</hard></s3>
Windows 7 and Vista filter update	WLK WHQL test	http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filterupdates.cab
Special H/W that use to PASS the test	None	None