

Motherboard Logo Program (MLP)

Intel® Desktop Board DG33FB

MLP Report

4/9/2008

Purpose:

This report describes the DG33FB Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NONINFRINGEMENT FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel®s Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel and Pentium are registered trademarks of Intel Corporation in the United States and other countries.

 $^{\star}\,$ Other names and brands may be claimed as the property of others.

Copyright © 2007 Intel Corporation. All rights reserved.

Contents

Introduction	4
Terms and Definitions	
Desktop Board Configuration	5
Desktop Board DG33FB Final Configuration Report: Completion of MLP	
Board Information	5
Product Code	5
Processor	
Power Management	5
Operating System Tested	5
Onboard Integrated Devices and Driver	6
Driver Test Manager Used (DTM)	7
Errata and Contingencies	8
Test Notes	9

Introduction

Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
DTM	Driver Test Manager
MLP	Motherboard Logo Program. For further information see: http://www.microsoft.com/whdc/hwtest/default.mspx
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&cid=105&g=s

Desktop Board Configuration

Desktop Board DG33FB Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

Board Information

Product Code ¹	BIOS String/Model	Technologies NOT Logo'd (yet)		
DB33FB	DPP3510J.86A.0413.2008.0306.2218	N/A - all technologies logo'd		
Processor	Processor			
Speed	2.66GHz			
Family	Intel® Core™2 Quad			
Bus Speed	1066 MHz			
Motherboard				
Board AA #	D81072			
Board FAB #	306			
	es to the production FAB revision; Please or ion you intend to perform logo testing if n	consult your Intel Corporation representative to clarify the ot the same.		
System Memory				
Speed	Dual Channel, DDR2, 800	Dual Channel, DDR2, 800		
Метогу Туре	DIMM			
Connector Type	DDR2, 240 Pin			
Power Management				
BIOS Default S3				
Operating System Tested				
	Check Tested	Comments		
Windows XP Pro	Ø	XP Pro with Service Pack 3 RC2		
Windows XP Pro 64-bit	✓ XP Pro with Service Pack 2			
Windows Vista	✓ Vista Ultimate with Service Pack 1			
Windows Vista 64-bit	✓ Vista Ultimate with Service Pack 1			
Windows Vista Basic	□ Vista Basic with Service Pack 1			

¹ These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

Windows Vista ☐ Basic 64-bit	Vista Basic with Service Pack 1
------------------------------	---------------------------------

Onboard Integrated Devices and Driver for XP Pro 32 and 64bit

Technology	OS	Version	
Chipset Update Utility	Windows XP Pro	8.4.0.1016	
Intel [®] Chipset Software Utility	Windows XP Pro 64-bit	8.4.0.1016	
Graphics	Windows XP Pro	14.32.3.4906	
Intel [®] Graphics Media Accelerator	Windows XP Pro 64-bit	14.32.3.64.4906	
Audio	Windows XP Pro	5574	
Realtek	Windows XP Pro 64-bit	5574	
LAN	Windows XP Pro	12.1	
Intel® PRO Network Connections	Windows XP Pro 64-bit	12.1	
HECI	Windows XP Pro	3.0.30.1086	
Intel® Management Engine Interface	Windows XP Pro 64-bit	3.0.30.1086	

Onboard Integrated Devices and Driver for Vista 32 and 64bit

Technology	OS	Version	
Chipset Update Utility	Windows Vista	8.4.0.1016	
Intel [®] Chipset Software Utility	Windows Vista 64-bit	8.4.0.1016	
Graphics	Windows Vista	15.7.3.1409	
Intel [®] Graphics Media Accelerator	Windows Vista 64-bit	15.7.3.64.1409	
Audio	Windows Vista	5548	
Realtek	Windows Vista 64-bit	5548	
LAN	Windows Vista	12.1	
Intel® PRO Network Connections	Windows Vista 64-bit	12.1	
HECI	Windows Vista	3.0.30.1086	
Intel® Management Engine Interface	Windows Vista 64-bit	3.0.30.1086	

Driver Test Manager Used (DTM)

Microsoft website: http://www.microsoft.com/whdc/DevTools/WDK/DTM.mspx

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows XP Pro Windows XP Pro 64-bit	DTM for Windows XP SP3	DTM for Windows XP SP3
Windows Vista Windows Vista 64-bit	DTM for Windows Vista SP1	DTM for Windows Vista SP1

Errata and Contingencies

Operating System	Failing Test	Expiry date	ID Number	Туре	Error Description
Windows Vista Windows Vista 64-bit	PCI Hardware Compliance Test For Systems Running Windows Vista (PCIHCT)	3/5/2008	990	Erratum	The Bit 5 (Surprise Down Error Severity) in the Uncorrectable Error Severity register (offset Ch) in the Advanced Error Reporting Capability table must be read-only and always return 1 if the Bit 5 (Surprise Down Error Mask) in the Uncorrectable Error Mask Register in the Advanced Error Reporting Capability table is not implemented
Windows Vista Windows Vista 64-bit	PCI Hardware Compliance Test For Systems Running Windows Vista (PCIHCT)	12/31/20 08	385	Erratum	The following PCI Compliance test failure is acceptable: Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return 0 as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges. Assertion 13A41D3E-2576-41DC-A67C-525DA3637CEA This failure is acceptable because this is a PCIe 1.1 feature and the WLP requires compliance with only PCIe 1.0a.
Windows Vista Windows Vista 64-bit	PCI Hardware Compliance Test For Systems Running Windows Vista (PCIHCT)	12/31/20 08	709	Erratum	Certain devices are known to have incompatibilities with the test causing a system hang during testing. This erratum is for those devices The PCIHCT tests Bit 15 of the Device Control Register in the PCI Express Capability table. The testing of Bit 15, specifically the writing of a 1 to the bit causes a function level reset making the device unavailable for a maximum of 100ms. All writes to the PCI config space of the device are ignored during the reset. All reads to the PCI config space of the device return all ones (1). This confuses the PCIHCT test and it incorrectly fails the assertions for Bits 4, 11, 12, 13 and 14. Assertion 73C19B53-84B8-4BA4-97EA-3FF6DEF57273: FAILED. Bit 4 (Enable Relaxed Ordering) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-writable if it's implemented. Assertion C0846E74-2CFE-4CC2-A492-6AAF16F206CD: FAILED. Bit 11 (Enable No Snoop) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-writable if it's implemented. Assertion A56B0EE0-0C2C-47A4-90C4-5F8EEB30D427: FAILED. Bit range 14:12 (Max_Read_Request_Size)in the Device Control register (offset 8h) in the PCI Express Capability table must be read-writable if implemented. Assertion 13A41D3E-2576-41DC-A67C-525DA3637CEA: FAILED. Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return 0 as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges.
Windows Vista Windows Vista 64-bit Windows XP Pro Windows XP Pro 64- bit	UAA Test - Vista (System)	7/31/200 8	534	Erratum	UAA Test requires the Traffic Priority bit to be read/write - however there are two specs that apply, and they conflict. One says the bit must be read/write, the other says it must be read-only. Contact has been made with the author of both specs (Intel) but until this point is clarified we cannot fail submissions containing this test failure.
Windows XP Pro	System - Common Scenario Stress With IO	8/31/200 9	310	Erratum	On Windows XP, the system occasionally will fail to go to sleep during this test. When this occurs, a "Windows - System Error: Insufficient system resources exist to complete the API." popup occurs in the system tray. This seems to be an issue with Windows XP only, and occurs most often when testing mass storage controllers and devices. This issue has been filtered out. Please verify that the system goes to sleep and hibernates manually without error, otherwise the end user may run into this problem. This should be verified multiple times

Test Notes

Operating System	Test	Description
XP and Vista	BIOS download	Internal: http://bios.intel.com/downloads/ External: http://www.intel.com/ click on Support and Download
XP and Vista	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings. System Date and Time: Current date and time Peripheral Configuration: Enable all onboard component Drive Configuration: Set to IDE Chipset Configuration: Enable HPET ACPI Suspend State: Set to <s3 state=""> Boot Device Priority: set <hard disk="" driver=""> to first</hard></s3>
XP and Vista Filter update	DTM WHQL test	http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filterupdates.cab
Special H/W that use to PASS the test	None	None
Vista 64-Bit	LAN driver installation	LAN Driver has to be installed manually. Extract the LAN driver folder and updated the driver directly from device manager.