



Intel® Motherboard

DH55TC

MLP REPORT

11/12/2009

Purpose:

This report describes the DH55TC Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NONINFRINGEMENT FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel and Pentium are registered trademarks of Intel Corporation in the United States and other countries.

* Other names and brands may be claimed as the property of others.

Copyright © 2007 Intel Corporation. All rights reserved.

Contents

- Introduction4**
 - Terms and Definitions..... 4
- Motherboard Configuration5**
 - Motherboard DH55TC Final Configuration Report: Completion of MLP 5
 - Board Information 5
 - Product Code..... 5
 - Processor 5
 - Motherboard 5
 - System Memory 5
 - Power Management 5
 - Operating System Tested 5
 - Driver Test Manager Used (DTM) 6
 - Errata / Contingency..... 7
 - Test Notes 7

Introduction

Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
DTM	Driver Test Manager
MLP	Motherboard Logo Program. For further information see: http://www.microsoft.com/whdc/hwtest/default.mspx
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&cid=105&q=s

Motherboard Configuration

Motherboard DH55TC Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

Board Information

Product Code ¹	BIOS String/Model	Technologies NOT Logo'd (yet)
DH55TC	TCIBX10H.86A.0020.2009.1019.2043	N/A - all technologies logo'd
Processor		
Speed	3.46 GHz	
Family	Intel® Core(TM) i5 670	
Bus Speed	1333Mhz	
Motherboard		
Board AA #	E70932	
Board FAB #	201	
System Memory		
Speed	Dual Channel, DDR3, 1333MHz	
Memory Type	DIMM	
Connector Type	DDR3, 240 Pin	
Power Management		
BIOS Default	S3	
Operating System Tested		
	Check Tested	Comments
Windows Vista	<input checked="" type="checkbox"/>	Vista 32 SP2
Windows Vista 64-bit	<input checked="" type="checkbox"/>	Vista 64 SP2
Windows 7	<input checked="" type="checkbox"/>	Windows 7
Windows 7 64-bit	<input checked="" type="checkbox"/>	Windows 7

¹ These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

Onboard Integrated Devices and Driver for Vista 32 & Vista 64

Technology	OS	Version
Chipset Update Utility Intel® Chipset Software Utility	Windows Vista	V9.1.1.1015
	Windows Vista 64bit	V9.1.1.1015
Graphics Intel(R) Graphics Media Accelerator HD	Windows Vista	V8.15.10.1952
	Windows Vista 64bit	V8.15.10.1952
Audio Realtek	Windows Vista	V6.0.1.5901
	Windows Vista 64bit	V6.0.1.5901
LAN Intel(R) 82578DC	Windows Vista	V11.2.19.0
	Windows Vista 64bit	V11.2.19.0
MEI Intel® Management Engine Interface	Windows Vista	V 6.0.0.1179
	Windows Vista 64bit	V 6.0.0.1179

Onboard Integrated Devices and Driver for Windows 7 32 & Windows 7 64

Technology	OS	Version
Chipset Update Utility Intel® Chipset Software Utility	Windows 7	V9.1.1.1015
	Windows 7 64bit	V9.1.1.1015
Graphics Intel(R) Graphics Media Accelerator HD	Windows7	V8.15.10.1952
	Windows 7 64bit	V8.15.10.1952
Audio Realtek	Windows 7	V6.0.1.5901
	Windows 7 64bit	V6.0.1.5901
LAN Intel(R) 82578DC	Windows 7	V11.2.19.0
	Windows 7 64bit	V11.2.19.0
MEI Intel® Management Engine Interface	Windows 7	V 6.0.0.1179
	Windows 7 64bit	V 6.0.0.1179

Driver Test Manager Used (DTM)

Microsoft website: <http://www.microsoft.com/whdc/DevTools/WDK/DTM.msp>

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit
Windows Vista Windows Vista 64 bit	DTM for Windows Vista	WLK1.4 for Windows Vista

Errata / Contingency

Test Notes

Operating System	Failing Test	Expiry date	ID Number	Type	Error Description
Windows Vista Windows Vista 64	Fidelity Test-Vista (System, Manual)	12/31/2009	1238	Erratum	Fidelity Render Power Transition test
	GlitchFree WMV HD 720p video playback quality test	12/31/2009	1245		GlitchFree WMV HD 720p video playback quality test cases 2 & 3 Preview for 6 months post WLK1.4 release
	HDAudio Class Driver Fidelity Test-Vista(System, Manual)	12/31/2009	1238		Fidelity Render Power Transition test
		12/1/2009	598		Fidelity Test: European Union requirement for headphone Output Level false-failed.
	HDAudio Class Driver Test - Vista or Server08(System)	6/1/2010	1256		AC3 Test: HD Audio class driver exposes MaximumBitsPerSample = 24, should be 16
		6/1/2010	142		PREVIEW FILTER - HDMI is required to support 44.1 kHz on Windows 7
	PCI Hardware Compliance Test For System	6/1/2010	1241		PCI Compliance - Data Link Layer Link Active Reporting Capable bit is set but Data Link Layer Link Active is not. Assertion 0E36472A-0EDB-4685-A67D-7AF1FFBFA81B
		12/31/2009	401		PCI Compliance - Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return 0 as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges.
	UAA Test--Vista or Server08(System)	6/1/2011	1466		UAA Test: Preview Filter - Intel Low Power DCN says "EPSS implies KeepAlive, but only after July 1st 2011"
		6/1/2010	1299		UAA Test: Some digital pin widgets incorrectly set Jack Detect Override
		6/1/2010	1288		UAA Test: preview filter for Encoded Packet Type validation
		6/1/2010	1351		UAA Test false-fails codecs in D3 Cold that don't respond to both halves of double-function-group reset
		12/1/2009	513		UAA Test (System) fails Intel HD Audio controller whose Traffic Priority bit is not read/write.
	Wave Test -Vista or Server08(System)	6/1/2010	1281		WaveTest false-fails user-disabled endpoints like CD In, Stereo Mix, etc.

Operating System	Failing Test	Expiry date	ID Number	Type	Error Description
Windows 7 Windows 7 64	Class Driver AC3 Test - Win7 (System)	6/1/2010	1256	Erratum	AC3 Test: HD Audio class driver exposes MaximumBitsPerSample = 24, should be 16
	Class Driver Fidelity Test - Win7 (System, Manual)	12/1/2009	598		Fidelity Test: European Union requirement for headphone Output Level false-failed.
		12/31/2009	1238		Fidelity Render Power Transition test
	PCI Hardware Compliance Test For Systems	6/1/2010	1241		PCI Compliance - Data Link Layer Link Active Reporting Capable bit is set but Data Link Layer Link Active is not. Assertion 0E36472A-0E8B-4685-A67D-7AF1FFBFA81B
		12/31/2009	401		PCI Compliance - Bit 15 (Bridge Configuration Retry Enable) in the Device Control register (offset 8h) in the PCI Express Capability table must be read-only and always return 0 as it is reserved for devices other than PCI Express to PCI/PCI-X Bridges.
	UAA Test - Win7 (System)	6/1/2011	1466		UAA Test: Preview Filter - Intel Low Power DCN says "EPSS implies KeepAlive, but only after July 1st 2011"
		6/1/2010	1299		UAA Test: Some digital pin widgets incorrectly set Jack Detect Override
		6/1/2010	1288		UAA Test: preview filter for Encoded Packet Type validation
		6/1/2010	1351		UAA Test false-fails codecs in D3 Cold that don't respond to both halves of double-function-group reset
		6/1/2010	1348		UAA Test digital converter channel to HDMI slot mapping failures
		12/31/2009	1198		UAA Test Preview errata: S/PDIF pin "Pin Sense" responses cannot use "Impedance" bits
		12/1/2009	513		UAA Test (System) fails Intel HD Audio controller whose Traffic Priority bit is not read/write.
	Wave Test - Win7 (System)	6/1/2010	1281		WaveTest false-fails user-disabled endpoints like CD In, Stereo Mix, etc.

Operating System	Test	Description
Windows 7 & Vista	BIOS download	Internal: http://bios.intel.com/downloads/ External: http://www.intel.com/ click on Support and Download
Windows 7 & Vista	BIOS setup	Please make sure the BIOS setting as below. System Date and Time: Current date and time Peripheral Configuration: Enable all onboard component Drive Configuration: Set to IDE Chipset Configuration: Enable HPET ACPI Suspend State: Set to <S3 State> Boot Device Priority: set <Hard Disk Driver> to first
Windows 7 & Vista Filter update	DTM WHQL test	http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filterupdates.cab
Special H/W that use to PASS the test	None	None