

Specification Update

**Intel® Modular Server System MFSYS25,
Intel® Modular Server System MFSYS25V2,
Intel® Modular Server System MFSYS35,
Intel® Compute Module MFS5000SI,
Intel® Compute Module MFS5520VI**

Intel Order Number E29976-040

September, 2011

Enterprise Platforms and Services Division

Revision History

Date	Modifications
November 2007	Initial release.
December 2007	Addition of erratum #14
January 2008	Addition of documentation change #2 & Erratum #15, Erratum 8 & 10 Moved to Fixed
May 2008	Updated existing erratum and added new erratum
August 2008	Updated existing erratum
October 2008	Updated existing erratum and product scope
November 2008	Updated existing erratum and added new erratum
December 2008	Updated existing erratum and added new erratum
January 2009	Updated existing erratum and added new erratum
February 2009	Added MFSYS35 to Spec Update. Updated existing erratum and added new erratum
March 2009	Updated existing erratum and added new erratum
April 2009	Updated existing erratum and added new erratum
May 2009	Added MFS5520VI to Spec Update. Updated existing erratum and added new erratum.
June 2009	Updated existing erratum and added new erratum
July 2009	Addition of erratum #35,36 and 37 and update documentation change
August 2009	Updated product scope.
September 2009	Addition of erratum #38 and 39
October 2009	Updated existing erratum.
November 2009	Updated existing erratum.
December 2009	Updated existing erratum and added new erratum #40 and 41.
January 2010	Updated product scope, existing erratum and added new erratum #42.
February 2010	Updated existing erratum.
March 2010	Add new erratum #43 and #44.
April 2010	No Update
May 2010	Add new documentation change #5 and new erratum#45.
June 2010	Updated erratum #40, added new erratum#46.
Jul 2010	Add new erratum #47, #48 and #49.
August 2010	Add new erratum #50
September 2010	Updated Product Scope, add new erratum #51
October 2010	Add new erratum #52
November 2010	Add new erratum #53, #54 and #55
December 2010	Add new erratum #56
January 2011	Updated product scope, updated erratum #52.
March 2011	Updated erratum #50
April 2011	No Update
May 2011	Add new erratum #57
June 2011	Updated erratum #55, #57 and added new erratum #58
July 2011	Add new erratum #59
August 2011	Add new erratum #60
September 2011	Add new erratum #61

Disclaimers

The Specification Update Server System may contain design defects or errors known as errata that may cause the product to deviate from the published specifications. Current characterized errata are documented in this Specification Update.

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation.

*Other brands and names may be claimed as the property of others.

Copyright © Intel Corporation 2011.

Contents

Preface	1
1. Product Code: MFS5000SI – Intel® Compute Module MFS5000SI	2
2. Product Code: MFS5000SIB – Intel® Compute Module MFS5000SI – 3 Pack	2
3. Product Code: MFS5520VI – Intel® Compute Module MFS5520VI	2
4. Product Code: MFS5520VIR – Intel® Compute Module MFS5520VIR	3
5. Product Code: MFS5520VIB – Intel® Compute Module MFS5520VI – 3 Pack	3
6. Product Code: MFS5520VIBR – Intel® Compute Module MFS5520VI R– 3 Pack	3
7. Product Code: MFSYS25 – Intel® Modular Server System MFSYS25	3
8. Product Code: MFSYS35 – Intel® Modular Server System MFSYS35	4
9. Product Code: MFSYS25V2 – Intel® Modular Server System MFSYS25V2	4
10. Product Code: AXXSCM3S – Intel® Storage Controller	4
11. Product Code: AXXSW1GB – Intel® Gigabit Ethernet Switch AXXSW1GB	5
12. Product Code: MFCMM – Intel® Management Module	5
13. Product Code: MFCMM2 – Intel® Management Module 2	5
14. Product Code: AXXPSU – 1000W Power Supply	5
15. Product Code: MFMIDPLANE – Intel® Modular Server System MFSYS25 – Midplane Board	6
16. Product Code: MFMIDPLANE – Intel® Modular Server System MFSYS35 – Midplane Board	6
17. Product Code: MFMIDPLANE2 – Intel® Modular Server System MFSYS25V2 – Midplane Board	6
18. Product Code: AXXGBIOMEZ – Intel® Compute Module MFS5000SI – Dual Gigabit Ethernet Expansion Card.....	6
19. Product Code: AXXGBIOMEZV – Intel® Compute Module MFS5520VI – Dual Gigabit Ethernet Expansion Card.....	7
Summary Tables of Changes	8
Errata	13
1. Intel® Compute Module MFS5000SI NIC/Activity LEDs do not display a link status	13
2. MFS5000SI remote floppy is not supported	13
3. 1024x768 Resolution with color depth set to thousands of colors not supported under Red Hat* Enterprise Linux 5.0 64-bit	13
4. NIC Utility <code>dcreate.exe</code> on MFS500SI -003 Resource CD incomplete.....	14
5. Event Log may report SMI Timeout Assertion after Server Power button is pressed	14
6. User is not able to configure different responses to pressing the Server Power button in Microsoft Windows 2008* Enterprise Server Edition	14
7. Dual Intel® Storage Controller configuration not yet supported in the Intel® Modular Server System MFSYS25 and MFSYS35	15
8. System Fault LED does not come on if smart devices (SCMs, ESMs, etc.) are completely non-functional.....	16
9. Deleting existing assigned virtual drive may result in GUI action failure	16

10.	Certain Non-critical Events logged as Critical in GUI.....	16
11.	System Fault LED does not turn on for all critical events.....	17
12.	Email Alerting not enabled by default for three Critical Events.....	17
13.	Removing/Inserting USB devices during BIOS POST or in EFI may cause unexpected system behavior	18
14.	Simultaneous Remote KVM installs of OS or applications will not successfully complete on MFS5000SI.....	18
15.	Relative and Absolute KVM Mouse Mode not Supported on all Operating System's	19
16.	Compute Modules with RAID 6 Virtual Drives Experiencing Slow Response	19
17.	CONFIRM dialog box action not required to complete requested action.....	20
18.	Pressing F1 during a KVM session will bring up the local KVM console help not the remote system application help.....	20
19.	Ethernet Switch Module will fail to automatically update in an operational chassis	21
20.	Microsoft Windows Server 2003* cluster support not available	21
21.	Suse Enterprise Linux 10* U1 cluster node shown as running after being physically removed from chassis after failure	22
22.	Fujitsu 146GB, 2.5" SAS hard drive takes longer than expected to come on line after a hot insertion.....	22
23.	BIOS R0048 Does Not Support Mixed Stepping E-0 and C-0 Processors.....	23
24.	In Windows Enterprise Server 2008* Cluster failover testing, it has been observed that cluster nodes may lose access to the clustered shared LUN drives.....	23
25.	The CMM is not able to provide management information for the power supply when an AXXPSU at revision D73299-006 is installed in a system chassis.....	24
26.	The Network Time Server setting on the date/time web page of the Intel® Modular Server Control GUI does not allow selection of time zones	24
27.	SuSE* Linux Enterprise Server 10 U1 will mark the OS LUN as read only if a SCM affinity change is made while the SUSE* Linux Enterprise Server 10 operating system is running or booted	25
28.	Chassis fault LED does not illuminate after removing a Main Fan module or the I/O Fan module.....	25
29.	Local video disappears with Console Redirection and Quiet Boot Enabled in the MFS5520VI compute module.....	26
30.	Speed Step Disable in BIOS setup disables the LSI SAS controller in the MFS5520VI compute module.....	26
31.	Red Hat Enterprise Linux AS 5.0 U3, 32 bit Xen kernel, only shows 13GB of memory when more than 14GB of memory is installed.....	26
32.	MPIO takes a long time to install under Microsoft Windows* 2003 Cluster	27
33.	Virtual Drives from external ports are not recognized on reboot with Microsoft Windows* 2003 Enterprise.....	27
34.	Extraction and quick reinsertion of the Intel® Server Compute Module MFS5520VI may cause various issues	27
35.	DIMM temperature warning in VMWare ESX 3.5 and ESX 4.0	28
36.	MFS5000SI compute module occasionally hangs during LTO-4 tape backup operations	28

37.	Virtual Drives within a Storage Pool may lose server assignments after a Virtual Drive has been deleted	28
38.	LUN Copier not activated with valid key	29
39.	RAID 10 to RAID 1E Automatic Migration	29
40.	The installation of SLES 11 x86_64 fails on SSD	29
41.	GMM Web GUI SSL certification expired on Oct 27 2009	29
42.	rKVM right Alt+F1 in VMWare 3.5, 4.0 launches help instead of ESX server console	30
43.	ESM will increase the counter of "Received Pause Frames" when receiving erroneous or illegal packets	30
44.	Excessive SEL logs may report after SuSE* Linux installed.....	31
45.	CPU L1 and L2 cache size incorrect in MFS5520VI BIOS	31
46.	Fail to launch remote KVM under Redhat Desktop WS 5.5.....	31
47.	CMM is not able to control date and time of Ethernet Switch Module	31
48.	Reset Ethernet Switch Module from "Advanced Configuration" will not generate "reset" event log.....	32
49.	The rKVM will be black screen when SUSE11 boot to login screen with S5000SI board	32
50.	The size of installed DIMM is wrong when mirroring mode on with MFS5000SI...	33
51.	The rKVM console may report "Invalid session ticket" or "Authentication Failed".	33
52.	Select rKVM help function by using hot key fail	33
53.	Mixed processors population will disable CPU2.....	34
54.	When Virtual Drive migration or expansion is running, and HDD physically removed, no failure reported.	34
55.	Lower network performance may be observed when Hyper-V role is added in Windows* Server 2008 R2 with more than 32GB memory	34
56.	Illegal FC packets counted as good FC packets in Ethernet Switch Module interface statistics	35
57.	Ethernet Switch Module Jumbo Frame changes not consistently being saved....	35
58.	Rebuild stuck at 99% when Storage Pool contains VD with RAID 0	36
59.	rKVM Mouse not syncing properly with SLES 11 Enterprise 64 bit SP1	36
60.	MFS5520VI may display incorrect POST code for memory error.....	36
61.	HDD cache enable does not enable HDD cache with UFU 10.3 and 10.4.....	37
Documentation Changes		38
1.	System Fault LED not depicted in front system views in Intel® Modular Server System MFSYS25 documentation	38
2.	Power Budget Information Incorrect in Intel® Modular Server System MFSYS25 TPS	38
3.	Release Notes, Section G, Red Hat* Enterprise Linux 5 Server U1 (32bit and 64bit) is incorrectly listed as supporting shared LUN	39
4.	Intel® Modular Server System MFSYS25/MFSYS35 Quick Start User's Guide has an incorrect Package Contents list.....	39
5.	Intel® Compute Module MFS5520VI Technical Product Specification has an incorrect statement about Turbo Mode setting	39

Preface

This document is an update to the specifications contained in the *Intel® Modular Server System MFSYS25/MFSYS35 Technical Product Specification* and the *Intel® Compute Module MFS5000SI Technical Product Specification*. It is intended for hardware system manufacturers and software developers of applications, operating systems, or tools. It will contain specification changes, specification clarifications, errata, and document changes.

Refer to the *Intel® Xeon® Processor 5100 Series and Intel® Xeon® Processor 5200 Series and Intel® Xeon® Processor 5300 Series and Intel® Xeon® Processor 5400 Series Specification Update* for specification updates on processors. Items contained in the *Intel® Xeon® Processor 5100 Series and Intel® Xeon® Processor 5200 Series and Intel® Xeon® Processor 5300 Series and Intel® Xeon® Processor 5400 Series Specification Update and Intel® Xeon® Processor 5500 Series Specification Update and Intel® Xeon® Processor 5600 Series Specification Update* that either do not apply to the product or have been worked around are noted in this document. Otherwise, it should be assumed that any processor errata for a given stepping are applicable to the Printed Board Assembly (PBA) revisions(s) associated with that stepping.

This documentation communicates the following types of changes:

Specification Changes are modifications to the current published specifications for Intel® server boards. These changes will be incorporated in the next release of the specifications. Specification changes include typos, errors, or omissions from the current published specifications. These changes will be incorporated in the next release of the documents.

Specification Clarifications describe a specification in greater detail or further highlight a specification's impact to a complex design situation. These clarifications will be incorporated in the next release of the documents.

Errata are design defects or errors. Errata may cause the server board behavior to deviate from published specifications. Hardware and software designed to be used with any given processor stepping must assume that all errata documented for that processor stepping are present on all devices.

Product Scope

Below are the specific boards, BIOS and components covered by this update.

1. Product Code: MFS5000SI – Intel® Compute Module MFS5000SI

MM #	Server TA #	Server PBA #	BIOS	BMC	Change Description (PCN #)
892778	D91952-003	D70726-404	SB5000.86B.10.00.0030	13.8	Product Launch
	D91952-004	D70726-405	SB5000.86B.10.00.0043	1.30.3	PCN 108333-00
900409	D91952-007	D70726-502	SB5000.86B.10.10.0048	1.36.4	PCN 109593-00

2. Product Code: MFS5000SIB – Intel® Compute Module MFS5000SI – 3 Pack

MM #	Server TA #	Baseboard PBA #	BIOS	BMC	Change Description (PCN #)
892856	E19099-001	D70726-404	SB5000.86B.10.00.0030	13.8	Product Launch
	E19099-002	D70726-405	SB5000.86B.10.00.0043	1.30.3	PCN 108333-00
900410	E19099-007	D70726-502	SB5000.86B.10.10.0048	1.36.4	PCN 109539-00

3. Product Code: MFS5520VI – Intel® Compute Module MFS5520VI

MM #	Server TA #	Baseboard PBA #	BIOS	BMC	Change Description (PCN #)
901369	E42643-005	E41515-402	S5500.86B.01.10.0034	1.15.1	Product Launch
901369	E42643-007	E41515-404	S5500.86B.01.10.0038	1.16.2	PCN 109592-00

4. Product Code: MFS5520VIR – Intel® Compute Module MFS5520VIR

MM #	Server TA #	Baseboard PBA #	BIOS	BMC	Change Description (PCN #)
905716	E42643-005	E41515-405	S5500.86B.01.10.0043	1.18.2	PCN 109821-00
905716	E87653-002	E41515-406	S5500.86B.01.10.0048	1.19.2	PCN 109917-00

5. Product Code: MFS5520VIB – Intel® Compute Module MFS5520VI – 3 Pack

MM #	Server TA #	Baseboard PBA #	BIOS	BMC	Change Description (PCN #)
901669	E54314-002	E41515-402	S5500.86B.01.10.0034	1.15.1	Product Launch
901669	E42643-007	E41515-404	S5500.86B.01.10.0038	1.16.2	PCN 109592-00

6. Product Code: MFS5520VIBR – Intel® Compute Module MFS5520VI R-3 Pack

MM #	Server TA #	Baseboard PBA #	BIOS	BMC	Change Description (PCN #)
905717	E54314-002	E41515-405	S5500.86B.01.10.0043	1.18.2	PCN 109821-00
905717	E87663-002	E41515-406	S5500.86B.01.10.0048	1.19.2	PCN 109917-00

7. Product Code: MFSYS25 – Intel® Modular Server System MFSYS25

MM #	System TA #	Midplane PBA #	CMM PBA #	ESM PBA #	SCM PBA #	HDD Bay PBA#	Interposer PBA#	PS TA #	Change Description (PCN #)
892235	D91400-003	D70484-403	D70735-403	D70739-404	D70737-404	D70727-303	D70481-403	D73299-005	Product Launch

	D91400-004	D70484-403	D70735-403	D70739-404	D70737-404	D70727-303	D70481-403	D73299-005	PCN 108305-01
	D91400-005	D70484-404	D70735-404	D70739-404	D70737-404	D70727-303	D70481-404	D73299-005	
902318	D91400-009	D70484-408	D70735-406	D70739-405	D70737-409	D70727-303	D70481-406	D73299-007	PCN 109490-01
	D91400-010	D70484-409	D70735-407	D70739-405	D70737-410	D70727-303	D70481-407	D73299-008	PCN 109774-01

8. Product Code: MFSYS35 – Intel® Modular Server System MFSYS35

MM #	System TA #	Midplane PBA #	CMM PBA #	ESM PBA #	SCM PBA #	HDD Bay PBA#	Interposer PBA#	PS TA #	Change Description (PCN #)
892300	D91403-004	D70484-407	D70735-404	D70739-405	D70737-404	D91372-301	D91371-301	D73299-005	Product Launch
	D91403-006	D70484-408	D70735-404	D70739-405	D70737-404	D91372-303	D91371-301	D73299-005	PCN 109490-01
	D91403-007	D70484-409	D70735-407	D70739-405	D70737-410	D91372-304	D91371-301	D73299-005	PCN 109774-01

9. Product Code: MFSYS25V2 – Intel® Modular Server System MFSYS25V2

MM #	System TA #	Midplane2 PBA #	CMM2 PBA #	ESM PBA #	SCM PBA #	HDD Bay PBA#	Interposer PBA#	PS TA #	Change Description (PCN #)
910774	G18812-001	G18194-409	E91057-302	D70739-406	D70737-502	D70727-303	D70481-407	D73299-008	Product Launch

10. Product Code: AXXSCM3S – Intel® Storage Controller

MM #	Module TA #	Baseboard PBA #	FW	Change Description (PCN #)
891831	E15895-002	D70737-404	2.91.140.1	Product Launch
	E15895-003	D70737-405	2.91.140.5	PCN 108362-01
	E15895-006	D70737-410	3.4.0140.08	PCN 109774-01

11. Product Code: AXSW1GB – Intel® Gigabit Ethernet Switch AXSW1GB

MM #	Module TA #	Baseboard PBA #	FW	Change Description (PCN #)
891842	E16069-002	D91241-002	1.0.0.6 / 1.0.0.25	Product Launch
	E16069-002	D91241-002	1.0.0.6 / 1.0.0.27	FW Update

12. Product Code: MFCMM – Intel® Management Module

MM #	Module TA #	Baseboard PBA #	CMM GUI	Change Description (PCN #)
891834	E16293-002	D70735-403	1.0.100.10012007.7372	Product Launch
	E16293-003	D70735-404	1.3.100.20080527.11328	
	E16293-006	D70735-406	5.5.100.20091202.19584	PCN 109774-01

13. Product Code: MFCMM2 – Intel® Management Module 2

MM #	Module TA #	Baseboard PBA #	CMM GUI	Change Description (PCN #)
910036	E98065-005	E91057-302	10.1.100.20101015.23981	Product Launch

14. Product Code: AXPSU – 1000W Power Supply

MM #	Module TA #	Baseboard PBA #	Change Description (PCN #)
891843	E14835-02	D73299-005	Product Launch
902463	E14835-004	D73299-003	PCN 109736-00

15. Product Code: MFMIDPLANE – Intel® Modular Server System MFSYS25 –
Midplane Board

MM #	Baseboard TA #	Baseboard PBA #	Change Description (PCN #)
891832	E19078-001	D70484-403	Product Launch
	E19078-002	D70484-404	PCN 108362-01
899916	E19078-004	D70484-408	PCN 109490-01
	E19078-005	D70484-409	PCN 109774-01

16. Product Code: MFMIDPLANE – Intel® Modular Server System MFSYS35 –
Midplane Board

MM #	Baseboard TA #	Baseboard PBA #	Change Description (PCN #)
899916	E19078-003	D70484-407	Product Launch
	E19078-004	D70484-408	PCN 109490-01
	E19078-005	D70484-409	PCN 109774-01

17. Product Code: MFMIDPLANE2 – Intel® Modular Server System
MFSYS25V2 – Midplane Board

MM #	Baseboard TA #	Baseboard PBA #	Change Description (PCN #)
910888	G18809-001	G18194-409	Product Launch

18. Product Code: AXXGBIOMEZ – Intel® Compute Module MFS5000SI – Dual
Gigabit Ethernet Expansion Card

MM #	Board TA #	Board PBA #	Change Description (PCN #)
891844	E15888-002	D70465-302	Product Launch

	E15888-002	D70465-303	
--	------------	------------	--

19. **Product Code: AXXGBIOMEZV - Intel® Compute Module MFS5520VI -
Dual Gigabit Ethernet Expansion Card**

MM #	Board TA #	Board PBA #	Change Description (PCN #)
901362	E42655-005	E41517-301	Product Launch

Summary Tables of Changes

The following tables indicate the errata and the document changes that apply to the Specification Update. Intel intends to fix some of the errata in a future stepping of components, and to account for the other outstanding issues through documentation or specification changes as noted. The tables use the following notations:

Doc: Intel intends to update the appropriate documentation in a future revision.

Fix: Intel intends to fix this erratum in the future.

Fixed: This erratum has been previously fixed.

No Fix: There are no plans to fix this erratum.

Shaded: This erratum is either new or has been modified from the previous specification update.

Table 1. Errata Summary

No.	Plans	Description of Errata
1.	No Fix	Intel® Compute Module MFS5000SI NIC/Activity LEDs do not display a link status
2.	No Fix	Remote floppy is not supported
3.	Fixed	1024x768 Resolution with color depth set to thousands of colors not supported under Red Hat* Enterprise Linux 5.0 64-bit
4.	No Fix	NIC Utility <code>dcreate.exe</code> on MFS500SI -003 Resource CD incomplete
5.	Fixed	Event Log may report SMI Timeout Assertion after server power button is pressed
6.	No Fix	User is not able to configure different responses to pressing the Server Power button in Microsoft Windows 2008* Enterprise Server Edition.
7.	Fixed	Dual Intel® Storage Controller configuration not yet supported in the Intel® Modular Server System MFSYS25 (see details below for specific operating system support)
8.	Fixed	System Fault LED does not come on if smart devices (SCMs, ESMs, etc.) are completely non-functional
9.	Fix	Deleting an existing assigned virtual drive may result in GUI action failure
10.	Fixed	Certain Non-critical Events logged as Critical in GUI
11.	Fixed	System Fault LED does not turn on for all critical events
12.	Fix	Email Alerting not enabled by default for three Critical Events
13.	No Fix	Removing/Inserting USB devices during BIOS POST or in EFI may cause unexpected system behavior
14.	Fixed	Simultaneous Remote KVM installs of OS or applications will not successfully complete
15.	No Fix	Relative and Absolute KVM Mouse Mode not Supported on all Operating System's
16.	Fix	Compute modules with RAID 6 Virtual Drives Experiencing Slow / No Response
17.	Fixed	CONFIRM dialog box action not required to complete requested action
18.	Fixed	Pressing F1 during a KVM session will bring up the local KVM console help not the remote system application help.

19.	Fixed	Ethernet Switch Module will fail to automatically update in an operational chassis
20.	Fixed	Microsoft Windows Server 2003* cluster support not available
21.	No Fix	SuSE Enterprise Linux 10* U1 cluster node shown as running after being physically removed from chassis after failure
22.	Fixed	Fujitsu 146GB, 2.5" SAS hard drive takes longer than expected to come on line after a hot insertion
23.	Fix	BIOS R0048 Does Not Support Mixed Stepping E-0 and C-0 Processors
24.	Fixed	In Windows Enterprise Server 2008* Cluster failover testing, it has been observed that cluster nodes may lose access to the clustered shared LUN drives
25.	Fix	The CMM is not able to provide management information for the power supply when an AXXPSU at revision D73299-006 is installed in a system chassis.
26.	Fixed	The Network Time Server setting on the date/time web page of the Intel® Modular Server Control GUI does not allow selection of different time zones.
27.	No Fix	SuSE* Linux Enterprise Server 10 U1 will mark the OS LUN as read only if a SCM affinity change is made while the SUSE* Linux Enterprise Server 10 operating system is running or booted.
28.	Fixed	Chassis fault LED does not illuminate after removing a Main Fan module or the I/O fan module.
29.	Fixed	Local Video disappears with Console Redirection and Quiet Boot Enabled in the MFS5520VI compute module.
30.	Fixed	Speed Step disable in BIOS setup disables LSI SAS controller in the MFS5520VI compute module.
31.	Fix	Red Hat Enterprise Linux AS 5.0 U3, 32 bit Xen kernel only, shows 13GB of memory when more than 14GB of memory is installed.
32.	No Fix	MPIO takes a long time to install under Microsoft Windows* 2003 Cluster.
33.	No Fix	Virtual Drives from external ports are not recognized on reboot with Microsoft Windows* 2003 Enterprise.
34.	No Fix	Extraction and quick reinsertion of the Intel® Server Compute Module MFS5520VI may cause various issues.
35.	Fixed	DIMM temperature warning in VMWare ESX 3.5 and ESX 4.0.
36.	Fixed	MFS5000SI compute module occasionally hangs during LTO-4 tape backup operations
37.	Fix	Virtual Drives within a Storage Pool lose server assignments after a Virtual Drive has been deleted.

38.	Fixed	LUN Copier not activated with valid key.
39.	No Fix	RAID 10 to RAID 1E Automatic Migration
40.	Fixed	The installation of SLES 11 x86_64 fails on SSD.
41.	Fixed	GMM Web GUI SSL certification expired on Oct 27 2009
42.	No Fix	rKVM right Alt+F1 in VMWare 3.5,4.0 launches help instead of ESX server console.
43.	No Fix	ESM will increase the counter of "Received Pause Frames" when receiving erroneous or illegal packets
44.	No Fix	Excessive SEL logs may report after SuSE* Linux installed.
45.	Fix	MFS5520VI shows a incorrect CPU L1 and L2 cache size in BIOS
46.	No Fix	Fail to launch remote KVM under Redhat Desktop WS 5.5
47.	No Fix	CMM is not able to control date and time of Ethernet Switch Module
48.	No Fix	Reset Ethernet Switch Module from "Advanced Configuration" will not generate "reset" event log
49.	Fixed	The rKVM will be black screen when SUSE11 boot to login screen with S5000SI board
50.	No Fix	The size of installed DIMM is wrong when Mirroring mode on with MFS5000SI
51.	No Fix	The rKVM console may report "Invalid session ticket" or "Authentication Failed"
52.	No Fix	Select rKVM Help function by using the hot key fail
53.	No Fix	Mixed processors population will disable CPU2
54.	Fix	When Virtual Drive migration or expansion is running, and HDD physically removed, no failure reported
55.	Fixed	Lower network performance may be observed when Hyper-V role is added in Windows* Server 2008 R2 with more than 32GB memory
56.	No Fix	Illegal FC packets counted as good FC packets in Ethernet Switch Module interface statistics.
57.	No Fix	Ethernet Switch Jumbo Frame changes not consistently saved.

58.	Fix	Rebuild stuck at 99% when Storage Pool contains VD with RAID 0
59.	No Fix	rKVM Mouse not syncing properly w/ SLES 11 Enterprise 64 bit SP1
60.	No Fix	MFS5520VI may display incorrect POST code for memory error
61.	Fix	HDD cache enable does not enable HDD cache with UFU 10.3 and 10.4.

Table 2. Documentation Changes

No.	Plans	Description of Documentation Change
1.	Fixed	System Fault LED not depicted in front system views in Intel® Modular Server System MFSYS25 documentation
2.	Fixed	Power Budget Information Incorrect in Intel® Modular Server System MFSYS25 TPS
3.	No Fix	In the V2.6 Release Notes, Section G, Red Hat* Enterprise Linux 5 Server U1 (32bit and 64bit) is incorrectly listed as supporting shared LUN
4.	Fixed	Intel® Modular Server System MFSYS25/MFSYS35 Quick Start User's Guide has an incorrect Package Contents list

Following are in-depth descriptions of each erratum / documentation change indicated in the tables above. The errata and documentation change numbers below correspond to the numbers in the tables.

Errata

1. Intel® Compute Module MFS5000SI NIC/Activity LEDs do not display a link status

Problem Compute Module NIC/Activity LEDs display is OFF instead of ON when link is established.

Implication Link status of the ports can be verified in the GUI on the Switch Status Tab. The Compute Module NIC/Activity LEDs will blink to show outbound NIC activity; however, the user should refer to the Switch Activity LEDs to verify communication status with the switch.

Status No Fix

2. MFS5000SI remote floppy is not supported

Problem MFS5000SI remote floppy is not supported.

Implication Customers will not be able to remotely mount a floppy drive during Remote KVM/Media redirection.

Status No Fix

3. 1024x768 Resolution with color depth set to thousands of colors not supported under Red Hat* Enterprise Linux 5.0 64-bit

Problem Video resolution test fails under Red Hat* Enterprise Linux 5.0 64-bit.

Implication Resolution of 1024x768 with color depth set to thousands of colors fails to enable.

Status Fixed in UFU V5.5

4. NIC Utility `dcreate.exe` on MFS500SI -003 Resource CD incomplete

Problem MFS500SI Resource CD ROM E12216-003 NIC driver package contains a `dcreate.exe` file that errors out.

Implication `dcreate.exe` is not functional on the MFS500SI Resource CD. If `dcreate` functionality is required, users can download the complete software stack from support.intel.com by going to <http://downloadcenter.intel.com/>, typing in “Intel® 82571EB” and selecting the file `PRO2KXP.exe`.

Workaround None

Status No Fix – utility removed from CD

5. Event Log may report SMI Timeout Assertion after Server Power button is pressed

Problem SMI Timeout Assertion is logged as a critical event in the Event Log after the Server Power button is pressed; however, the server powers up normally.

Implication No system impact – Timeout logic was incorrect, resulting in a false event logging.

Workaround None

Status Fixed, P2.6

6. User is not able to configure different responses to pressing the Server Power button in Microsoft Windows 2008* Enterprise Server Edition

Problem User is not able to configure different responses to pressing the Server Power button in the OS.

Implication By design the user should be able to configure the response of the Server Power button in the OS to do nothing, prompt for action, standby or hibernate. Changing these settings in the OS has no impact – the power button continues to power down the server.

Workaround Win2K8 allows the redefinition of the power button press to mean “Go into hibernate state” rather than “Power down.” If this configuration is enabled AND the power button is pressed the BMC will get out of sync with the physical power state since the BMC has no visibility into the changed OS configuration. In the context of a server in a chassis, redefining the power button to mean “hibernate” is not useful. In this environment, the OS should not be configured to hibernate on a power button rather than power off. If the OS is so configured and the power button is pressed, the power button should be pressed a second time to bring the power back up. The OS should be configured to power off in response to a power button.

A server in this condition can also be recovered by doing a “forced power off” followed by a normal “power on”.

Status No Fix

7. Dual Intel® Storage Controller configuration not yet supported in the Intel® Modular Server System MFSYS25 and MFSYS35

Problem Dual SCM configuration support not yet included in the MFSYS25 software stack for:

- A. Microsoft Windows* 2003 Enterprise, Microsoft Windows* 2008 Enterprise
- B. Red Hat 5.0 and SUSE Linux Enterprise 10

Implication Dual SCM configuration is not supported. Single SCM is only supported in slot 1.

Status Fixed, all operating systems and with appropriate UFU. P2.3.1 for Microsoft Windows* 2003 R2 SP2 and Microsoft Windows* 2008, P2.6 for SUSE Linux Enterprise* 10 U1, V5.5 for Red Hat* 5.0 U4.

8. System Fault LED does not come on if smart devices (SCMs, ESMs, etc.) are completely non-functional

Problem	System Fault LED does not come on if smart devices (SCMs, ESMs, etc.) are completely non-functional.
Implication	Currently, the System Fault LED will only turn on if the device is capable of telling the CMM it has a fault condition. If a device's software is completely inoperable, the System Fault LED may not turn on.
Workaround	None. In the future the GUI will illuminate the System Fault LED if the CMM cannot communicate with the device after ~60 seconds of timeout.
Status	Fixed

9. Deleting existing assigned virtual drive may result in GUI action failure

Problem	While deleting an existing assigned virtual drive, GUI action fails with 'Storage subsystem is busy. Please try again in a few minutes.'
Implication	Intermittently - as a user tries to delete a virtual drive, they may receive a message indicating that the SCM is busy. The action will not complete properly until all the servers are shut down and the SCM is physically removed and replaced.
Workaround	None
Status	Fixed

10. Certain Non-critical Events logged as Critical in GUI

Problem	GUI logs certain correctable errors as critical in the Event Log
Implication	GUI may incorrectly log correctable errors, such as SBE or mismatched processors installed, as "critical" errors. GUI categorization of the events will be corrected in a future release. Note that correctable errors do not cause the System Fault LED to turn on by design; only critical errors light the LED. The System Fault LED will only light for truly critical or higher severity issues such as MBEs.

Workaround None

Status Fixed

11. System Fault LED does not turn on for all critical events

Problem System Fault LED will not turn on as expected when certain critical events occur.

Implication When the Processor Cache Size Mismatch error occurs, the system will boot into BIOS setup; however, the System Fault LED will not turn on. Additionally when the Correctable Memory Error Threshold is reached, the event will be logged – however, the System Fault LED will not turn on.

Workaround None

Status Fixed

12. Email Alerting not enabled by default for three Critical Events

Problem On all critical event error logging, SNMP, and Email Alerting should be enabled by default. However, three Critical Events do not by default have Email Alerting enabled as expected.

Implication Both SNMP and Email Alerting were not enabled by default in the event policy for the following three events: Storage Subsystem – RAID Level Migration is aborted due to an internal error, CMM m – System Component Unfit, and CMM – CMM Internal Firmware Error.

Workaround Administrator can go in and enable SNMP and Email Alerting for these three events.

Status Fixed

13. Removing/Inserting USB devices during BIOS POST or in EFI may cause unexpected system behavior

Problem	Removing/Inserting USB devices during BIOS POST or in EFI may cause unexpected system behavior such as a server reboot, lock up or unexpected characters being displayed.
Implication	Customer will not be able to remove USB devices during BIOS POST or while in EFI.
Workaround	Server module must be powered off and back on to recover. Do not remove/insert USB devices during server POST or while in EFI.
Status	No Fix

14. Simultaneous Remote KVM installs of OS or applications will not successfully complete on MFS5000SI

Problem	Attempting to load two Operating Systems or software installations via Remote KVM sessions at the same time on two separate servers using two laptops will not successfully complete on MFSYS5000SI
Implication	Customers will not be able to conduct simultaneous Remote KVM OS or application installations on MFSYS5000SI
Workaround	None
Status	Fixed

15. Relative and Absolute KVM Mouse Mode not Supported on all Operating System's

Problem	Two mouse modes are available, Relative (the default) and Absolute – both are not supported for all Operating Systems.
Implication	Absolute mouse mode is used with Microsoft® Windows and other operating systems that compute mouse movements from absolute X, Y coordinates. Relative mouse mode is used primarily with some Linux and Unix X/Windows displays and other operating systems that compute mouse movements from the change in relative position to the last position (how much the mouse moved).
Workaround	<p>When using Linux or other operating systems that compute mouse movements from change in relative position you must change the mouse mode setting in the KVM Viewer. Choose Mouse Mode from the KVM Viewer application Options menu. Select Relative Mode. If the remote and local cursors are not synchronized, toggle the Sync Cursor setting from On to Off and back to On.</p> <p>Note: Mouse mode should be selected before starting CD Redirection. The menu option will be disabled when CD redirection is enabled</p>
Status	No Fix

16. Compute Modules with RAID 6 Virtual Drives Experiencing Slow Response

Problem	Compute Modules with a Raid 6 Virtual Drive from a Storage Pool with 9 or more physical hard drives may experience slow response when transferring very large files.
Implication	<p>When the compute module storage configuration has a Raid 6 Virtual Drive from a Storage Pool with 9 or more physical hard drives, the user may experience an apparent system freeze when transferring very large files. When monitoring CPU utilization using Task Manager while copying files, utilization may drop to zero and the system will stop copying and responding to input.</p> <p>The issue also does not occur in RAID 6 configurations from a Storage Pool with less than nine hard disk drives or with Virtual Drives in RAID 5 or RAID 10 configurations.</p>

Workaround	Current workaround is to use a Virtual Drive configured as RAID 6 with less than nine hard disk drives or a version of RAID other than 6.
Status	Fix

17. CONFIRM dialog box action not required to complete requested action

Problem	Any dialog box which prompts the user to type “confirm” before clicking OK in order to perform an action will actually complete the specific action if the user clicks OK without typing “confirm”. The action will complete if the user leaves the box blank or types any combination of letters including “confirm” before clicking OK.
Implication	A user may inadvertently perform an undesired action by clicking OK without typing “confirm”, typing any combination of letters or leaving the box blank.
Workaround	Prior to clicking OK ensure that the action about to be perform is actually desired.
Status	Fixed, P2.3.1

18. Pressing F1 during a KVM session will bring up the local KVM console help not the remote system application help

Problem	Pressing F1 during a KVM session will bring up the local KVM console help not the remote system application help.
Implication	Remote system application help is not viewable by the user.
Workaround	There is currently not a workaround to this issue.
Status	Fixed, P2.3.1

19. Ethernet Switch Module will fail to automatically update in an operational chassis

Problem If an Ethernet Switch Module, not at FW level 1.0.0.27, is inserted into slot 1 or slot 2 in a chassis that is in steady state (no FW updates in progress or pending, and the chassis is just operating normally), the CMM's attempt to update the FW on the switch will not succeed. The FW update page will show that a FW update is 'pending'. Resetting or re-inserting the switch will not correct the situation. The CMM must be reset. The FW update will be applied to the switch when the CMM restarts. This applies to ESM1 and ESM2.

Note: This erratum applies only to ESM hot-insert. Installing P2.6 on a chassis that already has an ESM that is not at FW revision level 1.0.0.27 will allow the ESM to update without requiring a CMM restart.

Implication FW update will not complete.

Workaround Reset the CMM.

Status Fixed, V3.0

20. Microsoft Windows Server 2003* cluster support not available

Problem Cluster support is not available for Microsoft Windows Server 2003* R2 SP2.

Implication Cluster support is not available to customers using Microsoft Windows Server 2003* R2 SP2.

Workaround There is currently not a workaround to this issue.

Status Fixed, V3.0, Reference Microsoft Windows Server 2003* (x86 and x64) Cluster-Driver Installation BKM (E67062-002) for details.

21. Suse Enterprise Linux 10* U1 cluster node shown as running after being physically removed from chassis after failure

Problem	When a node (compute module) is physically removed from the MFSYS25 chassis, the node is stopped but the resource is still shown as running. Manually stopping and restarting the resource will not correct this situation since the resource is still shown as running. When the node is reinserted its resource indicates as up and running again.
Implication	Incorrect resource status is displayed when a node is physically removed.
Workaround	User needs to develop and integrate a STONITH driver using the Intel® Compute Module Power Control for Clusters WhitePaper .
Status	No Fix

22. Fujitsu 146GB, 2.5" SAS hard drive takes longer than expected to come on line after a hot insertion

Problem	When a Fujitsu 146GB, 2.5" SAS drive is hot inserted into the hard drive bay, it takes longer than expected for the drive to come on line causing command timeouts. Resetting the Storage Control Module is required to have the drives come ready.
Implication	Hard disk drives are marked as not ready.
Workaround	Timeout values were extended in firmware to allow more time for the drives to become ready.
Status	Fixed, P2.6

23. BIOS R0048 Does Not Support Mixed Stepping E-0 and C-0 Processors

Problem	BIOS code specifically designed to allow support for mixed stepping processors was not included in BIOS R0048.
Implication	The use of mixed stepping E-0 and C-0 processors and BIOS R0048 may cause erratic system behavior such as operating systems failing to load or install.
Status	This erratum may be fixed in a future BIOS release.
Workaround	None.

24. In Windows Enterprise Server 2008* Cluster failover testing, it has been observed that cluster nodes may lose access to the clustered shared LUN drives

Problem	In Windows Enterprise Server 2008* Cluster failover testing, it has been observed that cluster nodes may lose access to the clustered shared LUN drives if a node is power cycled. If a node which has lost shared LUN access is the cluster resource owner for the cluster storage resources or becomes the owner, the cluster storage resources will go into an offline state.
Implication	Cluster storage resources going offline would lead to failures in any applications which are dependent on the cluster storage. Resetting SCM1 or power cycling the chassis will restore service.
Status	Fixed in UFU V2.7
Workaround	Resetting SCM1 or power cycling the chassis will restore service.

25. The CMM is not able to provide management information for the power supply when an AXXPSU at revision D73299-006 is installed in a system chassis

Problem	The CMM is not able to provide management information, firmware revision number or manufacturing information for the power supply when an AXXPSU at revision D73299-006 is installed in a system chassis.
Implication	In installations with firmware revision P2.3.5 the CMM will prompt “Install Power Supplies” in the Action Required window; in installations with firmware revision P2.6 that alert will not occur. In both cases, the PSU / system chassis will power up. This erratum does not prevent powering up of the Server Compute Module.
Status	Fixed in UFU P2.6.

26. The Network Time Server setting on the date/time web page of the Intel® Modular Server Control GUI does not allow selection of time zones

Problem	The Network Time Server setting on the date/time web page of the Intel® Modular Server Control GUI does not allow selection of different time zones. Time Zone is set at GMT.
Implication	Network Time Server is always set to GMT.
Status	Fixed in V2.7
Workaround	None.

27. SuSE* Linux Enterprise Server 10 U1 will mark the OS LUN as read only if a SCM affinity change is made while the SUSE* Linux Enterprise Server 10 operating system is running or booted

Problem	SuSE* Linux Enterprise Server 10 U1 will mark the OS LUN as read only if a SCM affinity change is made while the SuSE* Linux Enterprise Server 10 operating system is running or booted.
Implication	The OS LUN is marked as “read only”.
Status	No Fix.
Workaround	Power down the SuSE* Linux Enterprise Server 10 U1 operating system. While the operating system is powered down, go to the CMM UI and change the LUN affinity.

28. Chassis fault LED does not illuminate after removing a Main Fan module or the I/O Fan module

Problem	When one or both of the Main Fan modules or the I/O Fan module is removed from the system, the chassis fault LED does not illuminate.
Implication	There is no visual indication on the system that one or both of the Main Fan modules or the I/O Fan module have been removed
Status	Fixed in UFU V5.5.

29. Local video disappears with Console Redirection and Quiet Boot Enabled in the MFS5520VI compute module

Problem	Local video disappears with Console Redirection and Quiet Boot enabled in the MFS5520VI compute module.
Implication	Local video will disappear if Console Redirection and Quiet Boot are enabled.
Status	Fixed in UFU V3.6.
Workaround	Do not enable Console Redirection and Quiet Boot.

30. Speed Step Disable in BIOS setup disables the LSI SAS controller in the MFS5520VI compute module

Problem	Speed Step Disable in BIOS setup disables the LSI SAS controller.
Implication	When Speed Step is disabled in BIOS setup, the LSI SAS controller option ROM is disabled and storage is no longer seen.
Status	Fixed in UFU V3.6.
Workaround	Do not disable Speed Step.

31. Red Hat Enterprise Linux AS 5.0 U3, 32 bit Xen kernel, only shows 13GB of memory when more than 14GB of memory is installed

Problem	Red Hat Enterprise Linux AS 5.0 U3, 32 bit Xen kernel only, shows 13GB of memory when more than 14GB of memory is installed.
Implication	Memory is under reported.
Status	This erratum is a RHEL 5.0 U3 issue and has been reported to Red Hat for problem resolution.
Workaround	None.

32. MPIO takes a long time to install under Microsoft Windows* 2003 Cluster

Problem	MPIO takes a long time to install under Microsoft Windows* 2003 Cluster.
Implication	Delay can take as long as 2 – 5 minutes per virtual drive.
Status	No Fix.
Workaround	Install MPIO driver prior to setup of cluster. Do install/uninstall with one server module at a time; shut down cluster and update one server module at a time.

33. Virtual Drives from external ports are not recognized on reboot with Microsoft Windows* 2003 Enterprise.

Problem	Virtual drives from external ports are not recognized on reboot with Microsoft Windows* 2003 Enterprise.
Implication	On reboot, all LUNs set to LUN 0 will not be recognized and available..
Status	No Fix.
Workaround	Do not assign LUN 0 to LUNs on an external array. All LUNS on an external disk array should be set to a LUN other than LUN 0.

34. Extraction and quick reinsertion of the Intel® Server Compute Module MFS5520VI may cause various issues

Problem	Extraction and quick reinsertion of the MFS5520VI compute module may cause various different issues.
Implication	If the compute module is reinserted too quickly, various issues may occur.
Status	No Fix.
Workaround	After extracting a MFS5520VI compute module, wait 15 seconds before reinserting.

35. DIMM temperature warning in VMWare ESX 3.5 and ESX 4.0

Problem	VMWare ESX 3.5 and ESX 4.0 pick up a sensor as DIMM9 temperature and report a DIMM temperature warning.
Implication	VMWare ESX 3.5 and ESX 4.0 generates a false DIMM temperature warning for DIMM9.
Status	Fixed in UFU V4.0.

36. MFS5000SI compute module occasionally hangs during LTO-4 tape backup operations

Problem	MFS5000SI compute module occasionally hangs during LTO-4 tape backup operations. The backup operation byte count will stop incrementing and access to the server compute module will also slow down. Attempts to cancel the tape backup job in progress or to restart Backup Exec services appear to hang as well.
Implication	MFS5000SI compute modules occasionally hang during LTO-4 tape backup operations.
Status	Fixed in UFU5.5.

37. Virtual Drives within a Storage Pool may lose server assignments after a Virtual Drive has been deleted

Problem	When a Virtual Drive within a Storage Pool is deleted, assignments for subsequent Virtual Drives within the same Storage Pool may be lost during a firmware update or after a power cycle of the SCM.
Implication	In the event that Virtual Drive assignments are lost, effected Virtual Drives must be reassigned.
Status	Fix in future FW release.

Workaround Do not powercycle SCM or update FW immediatly following a Virtual Drive deletion. Maintain a current record of the storage layout and server assignments.

38. LUN Copier not activated with valid key

Problem On systems upgrading from UFU 3.0 to UFU 4.0 directly, when the LUN Copier feature is added via the feature activation screen, the key for LUN Copier is accepted but the feature is not activated.

Status Fixed in UFU V4.1

Workaround Reset CMM settings to system default or update system firmware to UFU V4.1.

39. RAID 10 to RAID 1E Automatic Migration

Problem RAID 10 Virtual Drives automatically migrated to RAID 1E Virtual Drives when the Storage Pool they belonged to was expanded by adding additional disks, either an even or odd number.

Implication Working as designed . No impact to redundancy or performance.

Status No fix.

40. The installation of SLES 11 x86_64 fails on SSD

Problem On MFSYS25 system with SSD installed, the installation of SLES 11 x86_64 fails at the point where the GRUB bootloader is being configured

Status Fixed in SLES 11 SP1.

Workaround Set SCM affinity to SCM2, installation will complete without a GRUB error.

41. GMM Web GUI SSL certification expired on Oct 27 2009

Problem GMM Web GUI SSL certification expired on Oct 27 2009.

Status Fixed in FW V5.5.

42. rKVM right Alt+F1 in VMWare 3.5, 4.0 launches help instead of ESX server console

Problem rKVM right Alt+F1 in VMWare 3.5,4.0 launches help instead of ESX server console.

Status No Fix

Workaround Use left Alt key+F1 since VMware does not support this function via right Alt key +F1.

43. ESM will increase the counter of "Received Pause Frames" when receiving erroneous or illegal packets

Problem Packets received with undersize, oversize, or/and with CRC are treated as good Flow Control packets and should not be counted as such, even if all above conditions are fulfilled. These packets should be counted according to the specific error (undersize, oversize, jabber fragment, or CRC). However, these illegal packets are counted as good Flow Control packets.

Implication Hardware Bug. No impact for functionality.

Workaround None

Status No Fix

44. Excessive SEL logs may report after SuSE* Linux installed

Problem	During system reboot excessive logs "PCIe Fatal Completer Abort Errors" maybe get reported in compute node's SEL log.
Implication	During a system reboot, the user may see excessive logs being reported in SEL log.
Workaround	These errors occur during the ISA PNP scan. A workaround is to edit /boot/grub/menu.lst and add "noisapnp" to the "kernel" parameter list after installation.
Status	No Fix

45. CPU L1 and L2 cache size incorrect in MFS5520VI BIOS

Problem	MFS5520VI shows a incorrect CPU L1 and L2 cache size in BIOS.
Implication	No impact for functionality.
Status	Fix in future BIOS release.

46. Fail to launch remote KVM under Redhat Desktop WS 5.5

Problem	Login to CMM GUI from Redhat Desktop WS 5U5, using Firefox 3.6.3, JRE6U20, Flashplayer 10.0.45.2. When launching rKVM Applet, a warning message pops out, "Failed to validate certificate. The application will not be executed."
Status	No Fix
Workaround	Change Java security by uncheck the "Check certificates for revocation using certificate revocation list(CRLs) and enable online certification validation" options.

47. CMM is not able to control date and time of Ethernet Switch Module

Problem	All Ethernet Switch related event logs show a January 2000 date. There is no way for the user to set the date, time or time zone in the ESM GUI interface. All
---------	--

the dates have been set during manufacturing. The CMM GUI is not able to control the date and time of Ethernet Switch Module.

Implication This is a firmware Bug. No impact for functionality.

Status No Fix

48. Reset Ethernet Switch Module from "Advanced Configuration" will not generate "reset" event log

Problem Reset works under Ethernet Switch's "Advanced Configuration" session, but no event in GUI about a reset though.

Implication This is a firmware Bug. No impact for functionality. "Reset" will able to generate reset event log when do it outside of "Advanced Configuration" session.

Status No Fix

49. The rKVM will be black screen when SUSE11 boot to login screen with S5000SI board

Problem The rKVM will be black screen when SUSE11 boot to login screen with S5000SI board.

Implication No impact on connecting the monitor directly to S5000SI board VGA port.

Workaround The SLES-11 S5000SI redirection works fine with Vesa and fbdev drivers without any issue but user needs to force use to vesa drivers during SLES-11 installation time. Steps are:

1. Boot SLES-11 DVD or iso image
2. Force to use vesa driver giving following command initial grub screen:
"video=vesa".

You can also try with specify resolution color bits and refresh rates with
"video=vesa:1280x960-16@70"

3. Continue SLES-11 installation

50. The size of installed DIMM is wrong when mirroring mode on with MFS5000SI.

Problem	The mirrored DIMM units are shown as 0MB on CMM web GUI.
Implication	The DIMM size information of MFS5000SI on CMM web GUI is incorrect when DIMM mirroring mode is on.
Status	No Fix.

51. The rKVM console may report "Invalid session ticket" or "Authentication Failed".

Problem	The rKVM console may report "Invalid session ticket" or "Authentication Failed".
Implication	It may happen when network connection lost and do network re-connect. No impact on connecting the monitor directly to computer node's VGA port.
Status	Fix in future FW release.

52. Select rKVM help function by using hot key fail

Problem	When using Remote KVM under Linux based OS, the Hot key "ALT + F1" can't open RConsole Client Help.
Implication	It shows the main menu of Linux instead of Remote console client help window pop up
Status	No Fix. This is common Linux behavior, "ALT+F1" is Linux system Hot key, will not be sent to browser.
Workaround	Access RConsole Client Help through drop down menu.

53. Mixed processors population will disable CPU2

Problem	When mixed processors are populated on MFS5000SI, CPU2 will be disabled.
Implication	No customer implication, Works as design.
Status	No Fix

54. When Virtual Drive migration or expansion is running, and HDD physically removed, no failure reported.

Problem	When Virtual Drive migration or expansion is running, and HDD physically removed, no failure reported.
Status	Fix in future firmware release

55. Lower network performance may be observed when Hyper-V role is added in Windows* Server 2008 R2 with more than 32GB memory

Problem	On a dual Intel® Xeon® 5600 series processor configuration with more than 32GB memory installed, user may notice network performance drop in Windows* Server 2008 R2 when Hyper-V role is added.
Implication	User may see lower than expected network performance under windows* Sever 2008 R2.
Status	Fixed in UFU v6.7.
Workaround	Reduce memory size to less than 32GB.

56. Illegal FC packets counted as good FC packets in Ethernet Switch Module interface statistics

Problem A packet is identified as a good formatted 802.3x Flow Control packet if all of the following conditions are met:

- MAC DA is 01-80-C2-00-00-01.
- Length/EtherType field is 88-08.
- OpCode field is 00-01.

Packets received with undersize, oversize, or/and with CRC, should not be treated as good Flow Control packets and should not be counted as such, even if all above conditions are fulfilled. These packets should be counted according to the specific error (undersize, oversize, jabber fragment, or CRC). However, these illegal packets are counted as good Flow Control packets.

Implication The wrong counter is incremented by the illegal Flow Control packet.

Status No Fix.

57. Ethernet Switch Module Jumbo Frame changes not consistently being saved

Problem In Ethernet Switch Advanced Configuration, set the Jumbo Frame to enable, save the changes, reset the switch. Upon reboot Jumbo Frame may still be Disabled.

Implication Customer may need to configure and reset the switch multiple times. After making the change the customer will need to recheck the setting after a switch reset to insure it has been set correctly.

Workaround Save settings on the jumbo frame page, save again on the switch reset page, wait 15 seconds and go back to the jumbo frame page, make sure the jumbo frame setting has been saved, then reset the switch on the reset page of advanced configuration. Upon switch reboot, recheck the jumbo frame setting to insure it is correct. If not retry the same procedure.

Status No Fix.

58. Rebuild stuck at 99% when Storage Pool contains VD with RAID 0

Problem	Whenever a storage pool has multiple VD RAID levels, and at least one VD has RAID 0, a rebuild operation will get stuck at 95 to 99%, and other storage management operations with the affected SP may fail. It is recommended that VDs with RAID 0 should be placed in a separate storage pool from those with other RAID levels.
Workaround	Power down all compute modules. If present, remove SCM2 and wait at least one minute for the system to stabilize. Extract SCM1, wait 30 seconds, reinsert SCM1. Watch the user interface storage page for SPs and VDs to reappear, then delete each RAID 0 VD in the affected SP. It is important this deletion take place within five minutes from inserting the SCM, otherwise the deletion operation will fail and these steps need to be repeated. The rebuild will then proceed and complete within a few minutes.
Status	Fix in future UFU release.

59. rKVM Mouse not syncing properly with SLES 11 Enterprise 64 bit SP1

Problem	rKVM Mouse not syncing properly w/ SLES 11 Enterprise 64 bit SP1.
Workaround	Reduce mouse acceleration and threshold in SLES 11 OS. From Computer-> Control Center -> Mouse-> General tab , set Acceleration to lowest and Threshold to lowest.
Status	No Fix

60. MFS5520VI may display incorrect POST code for memory error

Problem	MFS5520VI may display an incorrect POST code of 0xF2 (start of Memory Reference Code) when a memory error is detected.
Implication	Specific memory error can't be determined from the POST code LEDs.
Workaround	When POST code 0xF2 is encountered, first check that the installed memory configuration is valid. If the specific memory error POST code is needed:

- Extract blade.
- Install BMC force update jumper.
- Press front panel power button to power up blade.
- Record the POST code.
- Press front panel power button to power down blade.
- Extract blade.
- Remove BMC force update jumper.

Status No Fix

61. HDD cache enable does not enable HDD cache with UFU 10.3 and 10.4

Problem HDD cache enable does not enable HDD cache with UFU 10.3 and 10.4.

Implication Customer can not enable HDD cache with UFU 10.3 and 10.4.

Status Fix in next MFSYS25V2 UFU release.

Documentation Changes

1. System Fault LED not depicted in front system views in Intel®

Modular Server System MFSYS25 documentation

Problem System Fault LED is not identified in the front system view of the Intel® Modular Server System MFSYS25 in the following documents: -008 MFSYS25 User Guide, -003 MFSYS25 Quick Start User's Guide, and -003 MFSYS25 TPS.

Clarification The System Fault LED is located on the front of the chassis, in-between the I/O Cooling Module and the server in the bottom slot of the chassis.

Status Fixed

2. Power Budget Information Incorrect in Intel® Modular Server

System MFSYS25 TPS

Problem The Power budget information for the MFSYS25 system is incorrect in the Intel® Modular Server System MFSYS25 TPS. **Clarification**

The correct values are as follows:

Subsystem	12V Budget
Compute Module	401 W
Mezzanine Card	5 W
CMM	6 W
I/O Switch	40 W
Storage Module	48 W
Hard Drive Bay	165 W
Midplane & Cooling Modules	164 W
Power Supply blank	26 W
System Total	
Power subsystem spec	3000 W

Status Fixed In the P2.6

3. Release Notes, Section G, Red Hat* Enterprise Linux 5 Server U1 (32bit and 64bit) is incorrectly listed as supporting shared LUN

Problem	In the V2.6 Release Notes, Section G, Red Hat* Enterprise Linux 5 Server U1 (32bit and 64bit) is incorrectly listed as supporting shared LUN.
Clarification	Shared LUN is not currently supported on Red Hat* Enterprise Linux 5 Server U1 (32bit or 64bit). The Tested Hardware and Operating System List has this operating system listed correctly.
Status	No Fix

4. Intel® Modular Server System MFSYS25/MFSYS35 Quick Start User's Guide has an incorrect Package Contents list

Problem	On the front side of the Intel® Modular Server System MFSYS25/MFSYS35 Quick Start User's Guide, Document #E11186-00X, the Package Contents list incorrectly shows a rail kit included in the system shipping container.
Clarification	A rail kit is not included in the base system configuration or the shipping container of either the MFSYS25 or MFSYS35 systems. The rail kit is an accessory, product code AXXMFRAIL that can be purchased separately.
Status	Fixed in document #E11186-008.

5. Intel® Compute Module MFS5520VI Technical Product Specification has an incorrect statement about Turbo Mode setting

Problem	Intel® Compute Module MFS5520VI Technical Product Specification, Document #E64311-00X, in section 13.3, incorrectly shows that Turbo Mode is disabled by default.
---------	---

Clarification Turbo Mode is enabled by default on Intel® Compute Module MFS5520VI.

Status Fixed in document #E64311-006