

This Technical Advisory describes an issue which may or may not affect the customer's product

# **Intel Technical Advisory**

TA-1019-2

5200 NE Elam Young Parkway Hillsboro, OR 97124

October 15, 2012

# INTEL® SERVER SYSTEM R2000IP BASEBOARD MANAGEMENT CONTROLLER (BMC) LOGS AN INCORRECT "INFORMATION EVENT: CONFIGURATION ERROR" RECORD ON THE FXX750GERPS REVISION A02 POWER SUPPLY

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

### **Products Affected**

The following Intel® Server System and Power supply spare:

- Intel® Server System R2000IP System R2208IP4LHPC R2308IP4LHPC R2216IP4LHPC
- Intel® Server System Power Supply spare FXX750GERPS

## Description

Copyright © 2012 Intel Corporation.

\* Other names and brands may be claimed as the property of others.

When AC power is removed from one of the two R2000IP system power supply modules, the BMC incorrectly logs an "Informational event: configuration error" record on that power supply module. Soon after the AC power is removed, the BMC also logs an "Information event: AC has been regained", even though AC power has not yet been restored. This erroneous AC regained event forces the BMC to incorrectly report that the Power Unit Redundancy (Pwr Unit Redund) is fully redundant.

#### **Root Cause**

This error in BMC reporting is due to the power supply firmware (FW) reporting the event with incorrect information to the BMC.

#### **Corrective Action / Resolution**

Intel has completed validation and implemented updated power supply firmware for the FXX750GERP PSU modules.

The power supplies with new FW remain P/N G35978-003 version but have been marked with blue mark (see picture).



Original Power supply



Power supply with new FW

If customers have received a R2000IP system with FS750HS1-00 REV A02 power supply modules without the blue mark, at their discretion, they may either use them "as is" or exchange them for identical modules with updated PSU FW. Please reference this technical advisory by number and follow Intel's standard RMA process when returning an affected power supply module for exchange.

# Workarounds

N/A

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division Intel Corporation