



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-0996-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

April 1, 2012

INTEL® RAID C600 UPGRADE KEY REPLACEMENT ISSUE

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The Intel products described herein may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

The following Intel® Server Boards based on Intel® C600 chipset:

- Intel® Server Board S2600CP
- Intel® Server Board S2600CO
- Intel® Server Board S2600JF
- Intel® Server Board S2600WP
- Intel® Server Board S2600GZ/GL
-

The following Intel® Server Systems based on Intel® C600 chipset:

- Intel® Server System P4000CP
- Intel® Server System P4000IPL
- Intel® Server System P4000CRL
- Intel® Server System R2000GZ/GL
- Intel® Server System R1000GZ/GL
-

Description

The above mentioned Intel® Server Boards and Systems may detect the incorrect Storage Control Unit (SCU) Redundant Array of Inexpensive/Independent Disks (RAID) information after installing or replacing the RAID upgrade key. The board or system may still show the previous RAID information even if you replace the key with a new one.

Root Cause

An issue exists with the Manageability Engine (ME) Firmware 02.01.05.069, where the system may not detect the new RAID activation key during the first time AC power on.

Corrective Action / Resolution

This issue will be fixed in the next revision of the ME Firmware (02.01.05.091) and will be cut into Intel factory product in the April 2012 timeframe. The new System Update Package (SUP) with new ME version will be posted on the www.intel.com/support website around the middle of April 2012.

Workarounds

A possible workaround for this issue is to do a second AC power cycle to the system after the RAID upgrade key has been installed or replaced to ensure the correct type of key is identified.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation