

This Technical Advisory describes an issue which may or may not affect the customer's product

# **Intel Technical Advisory**

TA-1043-02

5200 NE Elam Young Parkway Hillsboro, OR 97124

December 02, 2013

# The Intel<sup>®</sup> Server Board S2600CP and Intel<sup>®</sup> Server System P4000CP may have been programmed with an incorrect BIOS

### **Products Affected**

| Product Name                             | Product Code | MM#    | Board PBA# |
|--|--------------|--------|------------|
|  | BBS2600CP2   | 916039 | G50768-510 |
| Intel <sup>®</sup> Server Board S2600CP  | DBS2600CP2   | 916040 | G50768-510 |
|  | DBS2600CP4   | 916041 | E99552-510 |
|  | BBS2600CP4   | 916042 | E99552-510 |
|  | P4308CP4MHEN | 916067 | E99552-510 |
| Intel <sup>®</sup> Server System P4000CP | P4308CP4MHGC | 918994 | E99552-510 |
|  | P4208CP4MHGC | 918995 | E99552-510 |

## Description

Intel has found that the Intel<sup>®</sup> Server Board S2600CP and Intel<sup>®</sup> Server System P4000CP may have been programmed with an incorrect BIOS. Affected board serial numbers are in the table below:

| From Serial Number * | To Serial Number * |
|----------------------|--------------------|
| QSCP33500001         | QSCP33500600       |

<sup>\*</sup> Table updated from revision 01 and serial number range reduced.

The BIOS on the affected boards may show the Platform ID as S2600SDP instead of S2600CP and may have extended BIOS settings, as shown in the picture below.

| Logged in as:<br>Platform ID | Administrator<br>S2600SDP |  |
|------------------------------|---------------------------|--|
| System BIOS                  |                           |  |
| BIOS Version                 | SE5C600.86B.01.08.0003    |  |
| Build Date                   | 02/26/2013 15:21:51       |  |

#### **Root Cause**

The server boards affected were programmed with an incorrect BIOS.

Copyright © 2013 Intel Corporation.

\* Other names and brands may be claimed as the property of others.

#### Corrective Action / Resolution

Verify the Platform ID in the BIOS menu and contact Intel using your normal warranty process if the server boards are affected by this issue. Please indicate that you are calling regarding TA-1043-02 when you contact Intel. Have the following information when you call: the MM#, the Product Code, and the serial number(s) of the affected product(s).

Please contact your Intel Sales Representative if you require more specific information about this issue.

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Intel Corporation