

intel® Technical Advisory

TA-709-2

5200 NE Elam Young Parkway
Hillsboro, OR 97124

November 16, 2004

Intel® E7320 MCH Transposed Interrupt Messages across Hub Interface Erratum: Impact to Intel® Server Board SE7320VP2

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The **Intel Server Board SE7320VP2** may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

Product Code	MM #	PBA#
SE7320VP2	859198	C63184-603
BVP7320	859199	C63184-603

Description

An erratum affecting PCI Express* slot capabilities has been found in the Intel® E7320 server chipset during testing and is root caused. Please reference *Intel® E7320 MCH Specification Update Erratum #23: "Transposed Interrupt Messages across Hub Interface Erratum"* for a complete description of the MCH errata. The Intel® Server Board SE7320VP2 is affected by this erratum.

Intel Server Board SE7320VP2 based systems running with a single processor thread and operating in legacy PIC mode or virtual wire Mode A may hang under high I/O-driver interrupt stress. For systems operating in full APIC mode where the number of virtual interrupt lines (intA, intB, etc.) used by all PCI-Express* adapters in a system exceeds the number of logical processors (threads), the system may hang.

Root Cause

Please reference *Intel® E7320 MCH Specification Update Erratum #23: "Transposed interrupt messages across Hub Interface Erratum"* for a complete description of the MCH errata.

Corrective Action / Resolution

PCI Express* add-in adapter card support is limited to single function devices with the Intel Server Board SE7320VP2, PBA# C63184-603.

A BIOS workaround is required for PIC mode operation. The BIOS workaround has been incorporated into Intel Server Board SE7320VP2 BIOS Production Release version P01 and later. Intel recommends that customers update all Intel® Server Board SE7320VP2 to the latest BIOS version. The latest BIOS version is available from iBL and <http://support.intel.com>.

An MCH component stepping change was implemented on the Intel Server Board SE7320VP2, PBA# C63184-604 in early November 2004 to add support for broad PCI Express* adapter add-in cards. PCI Express* add-in adapter cards tested and supported with the Intel Server Board SE7320VP2 are listed in the *Intel Server Board SE7320VP2 Tested Hardware and Operating System List (THOL)* document.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation