intel Technical Advisory

TA-672-3

5200 NE Elam Young Parkway Hillsboro, OR 97124

November 11, 2003

Intel® Server Board SE7501WV2 Power Cycling Issue with Intel® Xeon™ 3.2GHz 1M and 3.06GHz 1M Processors

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The Intel® Server Board SE7501WV2 may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

Product	Product Codes
Intel® Server Board	BWV533SBB
SE7501WV2	BWV533ABB
	SE7501WV2SCSI
	SE7501WV2ATA
	SE7501WV2SKU02
	SE7501WV2S02NA
	SW2USKU07
	SWV1USKU07

Description

Intel discovered an issue with the Intel® Server Board SE7501WV2 during the board validation process with Intel® Xeon™ 3.2GHz 1M processors. During Power Cycling or System Reset, the system occasionally hangs during POST. This issue does not affect the system operation after a successful POST with an uninterrupted run time.

The issue occurrence rate is not consistent, but appears to fail once out of ~100 boots. This issue has also been seen under the same conditions with the Intel® Xeon™ 3.06 GHz 1M processors.

This issue has **only** been seen when running in a dual processor 1M configuration on the Intel® Server Board SE7501WV2.

Work Around

If this issue is observed, a system Reset or Power Cycle is required. Upon successful POST, no further action is required.

It is possible that the Intel® Server Board SE7501WV2 could mark a processor off-line. In this situation it will be necessary to perform a processor retest in BIOS Setup.

To perform a Processor retest on the Intel® Server Board SE7501WV2

- 1. During POST, press <F2> to access BIOS setup
- 2. On the main menu, choose Processor Settings
- 3. Locate the entry Processor Retest, change the value to <ENABLED>
- 4. Press <F10> key to save the settings. Server will reboot & perform the processor retest.

intel Technical Advisory

TA-672-3

5200 NE Elam Young Parkway Hillsboro, OR 97124

November 11, 2003

Root Cause

Root cause has been confirmed. The problem was caused by an L3 cache initialization issue in the board level BIOS code during POST.

Corrective Action / Resolution

A board level BIOS with new POST cache initialization code has been created. The new BIOS production 16.0 build 190 is available for download on iBL and http://support.intel.com.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division Intel Corporation