

PRODUCTS: DP55WB (Standard BIOS)

BIOS Version 0336 - WBIBX10J.86A.0336.2012.0626.0141

About This Release:

- Date: June 26, 2012
- ME Firmware: Ignition 6.0.30.1199 PVSATA RAID Option ROM: v11.2.0.1527
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.65, PXE-2.1 build 089

IMPORTANT: If your board's AA# is E64798-208 or later, you must use BIOS version 0319 or later. Earlier BIOS versions will not work.

New Fixes/Features:

- Updated RAID option ROM to version 11.2.0.1527.
- Fixed no boot issue when certain graphics card is installed.

BIOS Version 0333 - WBIBX10J.86A.0333.2012.0129.2308

About This Release:

- Date: January 29, 2012
- ME Firmware: Ignition 6.0.30.1199 PV
- SATA RAID Option ROM: v11.0.0.1339
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.65, PXE-2.1 build 089

IMPORTANT: If your board's AA# is E64798-208 or later, you must use BIOS version 0319 or later. Earlier BIOS versions will not work.

New Fixes/Features:

- Updated RAID option ROM to version 11.0.0.1339.
- Fixed issues with register settings.
- Improved PCH USB 2.0 performance.
- Fixed issue where fans run at full speed after S3/S4 resume.
- Fixed issue where some graphics cards do not work.

BIOS Version 0319 - WBIBX10J.86A.0319.2011.0223.2022

About This Release:

- Date: February 23, 2011
- ME Firmware: Ignition 6.0.30.1199 PV
- SATA RAID Option ROM: v10.1.0.1008
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.65, PXE-2.1 build 089

IMPORTANT: If your board's AA# is E64798-208 or later, you must use BIOS version 0319 or later. Earlier BIOS versions will not work.

^{*}Other names and brands may be claimed as the property of others.

New Fixes/Features:

- Added Support for new SPI Flash part (Winbond W25016BV).
- Fixed issue where Intel® Desktop Utilities displays no data when UEFI Boot is enabled.
- Fixed issue where BIOS still requires password when user password is not installed and user access level is full.
- Fixed issue where POST Function Hotkeys display on the bottom of the screen before flash process starts during Express BIOS Update and iFlash update.
- Fixed an issue of no "Clear User Password" option prompt when user access set to Limited Access.
- Updated RAID option ROM to version 10.1.0.1008.
- Fixed issue with SMBIOS CPU locator.
- Fixed Intel® Integrator Assistant map file issue.
- Fixed no beep issue when no graphic card is installed.
- Fixed Expansion Card text display issue.
- Fixed SMBIOS PEG slot status issue.
- Remove help string in real-time Hardware monitoring page.

Known Errata:

• BIOS cannot be flashed back to version 0312 or earlier if board has the Winbond chip, since BIOS before version 0319 doesn't support this chip.

BIOS Version 0312 - WBIBX10J.86A.0312.2010.1123.2356

About This Release:

- November 23, 2010
- ME Firmware: Ignition 6.0.30.1199 PV
- SATA RAID Option ROM: v9.6.0.1014
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.65, PXE-2.1 build 089

New Fixes/Features:

- Fixed issue with the display of memory speed in Intel® Desktop Utilities.
- Correct SMBIOS memory location issue.
- Updated PXE UNDI and PXE Base code.
- Updated RAID option ROM to version 9.6.0.1014.
- Added SMBIOS support for G6950 processor.
- Improved BIOS update when Setup variable is changed.
- Corrected processor fan name on the Hardware Monitoring menu.
- Updated Setup strings.

BIOS Version 0310 - WBIBX10J.86A.0310.2010.0728.2257

About This Release:

- July 28, 2010
- ME Firmware: Ignition 6.0.30.1199 PV
- SATA RAID Option ROM: v8.9.0.1023
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.38, PXE-2.1 build 087

^{*}Other names and brands may be claimed as the property of others.

New Fixes/Features:

- Updated AHCI Option ROM.
- Fixed issue where BIOS hangs when using a PCI Express x1 RAID card
- Fixed UEFI boot issue when mass storage device is connected to 3rd party PCIe SATA controller.
- Fixed long delay in POST when using certain large size drives.
- Improved BIOS pre-video boot time.
- Added BIOS OEM version check for F7 update.
- Fixed issue where PCIE Frequency setting caused Intel® Desktop Control Center failure.
- Fixed issue where CPU Max Non Turbo Ratio does not restore to default.
- Updated CPU Idle State, EIST (GV3), and Turbo Boost help texts to more clearly describe interdependencies between them.
- Fixed issue where system hangs after keyboard controller is reset.

BIOS Version 0293 - WBIBX10J.86A.0293.2010.0419.1819

About This Release:

- April 19, 2010
- ME Firmware: Ignition 6.0.30.1199 PV
- SATA RAID Option ROM: v8.9.0.1023
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.38, PXE-2.1 build 087

- Increased tRRD setup option range.
- Improved pre-video boot time.
- Fixed issue where operating system will fail to resume from hibernation when user entered BIOS Setup during POST.
- Updated SMBIOS to version 2.6.
- Fixed issue where SATA port number was not correct in AHCI mode.
- Fixed issue where operating system does not show the processor string correctly.
- Fixed issue where memory overclocking using host clock will fail.
- Fixed issue where BIOS recovery will fail with certain processors.
- Fixed issue where certain USB DVD drives will not boot Windows* DVD from cold boot.
- Updated processor support.
- Set USB Legacy default to enable in UHCI mode.
- Fixed issue where CPU Max Non-Turbo Ratio will not be programmed correctly.
- Fixed issue where BIOS Setup has abnormal behavior.
- Improved BIOS boot time.
- Freed up 256MB of system memory when 3GB or more memory is installed.
- Increased tRFC setup option range.
- Added x12 memory ratio for certain processors.
- Added setup option to allow user to override the Front Panel Audio type to HD or Legacy.
- Fixed WOL issue from S5/S4.
- Added BIOS workaround for excessive USB interrupt activity.

^{*}Other names and brands may be claimed as the property of others.

About This Release:

- March 02, 2010
- ME Firmware: Ignition 6.0.30.1199 PV
- SATA RAID Option ROM: v8.9.0.1023
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.38, PXE-2.1 build 087

- Fixed issue where operating system does not display the processor string correctly.
- Fixed issue where S3 resume times were too long when using 16GB of memory.
- Improve S3 resume time to pass WHQL.
- Fixed issue where PCH DMI Receiver Overflow Uncorrectable Error causes error 0x9F in USBHUB.SYS.
- Updated flash process to skip the Intel ME region when the firmware version remains the same to reduce flashing time.
- Fixed issue where the SATA port number was not correct in AHCI mode.
- Fixed issue where the smmaccess driver did not use correct bus number when accessing the smram registers on S3 resume path.
- Fixed SMBIOS memory structures mismatch installed hardware.
- Added reading of the uncore ratio for certain processors.
- Fixed "Generic USB Hub" failures in WLK 1.4 Computer Single Display Object Test.
- Updated PCH: BIOS spec update 1.04 changes.
- Added HDMI verb table into product specific VerbTable.h file.
- Fixed issue where SMART error event was logging more than the expecting numbers.
- Added feature for "No Video Detected" beep code and switch.
 - o "No Video Detected Error Beeps <Enable/Disable>
 - o Set to enable by default on boards that support on processor graphics.
 - o Set to Disable by default and the switch should be hidden on boards with PEG only graphics.
- Fixed issue where the PCH interrupt registers where not programmed correctly.
- Added BIOS setup option to enable or disable PCH Rate Matching Hub (RMH).
- Fixed issue where microcode did not get loaded during early POST.
- Fixed issue where the processor runs at the minimum frequency when EIST is disabled.
- Fixed issue where system hangs at POST code 0x5A after warm reset with certain SATA drives SATA port 4 or 5.
- Fixed 2.25 terabyte hard disk setup display issue.
- Fixed issue where Intel® Integrator Assistant (IIA) is unable to set the LAN option back to factory default after it has been customized.
- Fixed issue where S3 cycling fails due to a Receiver overflow on DMI interface.
- Fixed issue where the operating system fails to resume from hibernation when user enters BIOS Setup during POST.

^{*}Other names and brands may be claimed as the property of others.

• Fixed issue where PCH UHCI controllers do not work in Windows.

BIOS Version 0190 - WBIBX10J.86A.0190.2010.0112.0219

About This Release:

- January 12, 2010
- ME Firmware: Ignition 6.0.30.1199 PV
- SATA RAID Option ROM: v8.9.0.1023
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.38, PXE-2.1 build 087

- Fixed issue where ACPI NPSS table is not correct when non-Turbo processor is installed.
- Fixed issue where the system hangs at POST code 66h or 69h when a F2 or F12 keys are pressed repeatedly.
- Added Flash-descriptor update process to BIOS Recovery.
- Fixed issue where PCH PCI Bridge is decoding an invalid memory address.
- Added workaround for USB Full-Speed/Low-Speed Port Staggering.
- Fixed Setup Display string on SATA Drive page.
- Added S3 Cycling Enhancement.
- Updated Ignition FW to build 6.0.30.1199
- Fixed issue where wake-on-LAN (WOL) still works in S4 when WOL from S5 is set to disabled.
- Removed disabling of RTT on desktop. RTT is enabled for both mobile and desktop parts.
- Fixed issue where processor runs at the minimum frequency when EIST is disabled.
- Added hard disk SMART error support.
- Added check to only display logo that is less than or equal to supported resolution of 1024x768.
- Changed flex module description of "HanksvilleDCUndi" and "HanksvilleUndi" to "LAN PXE Boot ROM".
- Added setup item to turn off operating system ACPI C2 state.
- Fixed issue where system hangs at POST code 0x5A after warm reset with certain SATA drive in SATA port 4 or 5.
- Improved the workaround to cater for the Gen1 card detection issue during system reset.
- Added BIOS setup item to enable/disable USB ports individually.
- Implemented USB Port(s) disable inside Legacy Boot callback routine.
- Fixed issue where AutoPlay does not work in Windows 7* from a single front panel USB port.
- Fixed MEmanuf test failure due to incorrect BIOS UVSCC value being programmed.
- Fixed issue where two extra beeps are heard after 'No Video Present' error beeps.
- Grey out the Maximum Non-Turbo Ratio option under the Performance setup page if the processor does not support the Flexible Ratio Limit
- Restricted INT 15 copy subfunction 05 from copying to/from certain protected memory regions.
- Resolved security issues concerning buffer overrun and NULL pointer access.

^{*}Other names and brands may be claimed as the property of others.

• Updated USB settings per PCH spec rev 002 version 1.4

BIOS Version WBIBX10J.86A.0165.2009.1110.1916

About This Release:

- November 10, 2009
- ME Firmware: Ignition 6.0.0.1126 PV
- SATA RAID Option ROM: v8.9.0.1023
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.38, PXE-2.1 build 087

New Fixes/Features:

- Fixed issue where PCI resource gets allocated to PCIe memory map region.
- Fixed issue where BIOS setup shows event log with event date but without event type string.
- Added C state configuration lock bit.
- Added EIST disable requires PERF_CTRL to be written for all cores.
- Fixed setup options to be gray when setup item is gray.
- Added the new UQI for Host Clock Frequency to the hide list.
- Updated LAN Initialization.
- Implemented BIOS specification updates 1.03.
- Added capability to disable execution of software SMIs at runtime.
- Updated 82578DC/DM: Intel(R) Boot Agent V1.3.38.
- Updated firmware ID check before recovery starts.
- Fixed issue where SMBIOS Type 10 Video information is shown incorrectly.
- Added workaround for the non-compliance PCI Express device in Gen2 ports.
- Fixed Turbo Boost Technology display issue.
- PEI Capsule File authentication.
- Changed the L2 cache size display to reflect the total L2 cache size.
- Fixed the USB Legacy Disable option non-functioning issue.
- Fixed issue where BIOS setup main page value for Memory Channel B Slot 0 is missing.

BIOS Version 0144

About This Release:

- September 28, 2009
- WBIBX10J.86A.0144.2009.0928.0010
- ME Firmware: Ignition 6.0.0.1126 PV
- SATA RAID Option ROM: v8.9.0.1023
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.36, PXE-2.1 build 087

- Implemented BIOS specification update 1.02.
- Added support in the flash update process to update GbE NV Image region.
- Updated non-vPro NV Image Rev 1.2.

^{*}Other names and brands may be claimed as the property of others.

- Fixed issue of no memory error beep.
- Fixed issue where the IGD would be enabled or show up in video menu when it shouldn't.
- Changed SetupStrY to add 19 for better display.
- Fixed status display when using higher host clock frequencies.
- Updated the MeInfoCallback to check for Rcvy info if Code info is 0.
- Fixed system hang issue when installing a different processor.
- Added feature for memory timings and command rate override for certain processors.
- Updated USB Buffer Strength according to PCH EDS 1.56 spec update.

BIOS Update 0142

About This Release:

- September 09, 2009
- WBIBX10J.86A.0142.2009.0909.2101
- ME Firmware: Ignition 6.0.0.1126 PV
- SATA RAID Option ROM: v8.9.0.1023
- LAN Option ROM : Rev 1.2
- Intel(R) Boot Agent GE v1.3.36, PXE-2.1 build 087

- Fixed BIOS from showing non-supported Setup Option in Intel® Integrator Toolkit (ITK) map file.
- Fixed hang issue when USB Legacy is disabled.
- Changed "Advanced" BIOS screen to "Configuration" BIOS screen.
- Added Intel® Trusted Execution Technology support on PCH Platform.
- Fixed Performance Status display of Memory Multiplier when set to
- Fixed hang during memory initialization when the HPET option is set to disabled.
- Implemented VT-d feature.
- Fixed issue where USB keyboard and mouse do not respond.
- Fixed issue where PEG slot link speed and link width information is displayed incorrectly.
- Added new Setup Boot Display page and other Setup updates.
- Added new PCI/PCIe Add-In card page.
- Fixed issue where watchdog was firing with multiple card readers installed.
- Fixed DFx rules related to BIOS Setup.
- Fixed issue where system would hang at POST code 3Bh with 6GB or 7GB of system memory installed.
- Fixed issue where TCG INT1A BB00h function call was returning incorrect values.
- Updated processor socket name in SMBIOS.
- Fixed performance degradation when running video testing with certain graphics cards.
- Added the capability to show/hide the VT and VT-d setup option.
- Fixed issue where No Event Log when Thermal Trip occurs.
- Added sensor mapping support for P55 based platforms.
- Fixed issue where certain video cards do not work after install/reboot.

^{*}Other names and brands may be claimed as the property of others.

- Fixed issue where clearing CMOS caused thermal trip beeps at next boot.
- PCH EDS specification update 1.53 changes.
- PCH BIOS specification update 1.01.
- Fixed issue where iFlash hangs with all four memory slots populated.
- Fixed a problem where the C1E was disabled if setup question for C states was disabled.
- Fixed issue where Turbo Ratio, TDC, and TDP are not grayed out for non-XE processors.
- Fixed Processor Family in SMBIOS Type 4 structure for Intel® Core™ i7 processors.
- Added feature to block compressed .BMP file from integrated by ITK.
- Fixed issue where Memory speed for empty DIMM slot is shown in Intel® Desktop Utilities (IDU).
- Fixed Memory Speed display issue in Setup.
- Fixed issue where certain RAID card does not work.
- Fixed issue where certain RAID controller card option ROM behavior was unstable.
- Corrected the SpeedStep P0 state ratio to (Max Non-Turbo Ratio + 1) if Turbo Mode is enabled.
- Updated fan control settings to improve fan response and function with boxed thermal solution.
- Added Auto filled the on board LAN MAC address offset in the ATE file.
- Changed BIOS default time from 01/01/2006 to 01/01/2009.
- Fixed issue where French/German/Spanish Language Capsule still show in ITK Flex Module.
- Added color changing highlight for selected Numeric BIOS Setup Options.
- Updated Intel Boot Agent(PXE) version 1.3.36.

BIOS Version 0122

About This Release:

- August 2, 2009
- ME Firmware: Ignition 6.0.0.1126 PV
- SATA RAID Option ROM: v8.9.0.1023
- LAN Option ROM : Rev 1.0
- Intel(R) Boot Agent GE v1.3.35, PXE-2.1 build 087

New Fixes/Features:

• Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied

^{*}Other names and brands may be claimed as the property of others.

warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries. Copyright (c) 2012 Intel Corporation.

^{*}Other names and brands may be claimed as the property of others.