

# Intel<sup>®</sup> True Scale Fabric Switches 12000 Series

**Release Notes** 

May, 2013

Order Number: G91935001US



INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

A "Mission Critical Application" is any application in which failure of the Intel Product could result, directly or indirectly, in personal injury or death. SHOULD YOU PURCHASE OR USE INTEL'S PRODUCTS FOR ANY SUCH MISSION CRITICAL APPLICATION, YOU SHALL INDEMNIFY AND HOLD INTEL AND ITS SUBSIDIARIES, SUBCONTRACTORS AND AFFILIATES, AND THE DIRECTORS, OFFICERS, AND EMPLOYEES OF EACH, HARMLESS AGAINST ALL CLAIMS COSTS, DAMAGES, AND EXPENSES AND REASONABLE ATTORNEYS' FEES ARISING OUT OF, DIRECTLY OR INDIRECTLY, ANY CLAIM OF PRODUCT LIABILITY, PERSONAL INJURY, OR DEATH ARISING IN ANY WAY OUT OF SUCH MISSION CRITICAL APPLICATION, WHETHER OR NOT INTEL OR ITS SUBCONTRACTOR WAS NEGLIGENT IN THE DESIGN, MANUFACTURE, OR WARNING OF THE INTEL PRODUCT OR ANY OF ITS PARTS.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined". Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

The products described in this document may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or go to: http://www.intel.com/design/literature.htm

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

\*Other names and brands may be claimed as the property of others.

Copyright © 2013, Intel Corporation. All rights reserved.

# Contents

1.0	Over	Overview of the Release			
	1.1	Introduction	5		
	1.2	Audience	5		
	1.3	If You Need Help	5		
	1.4	New Features and Enhancements	5		
	1.5	Installation Requirements	5		
	1.6	Changes to Hardware Support	6		
	1.7	Changes to Industry Standards Compliance			
	1.8	Miscellaneous	6		
	1.9	Documentation			
2.0	Bug Fixes				
_	2.1	Known Issues	8		
Tab	les				
1	Rela	ted Documentation for this Release	7		
2					
3		Open Issues			







# **1.0 Overview of the Release**

## **1.1** Introduction

These Release Notes provide a brief overview of the changes introduced into the True Scale Fabric Switches 12000 Series for this release. References to more detailed information are provided where necessary. The information contained in this document is intended for supplemental use only; it should be used in conjunction with the documentation provided for each component.

These Release Notes list the new features, system issues closed since the previous release, as well as any known issues.

## 1.2 Audience

The information provided in this document is intended for installers, software support engineers, hardware engineers, and service personnel.

## 1.3 If You Need Help

If you need assistance while working with the True Scale Fabric Switches 12000 Series, contact your Intel approved reseller or Intel True Scale Technical Support:

- By E-mail: ibsupport@intel.com
- On the Support tab at web site: http://www.intel.com/infiniband

For OEM-specific server platforms supported by this release, contact your OEM.

#### **1.4 New Features and Enhancements**

The following new features and enhancements have been made between Release 7.1.1.1.1 and 7.2.0.1.1:

- As part of the 7.2 release, the following Chassis SNMP MIBs are now provided:
  - icsChassisMib
  - icsChassisTrapMib
  - icsConfigFileTrapMib
  - icsIBStatMib
  - icsKeyMgmtMib
  - icsLogConfigMIB
  - icsMasterMib
  - icsSmMib
- The embedded version of the  $\ensuremath{\mathsf{Intel}}^{\ensuremath{\mathbb{R}}}$  Fabric Manager no longer requires a license key.
- All product rebranding has been completed.

#### **1.5 Installation Requirements**

There are no special or release-specific installation requirements for this release.



### **1.6 Changes to Hardware Support**

There are no release-specific changes to the hardware supported for this release.

#### **1.7 Changes to Industry Standards Compliance**

There are no changes to the industry standards for this release.

#### **1.8** Miscellaneous

- Different chassis types require different time intervals to fully reboot. The amount of time it takes a switch to reboot is dependent upon several factors, including:
  - The type of reboot
  - The number of leaves, spines and management modules in the chassis.
  - Whether or not the switch chip firmware is being updated as a result of the reboot.
- Below are the maximum times that a chassis will take to reboot. In your environment you might see reboot times much less than these:
  - 12200/12300 120 seconds
  - 12800-040 220 seconds
  - 12800-120 290 seconds
  - 12800-180 350 seconds
  - 12800-360 630 seconds

At any point during the reboot, you can point a web browser to the chassis IP address, or telnet/ssh to the chassis IP address to see if the reboot has completed.

- The embedded version of the  $\ensuremath{\mathsf{Intel}}^{\ensuremath{\mathbb{R}}}$  Fabric Manager supports a maximum of 500 nodes.
- Intel products will auto-negotiate with devices that utilize IBTA-compliant autonegotiation.
- When attaching Intel products to a third-party device, the bit error rate is optimized if the third-party device utilizes attenuation-based tuning.
- For most configurations, using the default MTU size of 2K is recommended.
- The True Scale Fabric Switches 12000 Series supports the following web browsers:
  - Windows Internet Explorer version 8.0 (for Windows XP)
  - Windows Internet Explorer version 9.0 (for Windows 7)
  - Mozilla Firefox version 19.0 (for Windows XP and Windows 7)
  - Mozilla Firefox version 3.5.9 (for SLES11 SP1)
  - Mozilla Firefox version 3.6 (for RHEL5.7, 5.8, 6.1, and 6.2)
  - Mozilla Firefox version 10.0 (for RHEL5.9 and 6.3, and SLES11 SP2)

#### **1.9 Documentation**

Table 1 lists the Release 7.2 related documentation. All related documentation is available on the Intel download site.

Documentation for Intel Partners is available at the vendors web site.



#### Table 1.Related Documentation for this Release

Document Title					
Intel <sup>®</sup> Hardware Documents					
Intel <sup>®</sup> True Scale Fabric Switches 12000 Series Hardware Installation Guide					
Intel <sup>®</sup> True Scale Fabric Switches 12000 Series Users Guide					
Intel <sup>®</sup> True Scale Fabric Switches 12000 Series CLI Reference Guide					
Intel <sup>®</sup> True Scale Fabric Adapter Hardware Installation Guide					
Intel <sup>®</sup> OFED+ Documents					
Intel <sup>®</sup> True Scale Fabric Software Installation Guide					
Intel <sup>®</sup> True Scale Fabric OFED+ Host Software User Guide					
Intel <sup>®</sup> True Scale Fabric OFED+ Host Software Release Notes					
Intel <sup>®</sup> IFS Documents					
Intel <sup>®</sup> True Scale Fabric Suite FastFabric User Guide					
Intel <sup>®</sup> True Scale Fabric Suite Fabric Manager User Guide					
Intel <sup>®</sup> True Scale Fabric Suite FastFabric Command Line Interface Reference Guide					
Intel <sup>®</sup> True Scale Fabric Suite Software Release Notes					
Intel <sup>®</sup> Fabric Viewer Documents					
Intel <sup>®</sup> True Scale Fabric Suite Fabric Viewer Online Help					
Intel <sup>®</sup> True Scale Fabric Suite Fabric Viewer Release Notes					

# 2.0 Bug Fixes

Table 2 lists the fixes that have been made to the True Scale Fabric Switches 12000 Series family of QDR InfiniBand  $^{\ast}$  switches:

#### Table 2.Resolved Issues

Release	Product	Description	
7.2.0.1.1	12000 Managed Switches	SNMP Target Address names that are 14 characters or greater now work properly.	
7.2.0.1.1	12000 Management Software	Adding an ESM Key after a 6-port incremental license key no longer causes the 6 ports to become unlicensed.	
7.2.0.1.1	12000 Management Software	Chassis Viewer Firmware Update page now displayed correctly with Firefox 3.6 browsers.	
7.1.1.1.1		None	



# 2.1 Known Issues

Table 3 lists the open issues for 7.2.0.1.1.

#### Table 3.Open Issues

Product/ Component	Description	Workaround
Chassis Hardware	Following a hot swap of a management module (MM) (with the part number 220055-001-C or earlier), the ATTN LED will occasionally flash once and the module does not boot.	<ol> <li>Add a subnet in Fabric Viewer for each Fabric Manager whose configuration they need to edit.</li> <li>Connect to each subnet, open the Edit Virtual Fabric dialog and make the changes to each Fabric Manager configuration.</li> </ol>
Chassis Viewer GUI	When using a web browser on a Linux system and rebooting the switch, only two digits of the countdown time are displayed. If the countdown time is greater than 100, the ones column is not displayed, causing the countdown to appear to be proceeding very slowly (that is, decreasing 1 second every 10 seconds).	Once the time remaining reaches 99 seconds, the counter will be displayed correctly.
Chassis Hardware	Sometimes when inserting fiber optic cables (with the following part numbers) the warning message "QSFP fault condition" is logged in the switch log. CBL2-1000301-3 - 3.0M Fiber QSFP to QSFP. CBL2-1001001-3 - 10M Fiber QSFP to QSFP. CBL2-1003001-3 - 30M Fiber QSFP to QSFP.	This message can be safely ignored.
Chassis Viewer GUI	In a dual-management module (MM) setup, when rebooting either a slave or master MM using the Chassis Viewer GUI, the GUI takes much longer than normal to refresh itself.	Rather than wait for the GUI countdown timer to complete, 100 seconds after rebooting the MM enter the chassis URL into the browser address bar.