

Motherboard Logo Program (MLP)

Intel® Desktop Board DG41MJ

MLP Report

9/21/2009

Purpose:

This report describes the DG41MJ Motherboard Logo Program testing run conducted by Intel Corporation.

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NONINFRINGEMENT FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel®s Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel and Pentium are registered trademarks of Intel Corporation in the United States and other countries.

 $^{\star}\,$ Other names and brands may be claimed as the property of others.

Copyright © 2007 Intel Corporation. All rights reserved.

Contents

Introduction	4
Terms and Definitions	
Desktop Board Configuration	5
Desktop Board DG41MJ Final Configuration Report: Completion of MLP	5
Board Information	5
Product Code	5
Processor	5
Motherboard	5
System Memory	5
Power Management	5
Operating System Tested	5
Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit	6
Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit	
Windows Logo Kits Used (WLK)	6
Errata and Contingencies	7
Test Notes	8

Introduction

Terms and Definitions

Term	Definitions
WHQL	Windows* Hardware Qualification Lab
WLK	Windows Logo Kits
MLP	Motherboard Logo Program. For further information see: http://www.microsoft.com/whdc/hwtest/default.mspx
AP Machine	Audio Precision Machine
Winqual	Windows Qualification
MSFT Tested Product List	Tested Products List. You can view the Windows Marketplace for tested products list at: http://winqual.microsoft.com/HCL/ProductList.aspx?m=v&cid=105&g=s

Desktop Board Configuration

Desktop Board DG41MJ Final Configuration Report: Completion of MLP

Data in this section reflects system configuration at time of MLP submission.

Board Information

Product Code ¹	BIOS String/Model	Technologies NOT Logo'd (yet)			
DG41MJ	MJG4110H.86A.0003.2009.0313.1434	N/A - all technologies logo'd			
Processor	Processor				
Speed	3.0GHz	3.0GHz			
Family	Intel® Core™2 Quad				
Bus Speed	1333 MHz				
Motherboard					
Board AA #	E54659				
Board FAB #	204				
	es to the production FAB revision; Please coion you intend to perform logo testing if no	onsult your Intel Corporation representative to clarify the ot the same.			
System Memory					
Speed	Dual Channel, DDR2, 800MHz				
Memory Type	DIMM				
Connector Type	DDR2, 240 Pin				
Power Management					
BIOS Default	S3				
Operating System Tested					
	Check Tested	Comments			
Windows 7 and 64-bit		Windows 7 Ultimate			
Windows Vista and 64-bit	✓ Vista Ultimate with Service Pack 1				
Windows Vista Basic and 64-bit	□ Vista Basic with Service Pack 1				

¹ These are the product names to enter in the "Submission ID of previously logo'd qualified PC system or server" field during your "System Using a Previously Logo'd Motherboard" submission to Microsoft.

Onboard Integrated Devices and Driver for Vista 32-bit and 64-bit

Technology	OS	Version	Package version
Chipset Update Utility	Windows Vista	9.0.0.1009	9.0.0.1011
Intel [®] Chipset Software Utility	Windows Vista 64-bit	9.0.0.1009	9.0.0.1011
Graphics	Windows Vista	7.15.10.1624	15.11.5.1624
Intel® Graphics Media Accelerator	Windows Vista 64-bit	7.15.10.1624	15.11.5.64.1624
Audio	Windows Vista	6.0.1.5783	5783
Realtek	Windows Vista 64-bit	6.0.1.5783	5783
LAN	Windows Vista	6.214.1211.2008	6.214
Realtek	Windows Vista 64-bit	6.214.1211.2008	6.214

Onboard Integrated Devices and Driver for Windows 7 32-bit and 64-bit

Technology	OS	Version	Package version	
Chipset Update Utility	Windows 7	6.1.7100.0	Inbox Driver	
Intel [®] Chipset Software Utility	Windows 7 64-bit	6.1.7100.0	Inbox Driver	
Graphics	Windows 7	8.15.10.1808	15.15.0.1808	
Intel [®] Graphics Media Accelerator	Windows 7 64-bit	8.15.10.1808	15.15.64.1808	
Audio	Windows 7	6.0.1.5859	5859	
Realtek	Windows 7 64-bit	6.0.1.5859	5859	
LAN	Windows 7	7.3.522.2009	7.003	
Realtek	Windows 7 64-bit	7.3.522.2009	7.003	

Windows Logo Kits Used (WLK)

Microsoft website: http://www.microsoft.com/whdc/DevTools/WDK/DTM.mspx

Please check regularly for test kit updates from Microsoft. Please ensure latest filters updated prior to WHQL run.

Operating Systems	Notes	WHQL Testkit	
Windows 7	WLK1.4 for Windows 7	WLK1.4 for Windows 7	
Windows 7 64-bit	WEIGHT WINDOWS 7	WENT. 4 TOT WINDOWS 7	
Windows Vista	WLK1.4 for Windows Vista SP1	WLK1.4 for Windows Vista SP1	
Windows Vista 64-bit	WCK 1.4 TOT WITHOWS VISTA SF T	WCK 1.7 TOT WITHOUTS VISTA SF I	

Errata and Contingencies

Operating System	Failing Test	Expiry Date	ID Number	Туре	Error Description
Windows 7 Windows 7 64-bit	1)Class Driver Fidelity Test - Win7 (System, Manual) 2)Fidelity Test -	12/31/2009	1547	Erratum	Fidelity Test now includes a "Render Power Transition" test. This preview filter covers all errors in this new test of SYSFUND-0050.
	Win7 (System, Manual)				
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/31/2009	759	Erratum	ISSUE: PCI Compliance - Bit range 11:10 (ASPM Support)in the Link Capabilities register (offset Ch) in the PCI Express Capability table must be read-only. RESOLUTION: The following PCI Compliance failure assertion is allowed 4D19D0E6-51CC-49CF-8459-31AAA0587E4B.
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	12/31/2009	884	Erratum	Assertion 3EF27DC9-463F-4712-857B-0321832E7383 Bit range 23:0 (Organizationally Unique Identifier)in the Serial Number 1st DW register (offset 4h) in the Device Serial Number Capability table cannot have a value of 0h as it must contain a value assigned by IEEE.
Windows 7 Windows 7 64-bit	PCI Hardware Compliance Test For Systems	06/01/2010	1543	Erratum	This happens because the PCI Compliance test assumes that if the Data Link Layer Link Active Reporting Capable bit in the Link Capabilities register for a given PCIe port is set then that indicates that the Data Link Layer Link Active bit will also be set. This is an incorrect assumption because the Data Link Link Layer Link Active bit can be reset when there is no device below the port. This assertion needs to be removed from the PCIHCT. The current architecture of the PCIHCT prevents it from knowing whether devices exist below a bridge/port.
Windows 7 Windows 7 64-bit	UAA Test - Win7 (System)	12/01/2009	1394	Erratum	UAA Test requires the Traffic Priority bit to be read/write - however there are two specs that apply, and they conflict. One says the bit must be read/write, the other says it must be read-only. Contact has been made with the author of both specs (Intel) but until this point is clarified we cannot fail submissions containing this test failure.
Windows 7 Windows 7 64-bit	UAA Test - Win7 (System)	07/01/2011	1793	Erratum	Preview filter - Keepalive on low power digital outputs
Windows 7 Windows 7 64-bit	UAA Test - Win7 (System)	06/01/2010	1794	Erratum	UAA Test wrongly tests pin widgets that have their Configuration Default register's Port Connectivity field set to No Connection.
Windows 7 64-bit	Wave Test - Win 7 (System)	06/01/2010	1584	Erratum	Run "Data Intersection Test\Capture Streaming\Check Supported Formats" out of WaveTest on a system containing audio devices that are "disabled" via the Sound Control panel. Expected results: should succeed. Actual results: fail with "Failed to find any endpoints for the current pin" and "Failed to decide if current data intersection test should be skipped"

Test Notes

Operating System	Test	Description
Windows 7 and Vista	BIOS download	Internal: http://bios.intel.com/downloads/ External: http://www.intel.com/ click on Support and Download
Windows 7 and Vista	BIOS setup	Please make sure the BIOS setting are as below, otherwise use default settings. System Date and Time: Current date and time Peripheral Configuration: Enable all onboard component (Except CIR) Drive Configuration: Set to IDE Chipset Configuration: Enable HPET ACPI Suspend State: Set to <s3 state=""> Boot Device Priority: set <hard disk="" driver=""> to first Note: Enhanced Consumer IR (CIR) component is not supported under Windows7.</hard></s3>
Windows 7 and Vista filter update	WLK WHQL test	http://winqual.microsoft.com/member/SubmissionWizard/LegalExemptions/filterupdates.cab
Special H/W that use to PASS the test	None	None