



This Technical Advisory describes an issue which may or may not affect the customer's product

# Intel Technical Advisory

TA-0890-1

5200 NE Elam Young Parkway  
Hillsboro, OR 97124

December 10, 2007

## SR2500 Based systems built with incorrect version of power distribution module

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The **SR2500** may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

### Products Affected

SR2500  
SR2500NA  
SR2500ALBRPR  
SR2500ALBRPRNA  
SR2500ALLXR  
SR2500ALLXRNA  
SR2500ALOEMR  
SR2500ALOEMRNA

### Description

Intel documented a change to the Power Distribution Module in PCN# 107919. The change to the new module was documented to occur with a Top Assembly Number (TA #) change. This change actually occurred prior to the TA # change. The table of affected product codes, TA #s and Serial Number ranges below details the affected units. Each serial number listed below was built prior to the documented TA # change with the new Power Distribution Module.

Product Code	TA#	Serial Number Range
SR2500 SR2500NA	D43689-012 D43689-013	BZDS74400101 – BZDS74400400
SR2500ALBRPR SR2500ALBRPRNA	E10104-003	BZDS74400437 – BZDS74400650
SR2500ALLXR SR2500ALLXRNA	E10105-002 E10105-003	BZDS74300451 – BZDS74300550 BZDS74400651 – BZDS74400900 BZDS74500551 – BZDS74500800
SR2500ALOEMR SR2500ALOEMRNA	E10333-002 E10333-003	BZDS74300553 – BZDS74300620 BZDS74500001 – BZDS74500050

The secondary change in PCN #107919 to the IDE cable was not affected. The IDE cable change occurred as documented in the PCN.

**Corrective Action / Resolution**

There is no functional impact to systems as a result of this Power Distribution Module change. The systems may be used as is without further action.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division  
Intel Corporation