



This Technical Advisory describes an issue which may or may not affect the customer's product

Intel Technical Advisory

TA-0891-1

5200 NE Elam Young Parkway
Hillsboro, OR 97124

December 10, 2007

SR1500 Based systems built with incorrect version of power supply

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice. The **SR1500** may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Products Affected

SR1500
SR1500NA
SR1500AL
SR1500ALNA
SR1500ALSAS
SR1500ALSASNA

Description

Intel documented a change to the Power Supply in PCN# 107931. The change to the new supply was documented to occur with a Top Assembly Number (TA #) change. This change actually occurred prior to the TA # change. The table of affected product codes, TA #s and Serial Number ranges below details the affected units. Each serial number listed below was built prior to the documented TA # change with the new Power Supply.

Product Code	TA#	Serial Number Range
SR1500 SR1500NA	D47572-006	BZDG74300539 – BZDG74300545 BZDG74400005 – BZDG74400092
SR1500ALR SR1500ALRNA	D99976-002 D99976-003	BZDG74400093 – BZDG74400337 BZDG74500001 – BZDG74500250
SR1500ALSASR SR1500ALSASRNA	E10101-002	BZDG74400343 – BZDG74400622

The secondary change in PCN #107931 to the power supply baffle was not affected. The power supply baffle change occurred as documented in the PCN.

Corrective Action / Resolution

There is no functional impact to systems as a result of this Power Supply change. The systems may be used as is without further action.

Please contact your Intel Sales Representative if you require more specific information about this issue.

Enterprise Platforms & Services Division
Intel Corporation