

Intel® Omni-Path Fabric Managed Switches

Version 10.0.1 Release Notes

April 2016

Order No.: J24422-1.0



You may not use or facilitate the use of this document in connection with any infringement or other legal analysis concerning Intel products described herein. You agree to grant Intel a non-exclusive, royalty-free license to any patent claim thereafter drafted which includes subject matter disclosed herein.

No license (express or implied, by estoppel or otherwise) to any intellectual property rights is granted by this document.

All information provided here is subject to change without notice. Contact your Intel representative to obtain the latest Intel product specifications and roadmaps.

The products described may contain design defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Copies of documents which have an order number and are referenced in this document, or other Intel literature, may be obtained by calling 1-800-548-4725, or by visiting: http://www.intel.com/design/literature.htm

Intel technologies' features and benefits depend on system configuration and may require enabled hardware, software or service activation. Learn more at http://www.intel.com/ or from the OEM or retailer.

April 2016

Order No.: J24422-1.0

Intel and the Intel logo are trademarks of Intel Corporation in the U.S. and/or other countries.

*Other names and brands may be claimed as the property of others.

Copyright © 2015-2016, Intel Corporation. All rights reserved.



Contents

April 2016 Order No.: J24422-1.0

1.0	Ove	erview of the Release	1
	1.1	Introduction	1
	1.2	Audience	1
	1.3	If You Need Help	1
	1.4	Supported in this Release	1
	1.5	Product Constraints	
	1.6	Installation Requirements	1
		1.6.1 Changes to Firmware Components	2
	1.7	Miscellaneous	2
	1.8	Documentation	2
2.0	Sys	tem Issues	4
	2.1	Resolved Issues	
	2.2	Open Issues	
Tab	les		
1.	-1	Related Documentation for this Release	2
2-1		Resolved Issues	
2.	-2	Open Issues	_



1.0 Overview of the Release

1.1 Introduction

These Release Notes provide a brief overview of the changes introduced into the Intel[®] Omni-Path Fabric Managed Switches. References to more detailed information are provided where necessary. The information contained in this document is intended for supplemental use only; it should be used in conjunction with the documentation provided for each component.

These Release Notes list the new features, system issues closed since the previous release, as well as any known issues.

1.2 Audience

The information provided in this document is intended for installers, software support engineers, hardware engineers, and service personnel.

1.3 If You Need Help

If you need assistance while working with the $Intel^{\circledR}$ Omni-Path Fabric Managed Switches, contact your Intel representative.

1.4 Supported in this Release

The following items are supported for this release:

- 48-port Intel® Omni-Path Edge Switch 100, internally managed
- 6-slot Intel[®] Omni-Path Director Class Switch 100 Series
- 24-slot Intel[®] Omni-Path Director Class Switch 100 Series

1.5 Product Constraints

• The embedded version of the Intel[®] Fabric Manager supports up to a maximum of 100 nodes within a fabric. This is due to the limited memory and processing resources available in the embedded environment.

1.6 Installation Requirements

This release has no special or release-specific installation requirements.

April 2016 Order No.: J24422-1.0



1.6.1 **Changes to Firmware Components**

The following firmware is supported in this release:

 Internally-managed edge: STL1.q7.10.0.1.0.21.spkg

and has been tested with the following externally-managed switch firmware:

• Externally-managed edge: Intel_PRREdge_V1_firmware.10.0.1.0.21.emfw

1.7 **Miscellaneous**

None.

1.8 **Documentation**

Table 1-1 lists the end user documentation for the current release.

Documents are available at the following URLs:

- Intel® Omni-Path Switches Installation, User, and Reference Guides http://www.intel.com/SUPPORT/NETWORK/OMNI-SWTCH100/SB/CS-035856.HTM
- Intel® Omni-Path Host Fabric Interface Installation, User, and Reference Guides (includes software documents)
 - http://www.intel.com/support/network/omni-adptr/sb/CS-035857.htm
- Drivers and Software (including Release Notes) https://downloadcenter.intel.com/

Table 1-1. Related Documentation for this Release (Sheet 1 of 2)

Document Title					
Hardware Documents					
Intel [®] Omni-Path Fabric Switches Hardware Installation Guide					
Intel® Omni-Path Fabric Switches GUI User Guide					
Intel [®] Omni-Path Fabric Switches Command Line Interface Reference Guide					
Intel® Omni-Path Edge Switch Platform Configuration Reference Guide					
Intel® Omni-Path Fabric Managed Switches Release Notes					
Intel [®] Omni-Path Fabric Externally-Managed Switches Release Notes					
Intel [®] Omni-Path Host Fabric Interface Installation Guide					
Fabric Software Documents					
Intel [®] Omni-Path Fabric Software Installation Guide					
Intel [®] Omni-Path Fabric Suite Fabric Manager User Guide					
Intel [®] Omni-Path Fabric Suite FastFabric User Guide					
Intel [®] Omni-Path Fabric Host Software User Guide					
Intel [®] Omni-Path Fabric Suite Fabric Manager GUI Online Help					
Intel [®] Omni-Path Fabric Suite Fabric Manager GUI User Guide					
Intel [®] Omni-Path Fabric Suite FastFabric Command Line Interface Reference Guide					
Intel® Performance Scaled Messaging 2 (PSM2) Programmer's Guide					
Intel® Omni-Path Fabric Performance Tuning User Guide					

April 2016 Version 10.0.1 Release Notes Order No.: J24422-1.0



Table 1-1. Related Documentation for this Release (Sheet 2 of 2)

Document Title					
Intel [®] Omni-Path Host Fabric Interface Platform Configuration Reference Guide					
Intel [®] Omni-Path Fabric Software Release Notes					
Intel [®] Omni-Path Fabric Manager GUI Release Notes					
Intel [®] Omni-Path Storage Router Design Guide					
Building Lustre* Servers with Intel [®] Omni-Path Architecture Application Note					



2.0 System Issues

This section lists the resolved and known issues for the ${\rm Intel}^{\circledR}$ Omni-Path Fabric Managed Switches.

2.1 Resolved Issues

Table 2-1 lists the resolved issues for this release.

Table 2-1. Resolved Issues

ID	Description	Resolved in Release
132525	If you are running in a host subnet manager-emdedded subnet manager configuration, a Virtual Fabric cannot run with a MaxMTU value of either 8192 or 10240. This causes checksum errors and forces one of the subnet mangages into an inactive state, even though the XML configurations appear to be valid.	10.0.1
132701	Director switches with redundant management may hang during firmware upgrade to release 10.0.0.0.686.	10.0.1
132707	dhcpdisable no longer generates a pagefault	10.0.1
132711	Link Down and Error Recovery are now cleared correctly.	10.0.1
132800	In Chassis Viewer, the FRU information window does not display correct Manufacturer Date and Time information.	10.0.1
132838	Pre-production STF Fan Tray hardware may intermittently report I2C path errors to fan modules in the diagnostic logs. Such log entries should not be a cause for significant concern. Firmware handles these path errors gracefully without disruption to system functionality, and fan performance is not impaired.	10.0.1
133265	All links meeting Intel [®] Omni-Path bit error ratio (BER) performance requirements will now report a link quality of 5.	10.0.1



2.2 Open Issues

Table 2-2 lists the known open issues for this release by component, including the description and workaround.

Table 2-2. Open Issues

ID/ Status	Product/ Component	Description	Workaround
132617	Switch Fabric Management/ SM	Fabric Manager SwitchCascadeActivateEnable configuration setting can leave IPoIB in a non-working state for HFIs. This problem occurs when the Sm.SwitchCascadeActivateEnable setting in opafm.xml is enabled for all devices, and the FM is restarted. The restarted SM never issues a client reregistration of SA subscriptions request to endnodes.	Change the default Sm.SwitchCascadeActivateEnable setting in opafm.xml to a value of 0.
132786	Switch Software/ Chassis Management Downgrading from the production validated (PV) release to release 10.0.0.0.625 (or earlier) fails.		Do not downgrade the firmware from the PV release.

§ §