

BIOS Update Release Notes

PRODUCTS: NUC5i5MYBE, NUC5i5MYHE

BIOS Version 0055 - MYBDWi5v.86A.0055.2019.0820.1505

About This Release:

- Date: August 20, 2019
- ROM Image Checksum: 0x9BA2
- ME Firmware: 10.0.56.3002
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23
- Supported Flash Devices: WinBond W25Q128FVSIG 16MB MACRONIX MX25L12835FM 16MB
- Microcode Updates included in .ROM & .BIO Files: MC0306D4 0000002D.mcb

New Fixes/Features:

• Updated BIOS code for security fixes.

BIOS Version 0054 - MYBDWi5v.86A.0054.2019.0520.1531

About This Release:

- Date: May 20, 2019
- ROM Image Checksum: 0x812E
- ME Firmware: 10.0.56.3002
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Updated BIOS code for security fixes.
- Changed the chassis enclosure type to 0x23.

BIOS Version 0051 - MYBDWi5v.86A.0051.2019.0409.1419

About This Release:

- Date: April 9, 2019
- ME Firmware: 10.0.56.3002
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics:
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
 - SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

•

• Updated BIOS code for security fixes.

BIOS Version 0050 - MYBDWi5v.86A.0050.2019.0221.1315

About This Release:

- Date: February 21, 2019
- ME Firmware: 10.0.56.3002
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Updated BIOS code for security fixes.
- Updated setting for "Boot Network Devices Last" item to allow user to modify IPv4/IPv6 priority when "Boot Network Devices Last" is enabled.

BIOS Version 0049 - MYBDWi5v.86A.0049.2018.1107.1046

About This Release:

- Date: November 7, 2018
- ME Firmware: 10.0.56.3002
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09

- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

- Fixed issue where system hangs during POST when Western Digital 1TB MyPassport external USB drive is connected.
- Added Setup item **Power Button Menu Beeps**, with default set to enabled.
- Added Setup item Auto USB provisioning for Intel AMT, with default set to enabled.

BIOS Version 0048 - MYBDWi5v.86A.0048.2018.0709.2009

About This Release:

- Date: July 9, 2018
- ME Firmware: 10.0.56.3002
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Updated CPU Microcode (Security Advisory-00115)
- Removed Intel® Ready Mode Technology code/items in BIOS for Intel security fix.

BIOS Version 0047 - MYBDWi5v.86A.0047.2018.0601.1552

About This Release:

- Date: June 1, 2018
- ME Firmware: 10.0.56.3002
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics
 - o Option ROM: Build 1039
 - o UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

• Security enhancements.

BIOS Version 0044 - MYBDWi5v.86A.0044.2018.0303.1558

About This Release:

- Date: March 3, 2018
- ME Firmware: 10.0.56.3002
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics
 - o Option ROM: Build 1039
 - o UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

- Updated CPU Microcode (Security Advisory-00088)
- Fixed issue where wrong an incorrect IRQ triggered AMT SOL.

BIOS Version 0040 - MYBDWi5v.86A.0040.2017.1130.1223

About This Release:

- Date: November 30, 2017
- ME Firmware: 10.0.56.3002
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics:
 - o Option ROM: Build 1039
 - o UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

- Updated Management Engine Firmware to version: 10.0.56.3002 (Security Advisory-00086).
- Added a new BIOS option within the "Power" tab, which allows USB power during reboot. The default state is disabled.
- Due to a security enhancement, it will not be possible to go to any BIOS earlier than BIOS 0040.

BIOS Update 0039 - MYBDWi5v.86A.0039.2017.1016.1545

About This Release:

- Date: Date: October 16, 2017
- ME Firmware: 10.0.55.3000
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics
 - Option ROM: Build 1039
 - UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09

- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

- Security enhancements.
- Added the setup option "Allow UEFI Third Party Driver loaded" and set the default state to disabled.
- Due to a security enhancement, it will not be possible to go to any BIOS earlier than BIOS 0038.

BIOS Version 0038 - MYBDWi5v.86A.0038.2017.0726.1622

About This Release:

- Date: Date: Jun 26, 2017
- ME Firmware: 10.0.55.3000
- Memory Reference Code: Based on 2.9.0
- MEBx Code: Based on 10.0.0007
- Integrated Graphics
 - o Option ROM: Build 1039
 - o UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

• Added S.M.A.R.T item and functionality.

BIOS Version 0035 - MYBDWi5v.86A.0035.2017.0506.1649

About This Release:

- Date: May 6, 2017
- ME Firmware: 10.0.55.3000
- EC Firmware: NA
- MEBx Code: Based on 10.0.0007
- Integrated Graphics
 - o Option ROM: Build 1039
 - o UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

New Fixes/Features:

• Updated Intel® Management Engine firmware to version 10.0.55.3000.

BIOS Version 0034 - MYBDWi5v.86A.0034.2017.0116.2148

About This Release:

- Date: January 16, 2017
- ME Firmware: 10.0.47.1006
- EC Firmware: NA

- MEBx Code: Based on 10.0.0.0007
- Integrated Graphics
 - o Option ROM: Build 1039
 - o UEFI Driver: 5.5.1033
- SATA RAID Option ROM: 14.5.0.2241
- SATA non-RAID Option ROM: 14.5.0.2241
- AHCI Code: Based on 09
- LAN Option ROM: 1.5.55
- Visual BIOS: 2.2.23

• Security Enhancements

BIOS Version 0033 - MYBDWi5v.86A.0033.2016.1124.2006

About This Release:

- Date: November 24, 2016
- ME Firmware: 10.0.47.1006
- TXT ACM revision: 1.2
- RST RAID: v14.5.0.2241
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.23
- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1039 UEFI Driver: 5.5.1033

New Fixes/Features:

• Security Enhancements.

BIOS Version - MYBDWi5v.86A.0032.2016.1109.1838

About This Release:

- Date: November 9, 2016
- ME Firmware: 10.0.47.1006
- TXT ACM revision: 1.2
- RST RAID: v14.5.0.2241
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.23
- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1039 UEFI Driver: 5.5.1033

New Fixes/Features:

• Security Enhancements.

BIOS Version 0031 - MYBDWi5v.86A.0031.2016.0913.1113

About This Release:

- Date: September 13, 2016
- ME Firmware: 10.0.47.1006
- TXT ACM revision: 1.2
- RST RAID: v14.5.0.2241

- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.23
- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1039 UEFI Driver: 5.5.1033

- Security Enhancements.
- Updated BootScriptHide module to BootScriptHide 02.
- Changed the SATA DevSleep setting from Enabled to Disabled.
- Updated Visual BIOS to version 2.2.23.
 - o Fixed missing voltages in Cooling Page.
 - o Fixed inactive Home Page 3 and Performance links on NUC theme.
 - Added support for loading data from file for platform (e.g. EDID, Secure Boot, etc).
 - o Fixed issue where unsupported keys could be entered in password.
 - Fixed hang when using keyboard to configure a drop down control.
 - o Added support for legacy boot options to Visual Boot Manager.
 - Added support for booting to multiple partitions on the same device from Visual Boot Manager.
 - o Added support to Visual Boot Manager for booting to operating systems that do not support EFI default boot path.

BIOS Version 0030 - MYBDWi5v.86A.0030.2016.0527.1657

About This Release:

- Date: May 27, 2016
- ME Firmware: 10.0.47.1006
- TXT ACM revision: 1.2
- RST RAID: v14.5.0.2241
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.20
- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1039 UEFI Driver: 5.5.1033

New Fixes/Features:

- Added Windows firmware update function.
- Fixed an issue where the NUC can't wake up from S3 by pressing the power button in Linux.

BIOS Version 0029 - MYBDWi5v.86A.0029.2016.0422.1803

About This Release:

- Date: April 22, 2016
- ME Firmware: 10.0.47.1006
- TXT ACM revision: 1.2
- RST RAID: v14.5.0.2241
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.20
- PXE ROM : 1.5.55
- Integrated Graphics

Option ROM: Build 1039 UEFI Driver: 5.5.1033

New Fixes/Features:

- Improved BIOS update function by disabling keyboard and power button during the flash/recovery process.
- Changed the Power button menu and F4 recovery:
 - o Removed G3 power button recovery

 - o Added BIOS ID information prompt and allow customer cancel the recovery if hit ESC by 20 second.
 - o Added recovery progress information
- Added NVRAM preserved variables "DmiData", "UUID" and "OA3Data".
- Hid "NFC" setup item.
- Improved Power Button Menu:
 - When the [ESC] key is pressed in the power button recovery menu, the BIOS turns on the SPI lock by GPIO, which globally resets the system for normal POST.
 - o Checks for a Password "F4" in power button menu if either user or supervisor password is set.
 - o Fixed an issue where the power button override invoked the power button menu in the next boot.
 - Removed the jumper recovery message, "Please turn off power and reinstall the BIOS Security Jumper in Normal (1-2) or Lockdown (2-3) position".
 - Added message, "If BIOS Recovery was invoked by BIOS security jumper," before "restore the BIOS Security Jumper in Normal (1-2) or Lockdown (2-3) position".
- Fixed an issue where Pin12: DirectApp Launch didn't work.
- Changed the default pin8 as SMBAlert and grayed out.
- Changed the default pins 13-16 to I2C.
- Changed the default high speed custom solutions header item: Added pin7 option to GPI035 and grayed out.
- Changed the default high speed customer solutions header item: Added pin8 option to GPIO38 and grayed out.
- Removed the NFC connection from the GPIO options.
- Fixed an issue where Linux couldn't see the GPIO controller.
- Update Visual BIOS to 2.2.20 from 2.2.17.
- Hotfix to remove download driver and automatic BIOS update feature.

BIOS Version 0028 - MYBDWi5v.86A.0028.2016.0303.1830

About This Release:

- Date: March 3, 2016
- ME Firmware: 10.0.47.1006
- TXT ACM revision: 1.2
- RST RAID: v14.5.0.2241
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.17
- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1039 UEFI Driver: 5.5.1033

- Fixed issue where Single Max Turbo Rate option could be set when User Access is set to View Only.
- Fixed issue where Toshiba x2 NVME THNSNN256GSX7 SSD would not boot.
- Fixed issue with PXE security and secure boot.

BIOS Version 0027 - MYBDWi5v.86A.0027.2015.1207.1917

About This Release:

- Date: December 7, 2015
- ME Firmware: 10.0.47.1006
- TXT ACM revision: 1.2
- RST RAID: v14.5.0.2241
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.17
- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1039 UEFI Driver: 5.5.1033

New Fixes/Features:

- Updated Intel® ME firmware to version 10.0.47.1006.
- Fixed issue where Windows installation fails with PXE.
- Fixed issue with headless AMT KVM.

BIOS Version 0026 - MYBDWi5v.86A.0026.2015.0820.1501

About This Release:

- Date: August 20, 2015
- ME Firmware: 10.0.45.1024
- TXT ACM revision: 1.2
- RST RAID: v14.5.0.2241
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.17
- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1039 UEFI Driver: 5.5.1033

New Fixes/Features:

- Updated BIOS security features.
- Fixed issue where external Bluetooth devices fail with Windows HLK testing.
- Fixed issue where system does not wake up from S5 using USB devices when BIOS option for Wake on LAN from S4/S5 is set to Stay Off.
- Fixed issue if Intel® Dynamic Power Technology is set to Off, the system can still enter into C7.
- Updated VBIOS to version 1039 and GOP to version 1033.
- Updated Intel ME firmware to 10.0.45.1024.
- Updated processor support.
- Updated RAID Option ROM to version 14.5.0.2241.
- Fixed issue where USB mouse and keyboard do not work as expected in BIOS setup.

- Fixed issue where the Ctrl + I hot key to access RAID configuration does not work.
 - Updated Visual BIOS to version 2.2.17. Fixes include:
 - Refactored graphics resolution algorithm to find closest supported resolution to 1024x768. This should correct scaling issues with 4K monitors.
 - Removed unused assets from Performance and Mainstream themes to reduce the overall size of Visual BIOS. Size savings should be around 300KB.
- Fixed issue where flat panel is not displayed during security recovery/power button menu.
- Added NVMe information on the SATA page in BIOS Setup.
- Updated BIOS to hide Single Max Turbo Ratio if Intel Turbo Boot Technology is disabled.
- Fixed issue where a user with limited access can still modify certain BIOS settings.
- Fixed issued where BIOS password prompts are not suppressed in Config Mode.
- Fixed SMBIOS Type 9 issue the Current Usage always shows In Use when an M.2 device is not installed.
- Fixed issue where SMBIOS type 8 information is not correct.
- Removed SMBIOS type 25, 26, 27, 28, 29, 34, 35, 36, 39 data that affects 3rd party tools.
- Added "Fanless" as an option for Fan Control Mode.
- Added support for Windows Recovery Environment (Windows RE) by pressing the F5 function key.

BIOS Version 0024 - MYBDWi5v.86A.0024.2015.0504.1120

About This Release:

- Date: May 4, 2015
- ME Firmware: 10.0.38.1000
- TXT ACM revision: 1.2
- RST RAID: 13.5.0.2164
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.16
- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1038 UEFI Driver: 5.5.1032

New Fixes/Features:

- 1. Added customizable options in Intel® Integrator Toolkit on the Primary Power Settings menu.
- 2. Fixed issue where SMBIOS system manufacturer and system model are incorrect in MSINFO32 and other applications.

BIOS Version 0022 - MYBDWi5v.86A.0022.2015.0304.2224

About This Release:

- Date: March 4, 2015
- ME Firmware: 10.0.38.1000
- TXT ACM revision: 1.2
- RST RAID: 13.5.0.2164
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.16

- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1038 UEFI Driver: 5.5.1032

- Added BIOS option on the USB Configuration page to enable or disable xHCI Mode.
- Updated processor support.
- Updated GOP to version 1032 and vBIOS to version 1038.
- Fixed issue with Power Sense and GPIO Lock Down default values when updating BIOS.
- Updated Visual BIOS version to 2.2.16. Fixes include: o Fixed issue in Download Drivers feature where certain drivers were not visible if multiple attachments exist in the same record.
 - o Fixed issue in Download Drivers feature where incorrect drivers would display if product was not found in database.
 - Fixed issue in Performance page that prevented additional workspaces from showing up (i.e. Memory Timings, etc.)
- Updated Intel® ME firmware to version 10.0.38.1000.
- Fixed issue with enabling and disabling VT and VT-d.
- Improved SMBIOS information for Onboard Devices.
- Removed item PCI latency Timer from BIOS Setup.
- Changed BIOS setting name Graphics Max Multiplier to Graphics Turbo Ratio.
- Fixed issue where USB S4/S5 power can't be hidden and disabled after Deep S4/S5 is set to Enabled.
- Fixed issue where the iSCSI driver does not accept "CHAP Name" to <iscsi> and "CHAP Secret" to 12 "1" or 12 "a".

BIOS Version 0018 - MYBDWi5v.86A.0018.2015.0128.1212

About This Release:

- Date: January 28, 2015
- ME Firmware: 10.0.30.1072
- TXT ACM revision: 1.2
- RST RAID: 13.5.0.2164
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.14
- PXE ROM : 1.5.55
 - Integrated Graphics Option ROM: Build 1035 UEFI Driver: 5.5.1031

New Fixes/Features:

- Changed IGD Minimum Memory default to 64MB
- Changed default year to 2015.
- Updated NFC behavior: when NFC is enabled in BIOS, GPIO Lockdown is disabled and greyed out.
- Fixed issue with null User Password.

BIOS Version 0015 - MYBDWi5v.86A.0015.2015.0117.1008

About This Release:

• Date: January 17, 2015

- ME Firmware: 10.0.30.1072
- TXT ACM revision: 1.2
- RST RAID: 13.5.0.2164
- iSCSI boot ROM : v3.0.34
- Visual BIOS: 2.2.14
- PXE ROM : 1.5.55
- Integrated Graphics Option ROM: Build 1035 UEFI Driver: 5.5.1031

• Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries. Copyright (c) 2015 Intel Corporation.