



Product Change Notification

107139 - 01

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: apacgccb@intel.com

Europe Email: eccb@intel.com

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2007. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <http://www.intel.com/intel/legal/tmusage2.htm>.



Product Change Notification

Change Notification #: 107139 - 01
Change Title: SR1530CL, PCN 107139-01, Product Material, Board Upgrade and System Improvements, Reason for Revision: Adding riser-card change to this system ECO
Date of Publication: January 05, 2007

Key Characteristics of the Change:

Product Material

Forecasted Key Milestones:

Date Customer Must be Ready to Receive Post-Conversion Material:	Feb 01, 2007
---	--------------

Description of Change to the Customer:

Reason for Revision: Adding riser-card change to this system ECO

System Server Board changes:

- The Intel(R) Server Board S5000VCL software is being updated to BIOS production 70, BMC 56 and FRU/SDR 14. The S5000VCL board video stepping change to replace EOL part, remove temp sensor at location U1A4. Adding diagnostic Post LED's.
- Adding EFUP label to meet Chinese Restriction of Hazardous Substance (CROHS) requirements.
- All boards with Lithium batteries must now contain a Lithium Perchlorate Notification sheet as per California environmental regulatory requirements. This is a documentation addition.

Chassis changes:

- System blower assembly screws being replaced with grommets to reduce vibration coming from the blowers.
- A change to the CD ROM Bracket to improve installation
- Studs being added to outside of the chassis to support High End Rail

System updates:

- Updating the system resource CD and adding 3rd party software CD
- The combo riser-card is changing from D59993-301 to D59993-302 to change resistor value to improve marginality

Customer Impact of Change and Recommended Action:

Intel anticipates no customer impact.

Products Affected / Intel Ordering Codes:

Pre Change Product Code	Pre Change MM#	Pre Change TA	Post Change MM#	Post Change TA
SR1530CL	887863	D64476-002	888004	D64476-003
SR1530CLNA	887864	D64476-002	888070	D64476-003
AHJPCIRISER	884620	D65719-001	884620	D65719-002

Reference Documents / Attachments:

Document:

Location #:

PCN Revision History:

Date of Revision:

December 22, 2006

January 5, 2007

Revision Number:

00

01

Reason:

Originally Published PCN

Adding riser-card change to this system ECO