

Intel® Modular Server System MFSYS25 Unified Firmware Update Package Contents Matrix

This matrix contains the contents of all Unified Firmware Update (UFU) software packages made available for the MFSYS25 system.

UFU Contents	CMM GUI	BIOS	BMC	SAS FW	SAS Option ROM	EBF	Storage IOP	Storage Expander	Storage Redboot	ESM Boot Code	ESM FW	Fan Op Code	Fan Boot Block
P1.0	1.0.100.10012007.7372	SB5000.86B.10.00.0030	13.8	1.20.00.00	6.14.00.00	1.2	2.91.140.1	1.02.140.81	1.00.140.52	1.0.0.6	1.0.0.25	1.1	1.2
P2.0	1.1.100.10302007.8260	SB5000.86B.10.00.0032	1.22.2	1.20.00.00	6.14.00.00	1.2	2.91.140.11	1.02.140.81	1.00.140.52	1.0.0.6	1.0.0.25	1.1	1.2
P2.0.5	1.1.100.11132007.8633	SB5000.86B.10.00.0032	1.25.1	1.20.00.00	6.14.00.00	1.2	2.91.140.11	1.02.140.81	1.00.140.52	1.0.0.6	1.0.0.25	1.1	1.2
P2.0.7	1.2.100.01242008.9431	SB5000.86B.10.00.0035	1.27.1	1.20.00.00	6.14.00.00	1.23	2.91.140.11	1.02.140.81	1.00.140.52	1.0.0.6	1.0.0.25	1.1	1.2
P2.2.2¹	1.3.100.20080516.11151	SB5000.86B.10.00.0043	1.30.3	1.23.07.00	6.18.01.00	1.24	2.91.140.45	1.03.0140.01	1.01.0140.08	1.0.0.6	1.0.0.25	1.1	1.2
P2.2.3²	1.3.100.20080527.11328	SB5000.86B.10.00.0043	1.30.3	1.23.07.00	6.18.01.00	1.24	2.91.140.45	1.03.0140.01	1.01.0140.08	1.0.0.6	1.0.0.25	1.1	1.2
P2.3.1³	2.4.100.20080610.11578	SB5000.86B.10.00.0043	1.30.3	1.23.07.00	6.18.01.00	1.24	2.91.140.50	1.030140.02	1.01.0140.08	1.0.0.6	1.0.0.27	1.1	1.2
P2.3.2⁴	2.4.100.20080910.13232	SB5000.86B.10.00.0047	1.30.3	1.23.07.00	6.18.01.00	1.24	2.91.140.50	1.030140.02	1.01.0140.08	1.0.0.6	1.0.0.27	1.1	1.2
P2.3.3⁴	2.4.100.20080923.13458	SB5000.86B.10.00.0048	1.30.3	1.23.07.00	6.18.01.00	1.24	2.91.140.50	1.030140.02	1.01.0140.08	1.0.0.6	1.0.0.27	1.1	1.2
P2.3.5⁵	2.4.100.20081010.13743	SB5000.86B.10.10.0048	1.30.3	1.23.07.00	6.18.01.00	1.24	2.91.140.50	1.030140.02	1.01.0140.08	1.0.0.6	1.0.0.27	1.1	1.2

Text in Blue indicates a change from the previously released Intel® Modular Server System MFSYS25 Unified Firmware Update Package.

1The system must be at firmware level P2.07 prior to starting the P2.2.2 update. **2**The system must be at firmware level P2.07 or P2.2.2 prior to starting the P2.2.3 update. **3**The system must be at firmware level P2.07, P2.2.2 or P2.2.3 prior to starting the P2.3.1 update. **4**P2.3.2 and P2.3.3 are no longer supported and should not be used. Upgrade immediately to P2.3.5. **5**The system must be at firmware level P2.3.1, P2.3.2, or P2.3.3 prior to starting the P2.3.5 update. This release supports rollback to firmware level P2.3.1.