



BIOS Update Release Notes

PRODUCTS: DX79SI, DX79SR, DX79TO (Standard BIOS)

BIOS Version 0650 - SIX7910J.86A.0650.2014.0307.0138

About This Release:

- Date:
April 11, 2014
- ME Firmware:
7.1.60.1193
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.5.0.1005
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Fixed issue where system always prompts for a BitLocker recovery key after a reboot.

BIOS Version 0594 - SIX7910J.86A.0594.2013.0806.2241

About This Release:

- Date:
August 7, 2013
- ME Firmware:
7.1.60.1193
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.5.0.1005
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Fixed fan speed control issue after system wakes from sleep.

BIOS Version - SIX7910J.86A.0590.2013.0717.2343

About This Release:

- Date:
July 17, 2013
- ME Firmware:
7.1.60.1193
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.5.0.1005
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

*Other names and brands may be claimed as the property of others.

- Fixed issue where PCIe Slot 2 does not work with certain PCIe x1 add-in cards.
- Fixed issue with Wake-on-LAN in Linux*.
- Fixed issue where certain add-in graphics cards are not properly detected.
- Updated processor support.
- Improved compatibility with the latest graphics cards.

BIOS Version 0559 - SIX7910J.86A.0559.2013.0305.2337

About This Release:

- Date:
March 5, 2013
- ME Firmware:
7.1.60.1193
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.5.0.1005
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Fixed OA3 and OA2.1 conflict issue.

BIOS Version 0553 - SIX7910J.86A.0553.2012.1027.1042

About This Release:

- Date:
October 27, 2012
- ME Firmware:
7.1.60.1193
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.5.0.1005
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Updated Intel® ME 7 firmware to version 7.1.60.1193.
- Updated SATA RAID Option ROM to version 3.5.0.1005.
- Fixed issue where certain 4-port LAN card does not work.
- Fixed issue with thermal error beep.

BIOS Version 0537 - SIX7910J.86A.0537.2012.0723.1217

About This Release:

- Date:
July 23, 2012
- ME Firmware:
7.1.50.1172
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.2.0.1022
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

*Other names and brands may be claimed as the property of others.

New Fixes/Features:

- Updated SATA RAID Option ROM to version 3.2.0.1022.
- Enabled recovery update capability between EDK1 and EDK2.

BIOS Version 0525 - SIX7910J.86A.0525.2012.0709.1221

About This Release:

- Date:
July 9, 2012
- ME Firmware:
7.1.50.1172
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.1.0.2101
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Removed warning when processor fan is not connected.
- Fixed issue where error is reported in the Event Log for the XHCI controller.
- Fixed issue where USB 3.0 fails when USB Optimization is enabled.
- Updated Intel® ME firmware to version 7.1.50.1172.

BIOS Version 0515 - SIX7910J.86A.0515.2012.0523.1049

About This Release:

- Date:
May 23, 2012
- ME Firmware:
7.1.21.1134
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.1.0.2101
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Enabled flash update capability from current Baseline to new EDKII Baseline BIOS.
- Fixed issue with Device Manager yellow bang on any off-board XHCI controller in the system.
- Enabled PCH SATA hot-plug support.
- Updated processor support.

BIOS Version 0494 - SIX7910J.86A.0494.2012.0424.1039

About This Release:

- Date:
April 24, 2012
- ME Firmware:
7.1.21.1134
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.1.0.2101

*Other names and brands may be claimed as the property of others.

- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Reduced S3 resume time.
- Fixed issue with power button recovery where video does not display during Main firmware update.
- Fixed false event from Flash Update Status Indicators.
- Added memory beep support for unsupported DIMMs.
- Added support for mismatched XMP DIMMs.
- Added ECC support.
- Updated SATA RAID Option ROM to version 3.1.0.2101.
- Improved compatibility with add-in RAID cards.

BIOS Version 0460 - SIX7910J.86A.0460.2012.0327.1627

About This Release:

- Date:
March 27, 2012
- ME Firmware:
7.1.21.1134
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.0.1.1370
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Updated processor support.
- Fixed issue where system hangs at POST code EB with SATA in IDE mode and certain 4-port NIC in the system.
- Updated Setup behavior between Auto Setup Entry and Fast Boot USB Optimization.
- Updated to show clear user password prompt when user password is installed.
- Fixed issue with yellow bang on second identical graphics card.
- Fixed issue where operating system cannot be installed in RAID mode when UEFI is enabled.

BIOS Version 0453 - SIX7910J.86A.0453.2012.0315.1212

About This Release:

- Date:
March 15, 2012
- ME Firmware:
7.1.21.1134
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.0.1.1370
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Enabled flash update status indicator.

*Other names and brands may be claimed as the property of others.

- Added Power Button menu.
- Added workaround for DIMMs with invalid XMP profile.
- Enabled PEI Authentication.
- Fixed issue where PCI Subsystem Vendor ID and Subsystem ID were not programmed on value-add devices.
- Added XMP support for 3T command rate.
- Fixed issue where system hangs during cycling.
- Removed keyboard not found event.
- Fixed issue where BIOS reported invalid tRFC for XMP 1.3 DIMMs.
- Increased tRFC to 400.
- Added beep for all memory error.
- Fixed issue where two identical video cards are not listed in BIOS Setup.
- Updated processor support.
- Added JKT RC package R1.0.013 changes.
- Updated code to change Fan Speed Control setup option to "Manual Duty Cycle (%)" when Control Mode is set to Manual.

BIOS Version 0430 - SIX7910J.86A.0430.2012.0213.1635

About This Release:

- Date:
February 13, 2012
- ME Firmware:
7.1.21.1134
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.0.1.1370
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Fixed issue where error shows in Device Manager* for USB 3.0 front panel controller.
- Added XMP 1.3 support.

BIOS Version 0424 - SIX7910J.86A.0424.2012.0127.1620

About This Release:

- Date:
January 27, 2012
- ME Firmware:
7.1.21.1134
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.0.1.1370
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Fixed issue with BIOS Recovery support.
- Added keyboard controller reset workaround.
- Fixed issue where internal PLL override option does not work correctly.
- Fixed issue where non-XE CPU will not run in Turbo speed.

*Other names and brands may be claimed as the property of others.

- Updated processor support.
- Fixed issue with manual mode fan control.
- Updated FSC Stack.
- Updated GUID defined section Security check.
- Disabled ACPI OS native PCI Express support when certain graphics card is installed in the system.
- Improved memory stability at higher memory speed.
- Updated Turbo Ratio maximum limit in BIOS Setup.
- Updated Turbo related options range in BIOS Setup.
- Improved BIOS watchdog timer support for Intel® Extreme Tuning Utility.
- Updated PEG slot to support PCIe* Gen3.
- Updated Setup options for Overclocking Assistance and Turbo Ratio.
- Added support for Primary/Secondary Temperature Input parameters to controller.
- Fixed issue where some USB optical drives are not detected.
- Fixed random hang at boot on systems with TPM present.
- Fixed POST hang at boot with cursor at top-left of screen with certain option ROM configurations.
- Updated SATA RAID option ROM to version 1370.

BIOS Update 0380 - SIX7910J.86A.0380.2011.1128.1456
--

About This Release:

- Date:
November 28, 2011
- ME Firmware:
7.1.21.1134
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.0.0.1184
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Added boot time enhancement.
- Fixed issue where S3 resume failed when Runtime Turbo Ratio is enabled.
- Updated SMBIOS Type 0 for UEFI Spec support flag.
- Improved USB keyboard handling in MS-DOS.
- Added Power Button Recovery support.
- Set CPU Voltage to 1.25V for Host Clock Multiplier 1.25x and 1.66x.
- Improved BIOS Extreme Tuning Utility support.
- Fixed issue where disabling the S4/S5 Wake-on-LAN causes the system not able to wake-on-LAN in S3.
- Fixed Extreme Tuning Utility to report PCH Temperature.
- Updated FSC related options for Intel® Integrator Toolkit.
- Fixed issue where XMP-2133 timing is misread.
- Updated processor support.
- Fixed the system text display issue after S4 cycle.

About This Release:

- Date:
October 19, 2011
- ME Firmware:
7.1.21.1134
- SATA RAID Option ROM:
Intel(R) RAID for SATA - v3.0.0.1184
- PXE Boot Agent:
Intel(R) Boot Agent GE v1.3.72
IBA GE Slot 0000 v1372 PXE 2.1 Build 089 (WfM 2.0)

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2013 Intel Corporation.