



BIOS Update Release Notes

PRODUCTS: D2500CC (Standard BIOS)

BIOS Version 0040 - CCCDT10N.86A.0040.2014.0520.1400

About This Release:

- Date: May 20, 2014
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Fixed USB printer issue.

BIOS Version 0039 - CCCDT10N.86A.0039.2013.0425.1620

About This Release:

- Date: April 25, 2013
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Added support for ErP.

BIOS Version 0038 - CCCDT10N.86A.0038.2013.0128.0940

About This Release:

- Date: January 28, 2013
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue where system cannot enter standby/hibernation mode in Windows XP*.

BIOS Version 0037 - CCCDT10N.86A.0037.2012.1217.1723

About This Release:

- Date: December 17, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Added BIOS setup options for LVDS timing.

*Other names and brands may be claimed as the property of others.

BIOS Version 0036 - CCCDT10N.86A.0036.2012.1114.1524

About This Release:

- Date: November 14, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1083
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue where some BIOS setup items do not appear.
- Added EuroStar* support.

BIOS Version 0034 - CCCDT10N.86A.0034.2012.0612.1520

About This Release:

- Date: June 12, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1071
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue with Fast Boot so USB devices still work under DOS if USB Optimization is enabled.
- Fixed security check issue.

BIOS Version 0033 - CCCDT10N.86A.0033.2012.0511.1700

About This Release:

- Date: May 11, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1071
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue where Shift + Right arrow does not work in edit.com under DOS.
- Fixed issue where system hangs at POST code 5Ah when SATA-to-Compact Flash adapter without media is connected.
- Fixed issue with LAN behavior under DOS.
- Fixed Linux* shutdown issue.

BIOS Version 0032 - CCCDT10N.86A.0032.2012.0323.1510

About This Release:

- Date: March 23, 2012
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1071
- PXE: v1.3.65

New Fixes/Features:

- Fixed issue where only 2.99GB usable memory is reported if system is populated with 4GB memory.
- Updated vBIOS to version 1071.

- Hid FSC CPU/Rear Fan minimal duty cycle if control mode is set to manual and changed the default values from 50/50 to 20/30.
- Fixed issue where the panel power sequence control items in BIOS do not work properly.
- Updated to skip pressing enter key after warning message for following events: CMOS battery failure/ CMOS Checksum Error/ system date/time.

BIOS Version 0030 - CCCDT10N.86A.0030.2011.1227.1123

About This Release:

- Date: December 27, 2011
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1053
- PXE: v1.3.65

New Fixes/Features:

- Updated VBIOS to version 1053.
- Fixed issue where VBIOS cannot get Payload EDID.
- Fixed issue where PS/2 port does not work during POST or in BIOS setup.
- Fixed issue where the POST hotkey shows incorrectly if the logo is set to a 320x200 image.
- Fixed issue where Type 01 of Pre-Defined EDID in Setup is incorrect.
- Hid swap mode question in Setup if LVDS interface type is set to single channel.
- Fixed issue where down-arrow key of the keyboard doesn't work properly under DOS.
- Fixed issue where certain USB flash drive is not bootable.
- Fixed issue where an alert is not triggered when fan is stopped manually.
- Fixed issue where a 1366x768 panel is too dark at the minimal brightness level.
- Fixed issue where system hangs during S4 resume if populated with 2GB memory and TPM is enabled.
- Fixed issue where integrated graphics will not be hidden in Setup if a PCI graphics card is plugged into a PCI riser card on slot 2.
- Fixed issue in Intel® Desktop Utilities where sensor threshold settings do not persist.
- Updated the color depth setup option for LVDS.
- Improved the time from power on to splash screen.
- Added support for USB optical drives to the F7 BIOS update method.
- Added support for Microsoft* OEM Activation 3.0.
- Fixed issue where 18.5" LCD display abnormal in recovery mode.
- Fixed issue where Windows* Resume Loader will occur during resume S4 if set to "Power on-PXE boot".
- Fixed issue where the panel will flicker once when adjusting screen brightness to dimmest in the operating system.
- Fixed issue where TPM cannot be disabled in the operating system.
- Fixed issue where BIOS cannot be updated via SATA optical drive in F7 BIOS flash update mode.

*Other names and brands may be claimed as the property of others.

- Fixed issue where the system will hang at POST code EB if there is a DVD disc in a USB optical drive.
- Fixed issue where FSC variable gets overwritten to original defaults on every boot.

BIOS Version 0014 - CCCDT10N.86A.0014.2011.0915.0927

About This Release:

- Date: September 14, 2011
- Integrated Graphics Option ROM: Created by BMP 2.67e
- vBIOS: 1043
- PXE: v1.3.65

New Fixes/Features:

- Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries.
Copyright (c) 2012 Intel Corporation.