

Information in this document is provided in connection with Intel products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Should you have any issues with the timeline or content of this change, please contact the Intel Representative(s) for your geographic location listed below. No response from customers will be deemed as acceptance of the change and the change will be implemented pursuant to the key milestones set forth in this attached PCN.

Americas Contact: asmo.pcn@intel.com

Asia Pacific Contact: <a href="mailto:apacgccb@intel.com">apacgccb@intel.com</a>

Europe Email: <a href="mailto:eccb@intel.com">eccb@intel.com</a>

Japan Email: jccb.ijkk@intel.com

Copyright © Intel Corporation 2006. Other names and brands may be claimed as the property of others.

Celeron, Centrino, Intel, the Intel logo, Intel Core, Intel NetBurst, Intel NetMerge, Intel NetStructure, Intel SingleDriver, Intel SpeedStep, Intel StrataFlash, Intel Viiv, Intel XScale, Itanium, MMX, Paragon, PDCharm, Pentium, and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

Learn how to use Intel Trade Marks and Brands correctly at <a href="http://www.intel.com/intel/legal/tmusage2.htm">http://www.intel.com/intel/legal/tmusage2.htm</a>.



# **Product Change Notification**

Change Notification #:	106892 - 00
Change Title:	Intel(R) Blade Server Ethernet Switch
	Module IXM5414E, PCN 106892-00, Product
	Discontinuance, Product Discontinuance
	Announcement
Date of Publication:	October 24, 2006

#### Key Characteristics of the Change:

Product Discontinuance

#### **Forecasted Key Milestones:**

Last Product Discontinuance Order Date:	Nov 17, 2006
Last Product Discontinuance Shipment Date:	Dec 29, 2006

#### **Description of Change to the Customer:**

Intel will stop selling the Blade Server Ethernet Switch Module IXM5414E once existing inventories are depleted.

At this point Intel will no longer manufacture the Blade Server Ethernet Switch Module IXM5414E. We encourage customers to continue purchasing the Blade Server Ethernet Switch Module IXM5414E while supplies last.

Intel has developed and is shipping two replacement GbE switch modules, designated Blade Server Ethernet Switch Module SBCEGBESW1 (MM# 880176) and Blade Server Ethernet Switch Module SBCEGBESW10 (MM# 880175).

#### **Customer Impact of Change and Recommended Action:**

Please determine your remaining demand for these products and place your last product discontinuance orders in accordance with the key milestones in the PCN.

Intel encourages customers to acquire appropriate models and quantities of the replacement switches for test and evaluation prior to the Product Discontinuance Shipment Date of the IXM5414E switch.

#### **Products Affected / Intel Ordering Codes:**

Product Name	Product Code	Pre Change Affected MM#
IXM5414E	IXM5414E	883795

### **Reference Documents / Attachments:**

**Document:** 

Location #:

## **PCN Revision History:**

**Date of Revision:** October 24, 2006 **Revision Number:** 00

**Reason:** Originally Published PCN