

#### **Server OS Testing Services**

#### **Enterprise Platforms and Services Division**

# Intel<sup>®</sup> Server Platform SR6850HW4M & SR4850HW4M

# **Server Test Submission (STS) Report**

For the Microsoft® Windows® Logo Program (WLP)

#### **Rev 1.2**

#### May 31, 2006

This report describes the Intel® Server Platform SR6850HW4M & SR4850HW4M Windows\* Logo Program test run conducted by Intel Enterprise Platforms and Services Division (EPSD).

#### **Purpose of this WLP Submission:**

System Update submission for the Intel® Server Platform SR6850HW4M & SR4850HW4M.

Submission Type:	Reason for test run	Check one
Update Submission	Update for Potomac Processor Support	V

# **Revision History and Disclaimers**

Revision History			
Revision	Date	Comments	
1.0	5/17/2006	STS Report for WLP Windows 2003 Enterprise Edition First-Time Submission for Intel® Server Platform SR6850HW4M & SR4850HW4M with 3.00GHz 2x2MB Cache [Paxville] Processors on P08 BIOS with 64GB memory support	
1.1	5/18.2006	STS Report for WLP Windows 2003 Enterprise Edition Update Submission for Intel® Server Platform SR6850HW4M & SR4850HW4M with 3.66GHz 1MB Cache [Cranford] Processors on P08 BIOS with 64GB memory support	
1.2	5/31/2006	STS Report for WLP Windows 2003 Enterprise Edition Update Submission for Intel® Server Platform SR6850HW4M & SR4850HW4M with 3.33GHz 8MB Cache [Potomac]] Processors on P08 BIOS with 64GB memory support	

THIS TEST REPORT IS PROVIDED "AS IS" WITH NO WARRANTIES WHATSOEVER, INCLUDING ANY WARRANTY OF MERCHANTABILITY, NONINFRINGEMENT FITNESS FOR ANY PARTICULAR PURPOSE, OR ANY WARRANTY OTHERWISE ARISING OUT OF ANY PROPOSAL, SPECIFICATION OR SAMPLE.

Information in this document is provided in connection with Intel® products. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document or by the sale of Intel products. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel products are not intended for use in medical, life saving, or life sustaining applications.

Intel retains the right to make changes to its test specifications at any time, without notice.

The hardware vendor remains solely responsible for the design, sale and functionality of its product, including any liability arising from product infringement or product warranty.

Intel, Pentium, Itanium and Xeon are trademarks or registered trademarks of Intel Corporation or its subsidiaries in the United States and other countries.

\* Other names and brands may be claimed as the property of others.

Copyright  $\ensuremath{@}$  2003, Intel Corporation. All rights reserved.

# **Contents**

Revision History and Disclaimers 2
Introduction 4
Overview of Contents4
Terms and Definitions
Server Board Submission Information 5
Intel Server Board Submission Report: Completion of WLP5
Submission Information
Submission ID5
Submission Type5
Update Type (Update Hardware and Drivers Test Submission ONLY)5
Update Type Detail (Update Hardware and Drivers Test Submission ONLY)5
Product Category5
Product Detail5
General Product Information
Testing Matrix (optional)6
Characterization (optional)6
Server Board Configuration Information7
Processor7
System Memory 7
Power Management7
BIOS7
Firmware7
Bus Types 8
Integrated Components8
Onboard Integrated Devices and Drivers8
Product Data for HCL: Completion of WLP9
Product Data9
Hardware Compatibility Tests10
Errata and Contingencies11
Intel® Server Platform SR6850HW4M & SR4850HW4M Submission Readme File 11
Testing Exceptions for Intel® Server Platform SR6850HW4M & SR4850HW4M Windows* Serve 2003
Additional Information
Appendix A – Submission History 14

# Introduction

This report provides an overview of the testing conducted on the Intel\$ Server Platform SR6850HW4MM & SR4850HW4MM server board by Intel EPSD and provides details about this testing run.

#### **Overview of Contents**

Section	Content	
Introduction	Brief descriptions of the sections in the report. Table listing terms and definitions.	
Server Product Submission Information	Submission information, ID # and final server board configuration upon completion of WLP including HW, Driver version, BIOS version, and Board AA number	
HCT	All HCT's used during testing	
Errata and Contingencies	All Microsoft* errata or contingencies used during testing	

#### **Terms and Definitions**

Term	Definitions	
EPSD	Enterprise Platforms and Services Division	
HCL	Windows Hardware Compatibility List. You can view the HCL at: <a href="http://www.microsoft.com/whdc/hcl/search.mspx">http://www.microsoft.com/whdc/hcl/search.mspx</a>	
нст	Hardware Compatibility Tests. For latest Server HCTs visit: <a href="http://www.microsoft.com/whdc/hwtest/system/default.mspx">http://www.microsoft.com/whdc/hwtest/system/default.mspx</a>	
STS	Server Test Submission Report published by EPSD	
WHDC	Windows* Hardware and Driver Central. Provides technical information, development and testing kits, newsletters and support information. <a href="http://www.microsoft.com/whdc/default.mspx">http://www.microsoft.com/whdc/default.mspx</a>	
WHOS	Windows Hardware Online Service – Secure online web site used to submit products for logo qualification and review submission history. <a href="https://winqual.microsoft.com/">https://winqual.microsoft.com/</a>	
WHQL	Windows* Hardware Qualification Lab. For more information visit the WHDC home page at: <a href="http://www.microsoft.com/whdc/default.mspx">http://www.microsoft.com/whdc/default.mspx</a>	
WLP	Windows Logo Program. For further information see: <a href="http://www.microsoft.com/whdc/winlogo/default.mspx">http://www.microsoft.com/whdc/winlogo/default.mspx</a>	
WTS	Workstation Test Submission Report published by EPSD	

# **Server Board Submission Information**

#### Intel Server Board Submission Report: Completion of WLP

Data in this section reflects system submission information at the time of WLP submission.

#### **Submission Information**

Submission ID		
Submission ID / Master ID	1129806	
Previously logo'd Submission ID / Master ID	N/A	
Submission Type		
	Check Submission Type	Comments
First-Time Hardware and Driver Test Submission		
System Update		Potomac with P08 BIOS and 64GB memory support
Update Type (Update Hardwa	re and Drivers Test Submission C	DNLY)
	Check Update Type	Comments
Hardware (Firmware) Update		
System Update	<b>V</b>	
Previously Logo'd Operating System		
Update Type Detail (Update H	lardware and Drivers Test Submis	ssion ONLY)
	Check Update Type	Comments
New CPU Speeds	$\overline{\checkmark}$	
Motherboard Updates		
BIOS/Firmware Updates		
OS Updates		
Product Category		
Hardware Category	PC System or Server	
Operating System Selected	Windows Server 2003 Enterprise Edition SP1 (x86 and EM64T), Windows Server 2003 Standard Edition and Windows Server 2003 Web Edition	

November 15, 2005  $5^{\perp}$ 

#### Intel® Server Platform SR6850HW4M & SR4850HW4M

Product Detail				
General Product Information				
Equipment Type	Server			
Primary Target Market	Business/Corporate			
Compliance	All applicable requirements			
Testing Matrix (optional)	Testing Matrix (optional)			
	Check Tested	Comments		
PAE_Tested	$\square$	Supports 4GB or more of memory		
Characterization (optional)	Characterization (optional)			
	Check appropriate options	Comments		
Web Server	$\square$			
SQL Database Server				
File Server	$\square$			

## **Server Board Configuration Information**

Processor		
Quantity	4	
Front Side Bus Speed	800MHz	
Family/Model	Intel® Xeon™ MP Hyper-Threading Technology	
Speed	3.33GHz 8MB Cache	
System Memory		
Amount Installed	64 GB	
Memory Type	ECC DDR2 400 SDRAM	
Power Management		
ACPI Sleep States (S1, S2, S3, S4)	S1 & S4	
Server Board Product		
System uses logo'd motherboard	NO (Server boards are <u>NOT</u> eligible for logo under the Microsoft* Motherboard logo program)	
Board AA #/Fab	I/O Board D22177-552, Memory Board C53302-501, SCSI Board D21460-251, Front Panel C61338-200, Intel Management Module D23013-452	
Board Manufacturer	Intel Corporation	
Board Model	Intel® Server Platform SR6850HW4M & SR4850HW4M	
Northbridge* Chipset Manufacturer	Intel	
Northbridge Chipset Model	E8501	
Southbridge* Chipset Manufacturer	Intel	
Southbridge Chipset Model	81801EB	
BIOS		
BIOS Manufacturer	Intel	
BIOS Version	SHW40.86B.P.08.0048	
BIOS Date	3/23/2006	
BIOS URL (For Updates)	http://support.intel.com/support/motherboards/server/	
Firmware		
BMC Version	50	
HSC Version	07	
FRU/SDR Version	34	
Firmware URL (For Updates)	http://support.intel.com/support/motherboards/server/	

November 15, 2005  $7^{\perp}$ 

Bus Types			
	Check all that Apply		Check all that Apply
PS/2		AGP*	
1394		PCCard* (16-bit)	
CF (Compact Flash)		CardBus* (32-bit)	
PCI-X	$\square$	USB	$\square$
Mini-PCI		USB 2.0	$\square$
AMR		InfiniBand*	
ACR		Bluetooth*	
COM (Serial)		PCI-E	$\square$
Integrated Components			
	Check all that Apply		Check all that Apply
Audio		Display	
IDE		Networking	
SCSI		RAID	$\square$
Modem		Bluetooth*	
Fibre Channel Expansion Module	Ø	SATA	V

## **Onboard Integrated Devices and Drivers**

Data in this section reflects system configuration at the time of WLP submission. The latest drivers for the Intel® Server Platform SR6850HW4M & SR4850HW4M server board are available for download at:

http://support.intel.com/support/motherboards/server/

Technology	os	Version
LAN Broadcom* BCM5704 NetXtreme* Gigabit	Windows Server 2003 x86	8.48.0.0
Ethernet controller	Windows Server 2003 EM64T	8.48.0.0
SCSI RAID	Windows Server 2003 x86	6.45.2.32
Intel RAID Controller SROMBU42E	Windows Server 2003 EM64T	6.45.3.64
Display ATI* RADEON 7000 Series PCI Video	Windows Server 2003 x86	6.14.10.6553 (8.15)
Controller (with 16 MB of Video Memory)	Windows Server 2003 EM64T	6.14.10.6553 (8.15)
Intel Fibre Channel Expansion Module	Windows Server 2003 x86	9.1.0000.16
Qlogic* ISP2322 FC PCI-X controller	Windows Server 2003 EM64T	9.1.0000.16

### **Product Data for HCL: Completion of WLP**

Data in this section reflects product data for HCL at time of WLP submission.

Product Data			
Product Name	Intel® Server Platform SR6850HW4M & SR4850HW4M		
Supported Platforms			
	Check Tested	Comments	
Windows 2000 Server			
Windows 2000 Advanced Server			
Windows Server 2003, Web Edition	V		
Windows Server 2003, Standard Edition			
Windows Server 2003, Enterprise Edition	Ø		

November 15, 2005  $9^{\perp}$ 

# **Hardware Compatibility Tests**

Microsoft\* Windows Hardware Driver Central Server Testing Home Page: <a href="http://www.microsoft.com/whdc/hwtest/system/default.mspx">http://www.microsoft.com/whdc/hwtest/system/default.mspx</a>.

Please check this website regularly for test kit updates.

Operating Systems	Notes	Hardware Compatibility Tests (HCT)
Windows Server 2003 SP1	HCT 12.1 Test Procedures and Readme files for Windows XP SP2 and Windows Server 2003 SP1	HCT 12.1 (Windows XP SP2 and Windows Server 2003 SP1) Test Kit
	http://www.microsoft.com/whdc/whql/WHQLdwn.mspx	http://www.microsoft.com/whdc/whql/WHQLdwn.mspx

# **Errata and Contingencies**

Microsoft\* System HCT Errata list is available at:

http://www.microsoft.com/whdc/hwtest/search/results.aspx?type=errata&key=system&kit=-1

<b>Operating System</b>	Identification Number	Title
Windows Server 2003	772	LAN Device Wake Up test is not required on network devices in mobile systems, multifunction, broadband, LAN emulation, wireless LAN, server LAN, or bus-powered USB network devices

# Intel® Server Platform SR6850HW4M & SR4850HW4M Submission Readme File

Effective May 1, 2002, the new Microsoft standardized Readme form will be required for all hardware submissions that include any of the following testing exceptions:

- Test failures
- Tests not run
- Missing test logs
- Inconclusive test results

All testing exceptions must be identified with a valid Errata ID, Incident ID, or Contingency ID provided by WHQL. The new Microsoft standardized Readme file is available for download at: <a href="http://download.microsoft.com/download/whistler/install/1.0/w98nt42kmexp/en-us/readme.exe">http://download.microsoft.com/download/whistler/install/1.0/w98nt42kmexp/en-us/readme.exe</a>

November 15, 2005  $11^{\perp}$ 

# Testing Exceptions for Intel® Server Platform SR6850HW4M & SR4850HW4M Windows\* Server 2003

Data in this section reflects product data and test exceptions listed in section 2 of the Intel® Server Platform SR6850HW4M & SR4850HW4M Readme file at time of WLP submission ID 1129806

Operating system (Windows XP, Windows 2000, etc.)	Failure type (Contingency, Errata, Incident)	ID number			
Windows 2003 Enterprise Server 32bit	Errata	772			
Failing test name	LAN Device Wake Up test				
Applicable error message (Type N/A if the error message or failing text is excessive or if there is no text)	LAN Device Wake Up test is not required on network devices in mobile systems, multifunction, broadband, LAN emulation, wireless LAN, server LAN, or bus-powered USB network devices				
Additional information (for example, test system in a multiple system configuration)	The LAN Device Wake test is not required  Multifunction devices  Broadband and WAN devices:  Cable modems  DSL  ISDN  LAN emulation devices  Wireless LAN devices  Server LAN devices:  Multiport NICs  FDDI  ATM  Gigabit and higher Ethernet devices  Bus-powered USB network devices  Network devices in mobile systems  Note: 10/100 single port LAN devices are referenced.				

#### **Additional Information**

Due to Windows\* 2003 Enterprise operating system limitations server systems that support 4GB or more of memory are tested with maximum memory installed for all HCTs except for the ACPI HCTs. Memory is removed in order to bring the total system memory below 4GB to enable Windows\* 2003 Enterprise to go into hibernation. Refer to errata ID: 92 and the AWE Test procedures for more information.

November 15, 2005  $13^{\perp}$ 

# **Appendix A – Submission History**

Microsoft "Designed for Windows" logo submission history for the Intel® Server Platform SR6850HW4M & SR4850HW4M :

Submission ID	Туре	Date	OS Qualified	Processor Speeds	Board Revision	BIOS Version
1123603	First-Time Submission	5/17/2006	Windows Server 2003 - Enterprise - Standard - Web	3.00GHz Intel® Xeon™ MP Hyper-Threading Technology	D22177-552 C53302-501 D21460-25 C61338-200 D23013-452	SHW40.86B.P01.01 .0001
1124618	Update Submission	5/18/2006	Windows Server 2003 - Enterprise - Standard - Web	3.66 GHz Intel® Xeon™ MP Hyper-Threading Technology	D22177-552 C53302-501 D21460-25 C61338-200 D23013-452	SHW40.86B.P01.01 .0001
1129806	Update Submission	5/31/2006	Windows Server 2003 - Enterprise - Standard - Web	3.33 GHz Intel® Xeon™ MP Hyper-Threading Technology	D22177-552 C53302-501 D21460-25 C61338-200 D23013-452	SHW40.86B.P01.01 .0001