

BIOS Update Release Notes

PRODUCTS: DG41KR (Standard BIOS)

BIOS Version 0032 - KRG4110H.86A.0032.2010.0628.1643

About This Release:

- June 28, 2010
- Integrated Graphics Option ROM: Build 1859 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent PXE Base Code (PXE-2.1 build 083)

New Fixes/Features:

• Updated MRC version to V2.81.

BIOS Version 0031 - KRG4110H.86A.0031.2010.0402.1008

About This Release:

- April 2, 2010
- Integrated Graphics Option ROM: Build 1859 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent PXE Base Code (PXE-2.1 build 083)

New Fixes/Features:

- Updated memory voltage setting in setup menu.
- Fixed issue where system hangs when setting SDRAM control to "Manual-User Defined".
- Updated PXE ROM.
- Fixed issue where memory size shows less than 3175 MB available when 4 GB memory is installed.
- Fixed issue where system hangs after flash bios update.
- Fixed issue where passwords show "Not installed" after flash bios update.
- Fixed issue where BIOS allowed a different product BIOS to be flashed.

BIOS Version 0029 - KRG4110H.86A.0029.2009.1218.1746

About This Release:

- December 18, 2009
- Integrated Graphics Option ROM: Build 1859 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent PXE Base Code (PXE-2.1 build 083)

New Fixes/Features:

- Fixed issue where DDR3 memory voltage should start from 1.50V.
- Removed non-reboot Flash method.
- Fixed issue where Supervisor Password and User Password will show "Not installed" in error.

*Other names and brands may be claimed as the property of others.

- Fixed issue where USB front ports do not work in BIOS when setting "USB Ports" to "Enable Rear Only".
- Fixed issue where USB devices will show in the Boot menu of BIOS Setup and in the F10 menu when "USB Boot" is disabled.
- Fixed issue where default option of Chassis Intrusion should be "Log only".
- Fixed issue where system can't access F10/F12 menus after installing a password.
- Updated processor support.
- Implemented Security Phase 2.

BIOS Update 0027 - KRG4110H.86A.0027.2009.1019.2129

About This Release:

- October 19, 2009
- Integrated Graphics Option ROM: Build 1859 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent PXE Base Code (PXE-2.1 build 083)

New Fixes/Features:

- Fixed issue where system hangs at post code "EB" when PCIe x1 video cards installed.
- Fixed issue where USB device can't display in F10 menu after "USB boot" set to disabled in setup menu.
- Removed unsupported setup items in Intel® Integrator Toolkit map file.
- Fixed issue where beep sound keep repeating with postcode "21" after processor heatsink is connected.
- Fixed issue where Processor Thermal Trip error event is not detected by BIOS.
- Implemented support for BIOS downgrade protection.

BIOS Version 0026 - KRG4110H.86A.0026.2009.0923.1822

About This Release:

- September 23, 2009
- Integrated Graphics Option ROM: Build 1859 PC 14.34
- LAN Option ROM: Intel(R) Boot Agent PXE Base Code (PXE-2.1 build 083)

New Fixes/Features:

• Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other

intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries. Copyright (c) 2010 Intel Corporation.