

BIOS Update Release Notes

PRODUCTS: DE3815TYKHE, DE3815TYBE (Standard BIOS)

NOTE: This BIOS update is for Intel NUC Kit DE3815TYHE with the SA number H27002-500 and later and Intel NUC Board DE3815TYBE with the AA number H26998-500 and later.

TYBYT20H.86A.0022.2019.0701.1544 Production BIOS

About This Release:

• Date: July 01, 2019

• ROM Image Checksum: 0x475E

• ME Firmware: 1.1.4.1145v3

• EC Firmware: 4.00

• Memory Reference Code: Based on 0.94

• Integrated Graphics

o Option ROM: Build 1004 PC 14.34

o UEFI Driver: 7.0.1029

• AHCI Code: Based on 5.004 AHCI002

• LAN Option ROM: 2.0.23

• Visual BIOS: 2.2.20

• Supported Flash Devices:

Macronix MX25U6435FM2I-10G 8MB Winbond W25Q64FWSSIG 8MB GIGADEVICE GD25LQ64CVIG 8MB

• Microcode Updates included in .ROM & .BIO Files:

M0C30673326.PDB M0C30678838.PDB M0130673326.PDB M0F3067990C.PDB

New Fixes/Features:

- Fixed Issue: Where USB wake from S5 wouldn't work.
- BIOS security fixes.

BIOS Version 0021 - TYBYT20H.86A.0021.2019.0603.1723

About This Release:

• Date: June 3, 2019

• ROM Image Checksum: 0x1CBA

• ME Firmware: 1.1.4.1145v3

• EC Firmware: 4.00

• Memory Reference Code: Based on 0.94

• Integrated Graphics

• Option ROM: Build 1004 PC 14.34

• UEFI Driver: 7.0.1029

• AHCI Code: Based on 5.004 AHCI002

• LAN Option ROM: 2.0.23

^{*}Other names and brands may be claimed as the property of others.

- Visual BIOS: 2.2.20
- Supported Flash Devices:

Macronix MX25U6435FM2I-10G 8MB Winbond W25Q64FWSSIG 8MB GIGADEVICE GD25LQ64CVIG 8MB

• Microcode Updates included in .ROM File:

M0C30673326.PDB M0C30678838.PDB M0130673326.PDB M0F3067990C.PDB

New Fixes/Features:

• Updated CPU microcode for security fix.

BIOS Version 0020 - TYBYT20H.86A.0020.2019.0409.1424

About This Release:

• Date: April 9, 2019

• ME Firmware: 1.1.4.1145v3

• EC Firmware: 4.00

• Memory Reference Code: Based on 0.94

• Integrated Graphics:

■ Option ROM: Build 1004 PC 14.34

■ UEFI Driver: 7.0.1029

• AHCI Code: Based on 5.004 AHCI002

• LAN Option ROM: 2.0.23

• Visual BIOS: 2.2.20

New Fixes/Features:

• Updated BIOS code for security fixes.

BIOS Version 0019 - TYBYT20H.86A.0019.2018.0619.1124

About This Release:

• Date: June 19, 2018

• ME Firmware: 1.1.4.1145v3

• EC Firmware: 4.00

• Memory Reference Code: Based on 0.94

Integrated Graphics

o Option ROM: Build 1004 PC 14.34

o UEFI Driver: 7.0.1029

• AHCI Code: Based on 5.004 AHCI002

• LAN Option ROM: 2.0.23

• Visual BIOS: 2.2.20

New Fixes/Features:

• Security Enhancements

• Added the setup option "Allow UEFI Third Party Driver loaded" and set the default state to disabled.

BIOS Version 0018 - TYBYT20H.86A.0018.2018.0308.1931

About This Release:

• Date: March 08, 2018

• ME Firmware: 1.1.4.1145v3

^{*}Other names and brands may be claimed as the property of others.

- EC Firmware: 4.00
- Memory Reference Code: Based on 0.94
- Integrated Graphics
 - o Option ROM: Build 1004 PC 14.34
 - o UEFI Driver: 7.0.1029
- AHCI Code: Based on 5.004 AHCI002
- LAN Option ROM: 2.0.23
- Visual BIOS: 2.2.20

New Fixes/Features:

• Updated CPU Microcode (Security Advisory-00088)

BIOS Version 0017 - TYBYT20H.86A.0017.2018.0212.1128

About This Release:

- Date: February 12, 2018
- ME Firmware: 1.1.4.1145v3
- EC Firmware: 4.00
- Memory Reference Code: Based on 0.94
- Integrated Graphics:
 - Option ROM: Build 1004 PC 14.34
 - UEFI Driver: 7.0.1029
- AHCI Code: Based on 5.004 AHCI002
- LAN Option ROM: 2.0.23
- Visual BIOS: 2.2.20

New Fixes/Features:

• Fixed an issue where the EMMC wouldn't be seen in the BIOS.

BIOS Version 0015 - TYBYT20H.86A.0015.2017.0427.1513

About This Release:

- Date: April 27, 2017
- ME Firmware: 1.1.4.1145v3
- EC Firmware: 4.00
- Memory Reference Code: Based on 0.94
- Integrated Graphics
 - Option ROM: Build 1004 PC 14.34
 - UEFI Driver: 7.0.1029
- AHCI Code: Based on 5.004 AHCI002
- LAN Option ROM: 2.0.23
- Visual BIOS: 2.2.20

New Fixes/Features:

• Added xHCI Mode UQI.

BIOS Version 0013 - TYBYT20H.86A.0013.2017.0411.1047

About This Release:

- Date: April 11, 2017
- ME Firmware: 1.1.4.1145v3
- EC Firmware: 4.00
- Memory Reference Code: Based on 0.94

^{*}Other names and brands may be claimed as the property of others.

• Integrated Graphics

• Option ROM: Build 1004 PC 14.34

UEFI Driver: 7.0.1029

• AHCI Code: Based on 5.004 AHCI002

LAN Option ROM: 2.0.23Visual BIOS: 2.2.20

New Fixes/Features:

• Initial production BIOS release

LEGAL INFORMATION

Information in this document is provided in connection with Intel Products and for the purpose of supporting Intel developed server/desktop boards and systems.

No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Intel's Terms and Conditions of Sale for such products, Intel assumes no liability whatsoever, and Intel disclaims any express or implied warranty, relating to sale and/or use of Intel products including liability or warranties relating to fitness for a particular purpose, merchantability, or infringement of any patent, copyright or other intellectual property right. Intel Corporation may have patents or pending patent applications, trademarks, copyrights, or other intellectual property rights that relate to the presented subject matter. The furnishing of documents and other materials and information does not provide any license, express or implied, by estoppel or otherwise, to any such patents, trademarks, copyrights, or other intellectual property rights. Intel products are not intended for use in medical, life saving, or life sustaining applications. Intel may make changes to specifications and product descriptions at any time, without notice.

Intel is a trademark of Intel Corporation in the US and other countries. Copyright (c) 2015 Intel Corporation.

^{*}Other names and brands may be claimed as the property of others.